

**Violation**

भारत सरकार/ **GOVERNMENT OF INDIA**  
 खान मंत्रालय/ **MINISTRY OF MINES**  
 भारतीय खान ब्यूरो/ **INDIAN BUREAU OF MINES**  
 क्षेत्रीय खान नियंत्रक कार्यालय/  
**OFFICE OF REGIONAL CONTROLLER OF MINES**



फैक्स: (080) 23371027 /  
 23373287  
 दूरभाष: 080-23371027 /  
 23375366/67  
 Email ID: ro.  
 bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, IIस्टेज, तुमकुररोड,  
 गोसुंटापाल्या, येशवंतपुर,  
 बेंगलुरु -560022

सं. / No. MCDR-MiFLOFE/41/2023/BNG-IBM\_RO\_BNG

दिनांक/Date: 14/11/2023

सेवार्में/ To,  
**Mr. Faisal Shareef, Managing Partner,**  
**M/s. Nadeem Mineral Private Limited,**  
 No, 53, Empire Towers, 3rd Floor,  
 Railway Parallel Road,  
 Kumara Park West, Bangalore – 560 020  
 E-mail: admin@nadeemminerals.com

**विषय/Sub:** Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Donimalai Iron Ore Mine (ML No. 2526) over an area of 52.82 Ha having mine code 30KAR03113 in Taranagar village, Sandur Taluk, Ballari District, Karnataka state.

महोदय/ Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 in your above mine during inspection on 13.10.2023 by Shri. Gangadhar Bhakat, AME in the presence of Sri. Jeelan, Mines Manager and other mine officials.

Rule	Nature of violations observed.
11(1)	<p>The Mining operations are required to be carried out in accordance with the approved Review and Updation of Mining Plan document vide letter no. 279/591/97/BNG dated 24/11/2020, However, during the site inspection, deviations were observed in mining operation vis-à-vis approved document and are as follows:</p> <p>For the Year 2022-23, It was proposed to carry out Development work with 90,032 Tonnes of waste generation. However, Development is carried out generating only 5,040 Tonnes of waste during the year deviating from the proposed</p>

quantities and not achieving the proposed stripping ratio.

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. The violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

04. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/ Yours faithfully,

(H. M. Shivakumar)  
Assistant Controller of Mines  
भारतीय खान ब्यूरो/Indian Bureau of Mines

**प्रतिलिपिसूचनार्थ/ Copy for kind information to:**

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, MMS Division, Indian Bureau of Mines, Nagpur.
3. The Director, Department of Mining & Geology, No.49, Khanija bhavan, R.C. Road, Bangalore-560 001.

Assistant Controller of Mines  
भारतीय खान ब्यूरो/Indian Bureau of Mines