



भारत सरकार/ GOVERNMENT OF INDIA  
खान मंत्रालय/ MINISTRY OF MINES  
भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय/  
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287  
दूरभाष: 080-23371027 / 23375366/67  
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब ॥ स्टेज, तुमकुर रोड,  
गोरगुंटापाल्या येशवंतपुर,  
बेंगलुरु -560022

सं./ No. KNT/BLR/FE/408/BNG/VOL-II

दिनांक/Date: 21/12/2023

सेवा में/ To,  
Sri. K.S. Vinayak, Nominated Owner,  
M/s. Veerabhadrappa Sangappa & Company,  
VESCO House, 2/138, Ballari Road,  
Sandur-  
vescopd028@gmail.com / smandal078@gmail.com

**विषय/Subject:** Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your **Ramanamalai Iron ore Mine (ML No. 2296) having Mine code: 30KAR03138** over an area of **53.16 Ha** (as per CEC) in Ramgad village, Sandur Taluk, Ballari District, Karnataka state.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Sri. Nandakumar H.M - Mines Manager, Sri. Imran Shaik, Mining Engineer & Sri. Shanmukhappa Mandal, Geologist on 16/11/2023.

Rule	Nature of violations observed
11 (1)	The Mining operations are required to be carried out in accordance with the approved Modifications to approved Mining Plan document vide letter no. <b>279/478/95/BNG</b> dated <b>31/03/2022</b> . However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows:  For the Year 2022-23 – It was proposed to construct Retaining Wall over a length of 220m and garland drain of 140m. However as per the PMCP report submitted for the reporting year only 163m of RW and 50m of GD is completed thereby deviating from the proposals.

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(H.M. SHIVAKUMAR)  
Assistant Controller of Mines

I/22407/2023

-2-

सं./ No. KNT/BLR/FE/408/BNG/VOL-II

प्रतिलिपिसूचनार्थ /Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanija bhavan, R.C. Road, Bangalore-560 001.

(H.M. SHIVAKUMAR)  
Assistant Controller of Mines  
Indian Bureau of Mines