

VIOLATION LETTER

भारत सरकार/ **GOVERNMENT OF INDIA**
 खान मंत्रालय/ **MINISTRY OF MINES**
 भारतीय खान ब्यूरो/ **INDIAN BUREAU OF MINES**
 क्षेत्रीय खान नियंत्रक कार्यालय/
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: **(080) 23371027 / 23373287**
 दूरभाष: **080-23371027 / 23375366/67**
 Email ID: **ro.bangalore@ibm.gov.in**

29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमकुर रोड,
 गोसुंटापाल्या येशवंतपुर,
 बेंगलुरु -560022

(MINE CODE: 30KAR03164)

सं/No.: **KNT/BLR/Fe/457/BNG**

दिनांक/Date: **10/04/2024**

सेवामें/To,
Shri. K. R. Kaviraj,
 M/s. Lakshmi Minerals
 #601, 7th Main, Near Balanjaney Temple,
 M. J. Nagar, Hospet, Ballari-583201.
 Email - srilakshmiminerals@gmail.com

विषय/Sub: - Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your **Jaisinghpur Iron Ore Mine (ML No. 2545)** over an extent of **34.14 Ha** in Jaisinghpur village, Sandur Taluk, Ballari District, Karnataka state.

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 21.03.2024 by Shri. Gangadhar Bhakat, AME in the presence of Sri. Kandi Sandeep Reddy Mining Engineer and other mine officials.

Rule	Nature of violations observed
	The Mining operations are required to be carried out in accordance with the approved Review and Updation Mining Plan document vide letter no. 279/789/2004/BNG dated 21.04.2024, However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows:

11(1)	<p>i. As per the proposal for the year 2022-23 the lessee has to be carried out exploration of 65 Trail pits having dimension of 3m(L) X 2m(W) X 4m(D) for the year 2022-23. However, it is observed during the inspection there is no exploration carried out up to till date of inspection.</p> <p>ii. As per the proposal for the year 2022-23 the lessee has to be constructed garland drain of 135m. However, it is observed during the inspection that only 15m of garland drain has been constructed.</p>
--------------	--

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. The violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

04. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(H. M. Shivakumar)
Assistant Controller of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines

प्रतिलिपि सूचनार्थ'/Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanija bhavan, R.C. Road, Bangalore-560 001.

(H. M. Shivakumar)
Assistant Controller of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines