



भारत सरकार/ GOVERNMENT OF INDIA
खान मंत्रालय/ MINISTRY OF MINES
भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय/
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब ॥ स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं./ No. KNT/TMK/FE/23/BNG

दिनांक/Date: 06/03/2024

सेवा में/ To,

Shri Dharm Tejaswi, Agent & Nominated Owner,
M/s Karnataka Limpo Cement Industry, (Partnership firm)
No. B-221 & 222, 5th Main,
II Stage, Peenya Industrial Estate,
Bengaluru-560 058, Karnataka.
E-Mail Id- ml2028.klci@gmail.com

विषय/Subject: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Karekurchi Iron ore, Manganese Ore & Red-Oxide Mine (ML No.2028) over an area of 15.55 Ha. (as per CEC) in Karekurchi Village, Tiptur Taluk, Tumukuru District, Karnataka state. (Mine Code 40KAR19021).

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection carried out by the undersigned along with Sri. H.M.Shivakumar, Asst. Controller of Mines in presence of Shri Dharm Tejaswi, Agent & Nominated Owner, Shri Rudraiah A M, Mines Manager & Mining Engineer, on 19/01/2024.

Rule	Nature of violations observed
11 (1)	<p>The Mining operations are required to be carried out in accordance with the Review and Updation of Mining Plan document approved vide letter no. 279/780/2003/BNG dated 21/01/2022. However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows:</p> <p>In the Iron ore reef pit (1) it is proposed to maintain the maximum height of the benches at 6m and minimum width of the benches at 6m. However, it is observed that between sections A-A' to B-B' the width of the benches are not maintained as per the approved proposals.</p>

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(डॉ. सुरेश प्रसाद/Dr. Suresh Prasad)
क्षेत्रीयखाननियंत्रक/Regional Controller of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines

प्रतिलिपिसूचनार्थ/Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khaniya bhavan, R.C. Road, Bangalore-560 001.

(डॉ. सुरेश प्रसाद/Dr. Suresh Prasad)
क्षेत्रीयखाननियंत्रक/Regional Controller of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines