

/29505/2024



भारत सरकार/Government of India
खान मंत्रालय/Ministry of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines
नागपुर क्षेत्रीय कार्यालय/Nagpur Regional Office

छाटवी मंजिल, वी एच सी ब्लाक,
इंदिरा भवन, सिविल लाइन्स,
नागपुर-44001
6th Floor, 'B' & 'C' Block
Indira Bhawan, Civil Lines,
Nagpur-440001
दुरभाष / Telephone 2562794
2565089 (Tel/Fax)
ईमेल - rcom.nr@ibm.gov.in

No. MCDR-CND0LST/4/2023-NR-IBM RO NR

Nagpur, dated: 12-04-2024

(38MSH473002)

To: Nominated Owner,
M/s Murli Industries Limited
Village:-Naranda, Korapna Road, Tehsil:- Korapana,
District:- Chandrapur-442916 (Maharashtra)
Email :: kulkarni.ashishanil@dalmiacement.com

Sub:- Violation of provision of Mineral Conservation and Development Rule 2017 in respect of your Sangoda Limestone Mine (154.70 Hect and mine Code 38MSH473002) of M/s Murli Industries Ltd., District- Chandrapur of Maharashtra State

Sir,

The following provisions of Mineral Conservation and Development Rule, 2017 (MCDR, 2017) were found violated in respect of the above said mine during inspection carried out on 17.02.2024 by undersigned in the presence of Shri Shrikant Mandalwar, Mining Engineer and Ms. Sneha Dhande, Geologist:-

Rule	Nature of Violation observed								
11(1)	<p>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of minerals specified in Part B of the First Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession Rules, 2016.</p> <p>In this connection following deficiencies are observed during the inspection of your above referred mine:-</p> <p>The production as proposed for the year 2022-23 was not achieved, but after examining the annual returns during the inspection, it is observed that no production has been achieved as per proposal submitted by the said mine.</p> <table border="1"> <thead> <tr> <th>Sr. no.</th> <th>Year</th> <th>Proposed production (T)</th> <th>Actual production as reported in Annual Return (T)</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>2022-23</td> <td>239760</td> <td>100</td> </tr> </tbody> </table> <p>Thus there is gross deviation of production from the targeted production as mentioned in approved mining plan and violations of provision of MCDR-2017 (amended to 2021).</p>	Sr. no.	Year	Proposed production (T)	Actual production as reported in Annual Return (T)	1	2022-23	239760	100
Sr. no.	Year	Proposed production (T)	Actual production as reported in Annual Return (T)						
1	2022-23	239760	100						
34A	As per provision of rule and SOP issued by IBM for submission of Digital Aerial Image i.e. Drone Data for the respective year but during inspection it was observed that no such permanent GCP points were observed.								

505/2024

03. In this connection, it is brought to your kind notice that the above violations constitute an offence, punishable under Rule 62(1) & 62(2) of MCDR, 2017.

04. The mining operations can be suspended under Rule 11(2), if compliance of MCD Rules 2017 is not found satisfactory, or prosecution can be made, or both can be done.

05. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,



(R. M. Khadse)

Assistant Controller of Mines

Copy by email to:

1. The Controller of Mines (CZ), I.B.M. Nagpur.
2. The Director, Directorate of Geology & Mining, Government of Maharashtra, Khanij Bhawan, 27, Shivaji Nagar, Cement Road, Nagpur-440010 (Maharashtra).

--SD--

(R. M. Khadse)

Assistant Controller of Mines