



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines



Jabalpur, Dated: 22.12.2023

To,

Shri Pradyuman Kumar Trivedi(Owner)

GFSR Manganese Mine(33 hect)

M/s J K Minerals, P.O Box no-1,

Main Road Balaghat,

Distt-Balaghat,M.P-481001

Email-pradyuman@hotmail.com

Sub.: Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to GFSR Manganese Mine , **40MPR01006, Area 33.00 hectare, in District Balaghat of Madhya Pradesh.**

Sir,

The following provision of Mineral Conservation and Development Rules 2017 were found violated in your above mentioned mine during the inspection by the undersigned on 26.09.2023 in presence of Shri. Deven P Trivedi (Lessee representative), and Shri J.P Yadav Mine Manager

Rule No	Nature of violation observed in detail
Rule 11(1)	<p><i>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5.</i></p> <ol style="list-style-type: none"> 1. Only 24,750 Tones of Manganese ore was produced against the proposed production of 73,427 Tonnes during 2022-2023 which distorting the proposal by 66 %. 2. In 18.00 ha block PIT2 first level at pillar No S-20 the splitting of pillar observed and In 15.00 ha block PIT No 02 second level and Third level the stope besides the Incline were split. 3. 15 Block pit 03 is submerged in water and dewatering arrangements are not efficient.
Rule 12(4)	<p><i>In the case of existing mining leases detailed exploration (G1 level) over the entire potentially mineralised area under the mining lease shall be carried out within a period of five years from the date of commencement of these rules.</i></p> <p>The Mining lease area has not been explored under G1 level over the entire potentially mineralized area.</p>

I/22384/2023

2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
3. Non compliance of rule 11(1) of MCDR, 2017 may lead to suspension of mining operation under the provision of rule 11(2) of MCDR-2017.
4. You are advised to rectify the above violations immediately and intimate the position to this office within a period of 45 days from the date of issue of this letter.

Yours faithfully

(Kathroju Naveen)
Sr. Asst. Controller of Mines,
For Regional Controller of Mines,

Copy to:

1. The Controller of Mines (CZ), Nagpur, IBM
2. The Director of Geology & Mining, Government of Madhya Pradesh, Khanij Bhavan, Arera Hills, Bhopal (MP). (All Lease Boundary Pillars not found established to delineate the lease area on the field).
3. The District Collector, Rewa.

((Kathroju Naveen)
Sr. Asst. Controller of Mines,
For Regional Controller of Mines,