

I/18053/2023

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
माखपुर औद्योगिक क्षेत्र अजमेर
305002



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of
Mines. Makhupura Industrial Area,
Ajmer- 305002

Ph-145-2695165 / 2695476 Fax-
2695202

ई-मेल : ro.ajmer@ibm.gov.in

संख्या : E4081 MCDR-MiFLOFE/1/2023-AJM-IBM_RO_AJM

दिनांक : 06-10-2023

To : Mine Agent, Dhedwas Iron Ore Mine,
M/s Jindal Saw Limited,
Araji Number: 9697/6711, Near Tiranga Hills,
Village: Pur, District: Bhilwara (Rajastaha)-311802,
(E-mail: naveen.airan@jindalsaw.com, dinesh.patil@jindalsaw.com)

विषय: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Dhedwas Iron Ore Mine over an area 1556.7817 Ha.in Bhilwara district of Rajasthan State.

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection made on 11/09/2023 by the undersigned in presence of Shri Dinesh Patil, Agent, Shri Naveen Kumar Airen, Mine Manager and Shri Ramesh Parihar, Geologist.

Rule No.	Nature of violation observed in detail
Rule 11(1)	The mining operations are carried out in violation of following provisions of approved Modified Mining Plan (Approved on 30.01.2023): - <ul style="list-style-type: none"> ➤ Ore to Overburden ratio (stripping ratio) was achieved 1:2.23 (Tone/Tone) against the proposed ratio of 1:3.20 (Tone/Tone). ➤ 3103478 tonnes quantity of O/B has been generated during the year 2022-23 against the proposal of 4776604 tonnes quantity of O/B which is 64.97% of the proposal resulting the benches in Overburden is not sufficiently advanced.
Rule 40	During the inspection, dust was observed at crusher hopper and no water sprinkler arrangements was available there.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियम का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अन्तर्गत:

- (क) आपकी खदान की सारी संक्रियाएं बंद की जा सकती है ।
(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है ।
(ग) खनन पट्टा खंडन की अनुसंशा की जा सकती है ।

03. अतः आपको यह निर्देशित किया जाता है कि आप उपरोक्त उल्लंघन का अतीशीघ्र सुधार करें एवं इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की तिथि से 45 (पैंतालीस) दिवस के भीतर इस कार्यालय को प्रेषित करें ।

भवदीय

(चन्द्रेश बोहरा)
उप खान नियंत्रक(कार्यालय प्रभारी)
भारतीय खान ब्यूरो

P.T.O.

I/18053/2023

प्रतिलिपी सूचनार्थ :

1. खान नियंत्रक (उ.आ.) भारतीय खान ब्यूरो, उदयपुर (ईमेल)
2. निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, शास्त्री सर्किल, उदयपुर ।
3. खनि अभियंता, खान एवं भूविज्ञान विभाग, भीलवाड़ा ।

उप खान नियंत्रक(कार्यालय प्रभारी)
भारतीय खान ब्यूरो