

I/26534/2024

भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक का कार्यालय  
माखपुर औद्योगिक क्षेत्र अजमेर  
305002



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of the Regional Controller of  
Mines. Makhupura Industrial Area,  
Ajmer- 305002  
Ph-145-2695165 / 2695476 Fax-  
2695202

ई-मेल : ro.ajmer@ibm.gov.in

संख्या : **E4195 MCDR-MiFLOLST/10/2023-AJM-IBM\_RO\_AJM**

दिनांक : 29.02.2024

To : Mine Agent, Malia Khera Limestone Mine,  
M/s JK Cement Works,  
Kailash Nagar, Tehsil- Nimbahera  
Dist-Chittorgarh, Rajasthan-312617.  
(E-mail: [manish.toshniwal@jkcement.com](mailto:manish.toshniwal@jkcement.com).)

विषय : Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Malia Khera Limestone Mine over an area 315.409 Ha.in Chittorgarh district of Rajasthan State.  
महोदय]

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection made on 08/01/2024 by the undersigned in presence of Shri Manish Toshniwal, Agent and Shri Dilip Kumar Dhakar, Mines Manager.

Rule No.	Nature of violation observed in detail	
Rule 11(1)	The mining operations are carried out in violation of following provisions of approved Modified Mining Plan (Approved on 24.11.2020): -	
	<b>Proposal [2022-23]</b>	<b>Actual [2022-23]</b>
	<b><u>New Pit</u></b> ML 6-7 to ML 7-8 (E) (upto RL 428 mts.)	<b><u>New Pit</u></b> Nil
	<b><u>Bench II – Between</u></b> ML 13 to ML 14 (S) ML 9-10 to ML 11-12 (SW) ML 4-5 to ML 8-9 (W) ML 0-1 to ML 3-4 (NW) (Upto RL 419 mts)	<b><u>Bench II – Between</u></b> Nil ML 9-10 to ML 12-13 (SW) ML 4-5 to ML 9-10 (W) Nil (Upto RL 419 mts)
	<b><u>Bench III – Between</u></b> ML 1-2 to ML 5-6 (NE) ML 12-13 to ML 13-14 (S) ML 4-5 to ML 6-7 (W) ML 0-1 to ML 4-5 (NW) (Upto RL 410.0 mts.)	<b><u>Bench III – Between</u></b> ML 1-2 to ML 7-8 (NE) Nil ML 4-5 to ML 9-10 (W) Nil (Upto RL 410.0 mts.)
	<b><u>Bench IV – Between</u></b> ML 3-4 to ML 8-9 (N,E,S,W) (Upto RL 401.0 mts.)	<b><u>Bench IV – Between</u></b> ML 2-3 to ML 8-9 (N,E,W) (Upto RL 404.1 mts.)
	<b><u>Bench V –</u></b> NIL (Upto RL 392.0 mts.)	<b><u>Bench V –</u></b> ML 4-5 to ML 8-9 (Upto RL 398.2 mts.)
	During the inspection, it has been observed that development and production has not been carried out on proposed location.	

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियम का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अन्तर्गत:

- (क ) आपकी खदान की सारी संक्रियाएं बंद की जा सकती है ।  
(ख ) आपके विरुद्ध अभियोग दायर किया जा सकता है ।  
(ग ) खनन पट्टा खंडन की अनुसंशा की जा सकती है ।

I/26534/2024

03. अतः आपको यह निर्देशित किया जाता है कि आप उपरोक्त उल्लंघन का अतीशीघ्र सुधार करें एवं इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की तिथि से 45 (पैंतालीस ) दिवस के भीतर इस कार्यालय को प्रेषित करें ।

भवदीय

(चन्द्रेश बोहरा )

उप खान नियंत्रक(कार्यालय प्रभारी)

भारतीय खान ब्यूरो

Copy for kind information to:

1. The Controller of Mines (NZ), Indian Bureau of Mines, Udaipur (Email)
2. The Director, Directorate of Mines & Geology, Govt. of Rajasthan, Shastri Circle, Udaipur (Raj.).
3. The Mining Engineer, Department of Mines & Geology, Govt. of Rajasthan, Chittorgarh district (Rajasthan).

उप खान नियंत्रक(कार्यालय प्रभारी)

भारतीय खान ब्यूरो