



**GOVERNMENT OF INDIA**  
**MINISTRY OF MINES**  
**INDIAN BUREAU OF MINES**  
**OFFICE OF THE REGIONAL CONTROLLER OF MINES**



Jabalpur

To,  
**Shri Warud Murti Mishra ( Nominated Owner),**  
Prayas Bhavan Block No1(A)  
Second Floor Jail Road,  
Arera Hills Bhopal 462011  
Email [info.mpsmc@mp.gov.in](mailto:info.mpsmc@mp.gov.in)

Sub.: Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to your **Tamar Bauxite Mine (21.00 ha )**, Mine Code 07MPR35077 in **Tamar** Village of Satna Dist M.P.

The following provision of Mineral Conservation and Development Rules 2017 were found violated in your above mentioned mine during the inspection by the undersigned on 28.05.2024 in presence of Shri. Yogesh Pandey (Lessee representative) & Shri. Mayank Singh Parihar Mining Engineer.

Rule No	Nature of violation observed in detail
<b>Rule 11(1)</b>	<p><i>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5.</i></p> <ol style="list-style-type: none"> <li>i. Mining lease Boundary pillars has not been established at the precise locations.</li> <li>ii. The exploration proposal of 06 boreholes during the year1 i.e 2023-24 has not been carried out as proposed.</li> <li>iii. Back filling of 7.5 m barrier has not been carried out as proposed..</li> <li>iv. It is proposed to construct 980m length of garland drain in southern part of the lease which is not constructed.</li> <li>v. Plantation has not been carried out as proposed 500 sapling during the reporting year.</li> </ol>
<b>Rule 31(4)</b>	<p><i>The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in the case of any other mine.</i></p> <p style="text-align: center;">The plans and sections have not been updated as required.</p>

I/33907/2024

2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.

3. You are advised to rectify the above violations immediately and intimate the position to this office within a period of 45 days from the date of issue of this letter.

Yours faithfully

(Kathroju Naveen)  
Sr. Asst. Controller of Mines,  
For Regional controller of Mines,  
Jabalpur.

Copy to:

1. Controller of Mines, COM(CZ).
2. The Director of Geology & Mining, Government of Madhya Pradesh, Khanij Bhavan, Arera Hills, Bhopal (MP)
3. The District Collector, Satna

(Kathroju Naveen)  
Sr.Asst. Controller of Mines,  
For Regional controller of  
Mines, Jabalpur