

**Violation Letter  
Speed Post/Email**

भारत सरकार /Government of India  
खान मंत्रालय/Ministry of Mines  
भारतीय खान ब्यूरो /Indian Bureau of Mines  
Office Of Regional Controller of Mines



दूरभाष: (080) 39505368 / 29720499

Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,

गोरगुंटापाल्या येशवंतपुर,

बेंगलुरु -560022

NO: MCDR-MiFLOFE/5/2022-BNG-IBM\_RO\_BNG Mine-code: 30KAR03183 Dated: 06 /09/2024

To,

Shri Gajraj Singh Rathore,  
Nominated Owner, Devadari iron ore mine  
M/s. JSW Steel Ltd  
JSW Mining office  
Near Talur Cross, Vidyanagar Works  
Po-Vidyanagar, Dist-Ballari, Karnataka-583275  
E-mail id- gajraj.rathore@jsw.in ; sunil.singh@jsw.in, sharma.nishant@jsw.in

विषय/Subject: **Violation of provisions of MCDR 2017 in respect of your Devadari Iron ore mine, ML 0006 over an extent of 100.54 ha, in Lakshimpura Village, Sandur Taluk , Ballari District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 21.08.2024 by the undersigned in presence of Shri Nishant Kumar Sharma, Mines Manager, Shri Jitendra Kumar, Mining Engineer, Shri Rajarshi Majumdar, Geologist and other mine officials:

Rules	Nature of Violations observed
11 (1)	The Review and updation of mining was approved by IBM vide letter no. 279/1091/2017/BNG dated 08/02/2023 for the period 2023-24 to 2027-28 & the modification of Mining plan was approved by IBM vide letter no. MCDR-MPC0FE/22/2023-BNG-IBM_RO_BNG dated 23/02/2024 for the period 2023-24(1/11/23 to 31/03/24) to 2027-28. The deviations observed in mining operation vis-à-vis approved document are given below.  i) It is observed from the submitted drone data and during inspection that development of benches at South eastern portion of pit between section S-1-1' to S-4-4' (N-1665770 E-669833 to N-1665999, E-669813) from 858 mRL to 818 mRL have not been developed systematically with 8m benches as per the proposal.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

I/39121/2024

भवदीय/Yours faithfully,

(Sandeep Kumar Singh)

Senior Assistant Controller of Mines

Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

(Sandeep Kumar Singh)

Senior Assistant Controller of Mines

Indian Bureau of Mines