



भारत सरकार /Government of India
खान मंत्रालय/Ministry of Mines
भारतीय खान ब्यूरो /Indian Bureau of Mines
Office Of Regional Controller of Mines



Violation Letter
Speed Post/Email

दूरभाष: (080) 39505368 / 29720499

Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,

गोरगुंटापाल्या येशवंतपुर,

बेंगलुरु -560022

NO: MCDR-MiFLOFE/14/2023-BNG-IBM_RO_BNG Mine-code: 30KAR03160 Dated: 06/09/2024

To,

Shri Syed Ahmed,
Nominated Owner & Managing Partner,
Ramgad Iron ore Mine.
M/s. Zeenath Transport Company.
Zeenath House, Cowl Bazar,
Ballari-583 102
Karnataka
E-mail id- ztco2000@yahoo.com

विषय/Subject: **Violation of provisions of MCDR 2017 in respect of your Ramgad iron ore mine, ML 2547 over an extent of 49.73 ha, in Ramgad Village, Sandur Taluk, Ballari District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 23.08.2024 by the undersigned in presence of Shri J Srikanth, Mines Manager & Mining Engineer, Shri Rashmi Ranjan Sahu, Geologist and other mine officials:

Rules	Nature of Violations observed
11 (1)	The modification of mining plan was approved by IBM vide letter no. 279/419/94/BNG dated 18/09/2023 for the period 2023-24 to 2026-27. The deviations observed in mining operation vis-à-vis approved document are given below. i) The 10 m systematic stages/lifts have not been maintained at active waste dump (AD) between section N-N' to O-O'(N-1667569 E-661153 to N-1667504 E-661207) from 960 to 980 mRL as per 2023-24 waste dumping proposal.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

(Sandeep Kumar Singh)

I/39127/2024

Senior Assistant Controller of Mines
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

(Sandeep Kumar Singh)

Senior Assistant Controller of Mines
Indian Bureau of Mines