

1



भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF
MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL
CONTROLLER OF MINES



BY REGD POST A/
D

Phone: 0674-2352463
Tele Fax: 0674-2352490
E-mail:
ro.bhubaneshwar@ibm.gov.
in

Plot No.149, Pokhariput
BHUBANESWAR-751020

दिनांक

30/09/2024

प्रेषिति-

Shri Balwant Singh, MD & Nominated Owner
M/s Odisha Mining Corporation Limited.
OMC HOUSE, POST BOX NO-34,,
BHUBANESWAR ODISHA-751001
E-mail: md@odishamining.in,
kpradhan@odishamining.in,
planningcellomc@gmail.com

विषय- ओडिशा राज्य के कोरापुट एवं रायगाड़ा जिले में स्थित आपकी कोदिंगमलि बाक्साइट खदान 428.075 हे० में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 12.09.2024 by undersigned accompanied by Shri Kathi Pradhan, Mines Agent & Shri Hemant Kumar Behera, Mines Manager.

Rule	Nature of Violation observed
11(1)	Mining operations should have been undertaken in accordance with the Mining Plan/Modification of Review of Mining Plan. The Review of Mining Plan was approved vide letter no. RMP/A/21-ORI/BHU/2021-22 Dated 10.11.2021 and following deviation was observed during inspection 1. The proposal for ROM production was given for 6000000 tons in 2023-24 but only 3000000 tons production done which is only 50% of the proposed production. 2. The proposal for overburden generation was given for Quarry1: 1070000 m3 Q2: 760000 m3 (Total 1830000 m3) in 2023-24 but only Q1: 1, 73,388 m3 Q2: 4,30,323.327 m3 (Total 603711.327 m3) generation done which is only 33% of the proposed overburden generation.
45(5) (c)(i)	While scrutiny of Annual returns 2023-24 following discrepancy observed 1. The Ex-mine price given is not matching with the sale value/ton as given in the return

- 2 इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवम 45(7)(क) के अंतर्गत
(क) खान की सारी खनन संक्रियाएँ बंद की जा सकती हैं।
(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।
(ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
- 3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशिघ्र सुधार करें एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय

**Signed by Rajesh Kumar
Das
Date: 01-10-2024 17:24:24**

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर

Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
- (2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata- 700 091.

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर