



भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय /
OFFICE OF REGIONAL CONTROLLER OF MINES

By Speed Post



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro_bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुटापाल्या, येशवतपुर, बंगलुरु
29, Industrial Suburb, II Stage,
Tumkur Road, Goruguntapalya,
Yeshwantpur, Bangalore - 560022

सं/No.: MCDR-MiFLOFE/2/2023-BNG-IBM_RO_BNG

सेवा में/ To,

M/s Veerabhadrappa Sangappa & Company
No. 2/138, VESCO House,
Ballari Road, Sandur -583119
Ballari District, Karnataka
Email: vescosdr@yahoo.com

विषय/Subject : Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your **Dharmapura Iron ore Mine (ML-2160)** (Mine Code-30KAR03104) over an area of 18.46 ha in Ballary district of Karnataka State.

महोदय/Sir,

The following provisions of Mineral Conservation and Development Rule, 2017 (MCDR, 2017) were found violated in respect of the above said mine during inspection on 01.10.2024 by the undersigned along with Shri A K Pany, AME of this office, in presence of Shri Amartaluri V. Rao, Mines Manager and other Mine officials.

Rule s	Nature of Violations Observed
11(1)	As per Review of Mining Plan approved on 23.11.2021, there is proposal of construction of 25m garland drain during the year 2023-24. During inspection, it is observed that the same has not been constructed.
12(1)	During the inspection, it is observed that around 1.5 lakh tonnes of Iron ore fines stacked in the mine. Stacking of such a large quantity of fines in the mine during rainy season is not appropriate in the view of conservation of mineral as there is chance of flow of mineral by rain water.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Signed by Suresh Prasad
Date: 22-10-2024 17:12:03
(डॉ सुरेश प्रसाद/ Dr. Suresh Prasad)

क्षेत्रीय खान नियंत्रक/ Regional Controller of Mines

प्रतिलिपि सूचनार्थ' /Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.