Name of the Mine: Vijaypathi-2 Limestone Mine / 29.90 Ha / 38TMN15107

Name of the Owner: M/s The India Cements Ltd.

Location: Tirunelveli District (Latitude: 8°11'19" & Longitude: 77°43'55")

## Brief report on the mine:

1.	Surrendered area breakup: Government, private, forest etc, Name of the Mineral	The lessee has submitted lease surrender application to the state government. However, the same is yet to be issued.  Non-Forest Govt. Land – 24.335 Ha
	or the Hamerta	Patta Land – 5.565 Ha Mineral: Limestone
2.	Potential scope of further exploration or re-grant of area: Resource status etc	Entire mineable reserves within the lease area has been mined out The balance resources blocked up in the safety barrier is 1,13,114 Ts (211).
3.	Current status of area :in reference to its merger with surrounding and safety considerations.	The lease area is vacant land as of now and is in the immediate vicinity of Kundankulam Nuclear Power Plant as a result of which no activity is allowed in the said area.
4.	Any danger to man & material : Rectificatory work to be done	Nil
5.	Any danger of escape of effluents / leachants.: Safeguards to be taken	Nil
6.	Any other observation key to closure aspect.	The lease area is vacant land as of now and is in the immediate vicinity of Kundankulam Nuclear Power Plant as a result of which no activity is allowed in the said area.

## Enclose the following as Annexures:

- 1. High definition Photographs depicting work done under FMCP and present Status of the Area. Enclosed
- 2. High definition Video clip of the lease area. Enclosed
- 3. Details regarding activities carried out under Mine Closer (Reclamation, Rehabilitation, afforestation, water harvesting, eco tourism site etc.) and details of the erstwhile lease area (Govt/pvt/forest).

Sl. No.	Description	Status of the work
1	Levelling the area	The edges of the mined out pits has been trimmed.
2	Dismantling the infrastructure	The semi-permanent parts of the infrastructures have been dismantled.
3	Transportation of mining machinery such as drills and hammers	The mining machinery utilised have been deployed in other mines owned by the lessee.
4	Plantation in the mined out land and the periphery of the ML area	The mining lease area consist of dry rocky terrain with very low rain fall, however the plantation has been developed along the safety distance area and also in the mined out pits.