



भारत सरकार / GOVERNMENT OF INDIA

खान मंत्रालय / MINISTRY OF MINES

भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES

क्षेत्रीय खान नियंत्रक का कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES



दूरभाष/Tel.: 044 - 24914461

फैक्स/Fax: 044 - 24911295

सी-4-ए, राजाजी भवन / C-4-A, Rajaji Bhawan, C.G.O Complex,

बेसंत नगर, चेन्नई / Besant Nagar, Chennai - 600 090.

मिसिल सं. File No. TN/ALR/LST-49/MDS

Mine code - 38TMN38009

दिनांक Dt. 15/01/2025

सेवा में/To,

Shri P.R.Venkatramarajah,
Chairman (The RAMCO Cements Limited) &
Nominated Owner, (Tular Limestone Mine),
Auras Corporate Centre, 98-A, Dr.Radhakrishnan Salai,
Mylapore, Chennai - 600 004, Tamil Nadu

विषय/Sub: Violation of provisions of Mineral Conservation & Development (Amendment) Rules, 2024, in respect of your Tular Limestone Mine over 136.11 Ha having mine code 38TMN38009 in Tular & Manakkudaiyan Villages, Sendurai Taluk, Ariyalur District of Tamil Nadu.

महोदय/Sir,

The following provisions of the MCD(A)R, 2024 were found violated in your above mine during the inspection on 12/12/2024 by the undersigned in the presence of Mr. S. Duraimurugan (Sr. DGM Mines) & Mr. J. Ravi (DGM Geology):

Rule No.	Nature of Violation
11(1)	Mining operations have not been carried out in accordance with the Review of Mining Plan approved vide Letter No. TN/ALR/LST/ROMP-1703.MDS dated 01/12/2022 to the extent indicated below: <i>There was a proposal to excavate 14,98,000 tonnes of ROM during the year 2023-24 against which only 8,23,575 tonnes of ROM has been removed during the year.</i>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62(1) of Mineral Conservation and Development (Amendment) Rules, 2024, with imprisonment for a term which may extend to two years or with fine which may extend to rupees five lakhs, or with both, and in the case of a continuing contravention, with additional fine which may extend to rupees fifty thousand for every day during which such contravention continues after conviction for the first such contravention.

03. The mining operation can be suspended under Rule 11(2) and/or prosecution be launched if the compliance of the rule is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully,

(मतिउल इस्लाम / Matiul Islam)

सहायक खान नियंत्रक / Assistant Controller of Mines

प्रतिलिपि / Copy forwarded to:

1. खान नियंत्रक (द.अ.), भारतीय खान ब्यूरो, बैंगलुरु/The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Commissioner, Department of Geology & Mining, Chennai.
3. Shri Meenashisundaram, SVP – Manufacturing & Agent (Mines), M/s The Ramco Cements Limited, Alathiyur Works, Sendurai Taluk, Ariyalur District – 621 730. Email – mclalr@ramcocements.co.in
4. Guard File
5. कार्यालय प्रति/Office Copy

(मतिउल इस्लाम / Matiul Islam)

सहायक खान नियंत्रक / Assistant Controller of Mines