# INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

#### MCDR INSPECTION REPORT

### Gandhinagar regional office

Mine file No : RAJ/RJS/LEAD-ZINC-COPPER-1 Mine code : 34RAJ27001

(i) Name of the Inspecting : GQ21 ) DATA RAM GURJAR

Officer and ID No.

(ii) Designation : Deputy Controller Mines

(iii) Accompaning mine : Sh. Sanjay Kumar, Mine Manager & Sh Sandeep rajpur, G

Official with Designation

(iv) Date of Inspection : 17-MAY-24
(v) Prev.inspection date : 13-SEP-19

PART-I : GENERAL INFORMATION

. (a) Mine Name : RAJPURA DARIBA

(b) Registration NO. : IBM/421/2011

(c) Category : A Mechanised

(d) Type of Working : Underground

(e) Postal address

State : RAJASTHAN
District : RAJSAMAND
Village : DARIBA
Taluka : RAILMAGRA
Post office : DARIBA
Pin Code : 313211

FAX No. : 02952-65143

E-mail : arun.misra@vedanta.co.in

Phone : 0294-2421420

(f) Police Station : Railmagra
(g) First opening date : 28-DEC-70

(h) Weekly day of rest : SUN

2. Address for : RAJPURA-DARIBA

correspondance DISTRICT-RAJSAMAND(RAJ.)

PIN-313211

3. (a) Lease Number : RAJ0654
(b) Lease area : 1142.2

(c) Period of lease : 20

(d) Date of Expiry : 29-MAY-30

4. Mineral worked : COPPER ORE Associated

LEAD & ZINC ORE Main

5. Name and Address of the

Lessee : Hindustan Zinc Ltd

Yashad Bhavan Udaipur UDAIPUR RAJASTHAN

Phone: FAX:

Owner : Shri Arun Misra

YASHAD BHAWAN HINDUSTAN ZINC LIMITED Udaipur UDAIPUR RAJASTHAN Phone: 0294-2421420 FAX : 0294-2412545

Agent : Debanshu Chatterjee

Rajpura Dariba Lead Zinc Mine PO-Dariba Tehsil-Railmagra RAJSAMAND

RAJASTHAN

Phone: 02952-265164 FAX: 0295-2265143

Mining Engineer

Name : Sanjay Kumar, Full Time

Qualification : BE(Mining)
Appointment/ : 12-JUL-23

Termination date

Geologist

Name : Dr. Sandeep Kumar Rajput, Full Time

Qualification : Ph.D., N.E.T Appointment/ : 15-JUN-20

Termination date

Manager

Name : Sanjay Kumar
Qualification : BE(Mining)
Appointment/ : 12-JUL-23

Termination date

6. Date of approval of Mining : Mining Scheme rule 12 MCDR1988 Plan/Scheme of Mining : Mining Scheme rule 12 MCDR1988

Mining Scheme rule 12 MCDR1988 19-AUG-05
Renewal under rule 22 MCR1960 26-MAY-09
Modif.approved Mining Scheme 26-MAY-09
Modif.of approved Mining Plan 19-OCT-12
Mining Scheme rule 12 MCDR1988 22-JUL-15
MP modif under 17(3) MCR 2016 26-SEP-17
MP review under 17(1) MCR 2016 23-JAN-18
MP modif under 17(3) MCR 2016 10-MAY-19

12-DEC-00

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

## Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	A total of 192 BHs with 20000 mts of drilling was proposed during reporting year 2022-23.	A total of 220 BHs with 44192 mts of drilling was carried out during reporting year 2022-23.	No backlog of previous year 2022-23.
1b	Exploration over lease area for geological axis 1 or 2	A total of 180 BHs with 25000 mts of drilling was proposed during reporting year 2023-24.	A total of 125 BHs with 35973 mts of drilling was carried out during reporting year 2023-24.	During the reporting year 2023-24, shortfall in exploration drilling in respect of nos. of bore holes, hence violation of Rule 11(1) of MCDR 2017 issued vide letter dated 19.07.2024.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	Exploration Agency Mining Associates Pvt. Ltd, M/s Onkarlal Baluram No proposal on expenditure.	Exploration Agency: Transnational Drilling & Mining Associates, M/s Onkarlal Baluram. Expenditure: Rs. 1734.67 lakh	Nil
1d	Balance area to be explored to bring Geological axis in 1 or 2	It is not a surficial deposit, it is vein type/lens type deposit, exploration drilling proposed to prove depth continuity of mineral and upgradation of resource to reserve.	Exploration drilling has been carried out during the year 2023-24.	Nil
1e	Balance reserve as on 01/04/20	No specific proposal for balance reserve.	As on 01/04/2024 the position of reserve and resource was 47.11 and 40.55 million tons respectively.	Nil

1f General remarks of inspecting officers on geology, exploration etc

During the reporting year 2023-24, shortfall in exploration drilling in respect of nos. of bore holes, hence violation of Rule 11(1) of MCDR 2017 issued vide letter dated 19.07.2024.

### Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	Development has been proposed in North Lode, East Lode, Main Lode and South Lode at various levels. A total of 10096 mts of development was proposed during the year 2023-24.	Development has been carried out in North Lode, East Lode, Main Lode and South Lode at various levels, a total development of 10231.92 mts has been carried out during the RY 2023-24.	No shortfall in U/G mine developement.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	Not applicable as mining operations were proposed through UG mining method.	Not applicable.	Nil
2c	Stripping ratio or ore to OB ratio	Not applicable as mining operations were proposed through UG mining method.	Not applicable.	Nil
2d	Quantity of topsoil generation in m3	top soil	No top soil generated during the RY 2023-24.	Nil

2e	Quantity of overburden generation in m3	OB generation as mining operations was proposed through UG	No OB generation as mining operations were carried out through UG method. However, an quantity of 116220 m3 or 313793 MT of waste has been generated through UG mine development.	No major deviation observed with respect to proposal.
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc	The development was proposed through UG mining Method.	The method of development was as per proposal.	The UG mechanized method has been adopted for carrying out mining operations in the lease area which is best suited to the type of the deposit.

## Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	Not applicable being an underground mine.	Not applicable.	Nil
3b	Quantity of ROM mineral production proposed	2023-24: 1750050 Tonnes	2023-24: 1343829 Tonnes	No major deviation observed.
3с	Recovery of sailable/usable mineral from ROM production	2023-24: 1750050 Tonnes	2023-24: 1343829 Tonnes	No major deviation observed.
3d	Quantity of mineral reject generation	No proposal of mineral rejects (MR) generation.	Entire ROM is subject to beneficiation. No mineral reject generation.	Nil
3e	Grade of mineral rejects generation and threshold value declared.	Not applicable as no proposal of mineral reject generation.	Not applicable.	Nil
3f	Quantity of sub grade mineral generation.	No proposal of sub-grade generation.	Not applicable.	Nil

3g	Grade of sub grade mineral generation	Not applicable as no proposal of sub-grade generation.	Not applicable.	Nil
3h	Manual / Mechanised method adopted for segregating from ROM		Beneficiation of ROM is being carried out as per proposal.	Nil
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No proposal of any fresh beneficiation study.	None during the reporting year 2023-24.	Nil
3ј	Provision of drilling and blasting in mineral benches	Not applicable being an underground mine.	Not applicable.	Nil
3k	Provision of mining machineries in mineral benches	Not applicable being an underground mine.	Not applicable.	Nil
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	being an underground	Not applicable.	Nil
3m	Total area covered under excavation/pits	No proposal as it is U/G mine.	Not applicable	Nil
3n	Ore to OB ratio for the pit/mine during the year.	being an	Not applicable.	Nil
30	Total area put in use under different heads at the end of year	293.42 ha	267.67 ha	Nil
3p	Production of ROM mineral during the last five year period as applicable	2018- 19:1200000, 2019- 20:1500000, 2020- 21:1500000, 2021- 22:1550000, 2022- 23:2000000, 2023- 24:1750050	2018-19: 1079955 2019-20: 1037607 2020-21: 1215171 2021-22: 1252365 2022-23: 1390245 2023-24: 1343829	All figures in tonnes.

3q General remarks U/G Mining of inspecting officers on method of mining

etc.

method proposed. U/G mining method adopted., which is best suited to the type of deposit.

Nil

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	top soil and mineral reject	dump.	Nil
4b	Location of topsoil, OB and mineral reject dumps	Dumping of the waste has been proposed over the existing waste dump as well as backfilling in UG voids.		Nil
4c	Number of dumps within lease area and outside of lease area	within lease	One waste dump within lease and no waste dump outside lease area.	Nil
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Not applicable being an underground mine.	Not applicable.	Nil
4e	Number of active and alive dumps.	One.	One.	Nil
4f	Number of dead dumps.	No proposal.	Not applicable.	Nil.
4g	Number of dumps established.	No proposal.	Not applicable.	Nil
4h	Whether Retaining wall or garland drain all along dumps are there.	No proposal.	Retaining wall and garland drain observed at necessary places along the waste dump.	Nil

4i	Length of Retaining wall or garland drain all along dumps	during the RY	Not applicable.	Nil
4j	Number of settling ponds	No proposal of settling pond during the RY.	Not applicable. As no proposal.	Nil
4k	Specific comments of inspecting officer on waste dump management	waste was proposed to	UG mine development waste generated during the RY was disposed as per proposal.	No issue observed related to waste dump management.

## Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	full	In stope backfilling/dumping of waste after full extraction of mineral.	Nil
5b	Area under backfilling of mined out area	2023-24 428191m3	2023-24 334381m3	Due to less production in the RY 2023-24, less U/G voids created hence less backfilling has been carried out with respect to proposal.
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No proposal of top soil generation during the RY 2023-24.	No top soil generated during the RY 2023-24.	Nil
5d	Total area fully reclaimed and rehabilitated	No proposal of full reclamation and rehabilitation during RY.	Not applicable.	Nil

Backfilling or In void stopes 5e General remarks No issue observed of inspecting backfilling/ waste related in stope officers on dumping was dumping after to backfilling. backfilling and proposed after full extraction of reclamation etc. full mineral. extraction of the mineral.

### Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	As per rule 26(2) of MCDR, 2017, PMCP report to be submitted for the previous year by 1st July.	PMCP report for the year 2023-24 has been submitted.	Nil
6b	Area available for rehabilitation (ha) .	No proposal.	Not applicable.	Nil
6c	afforestation done (ha).	2023-24: 2.05 ha gap filling	2023-24: 2.08 ha gap filling	Nil
6d	No. of saplings planted during the year	2023-24: 1800 nos.	2023-24: 5800 nos.	Nil
бе	Cumulative no .of plants	No specific proposal on cumulative number of plants.	209550 at the end of the RY 2023-24.	Nil
6f	Any other method of rehabilitation	No any other proposal.	Not applicable.	Nil
6g	Cost incurred on watch and care during the year	No proposal	Approximately: Rs. 74.31 lakh.	Nil
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling ( Lx B x D	2023-24 5,83,350 m3	2023-24 4,47,943 m3	Less U?G voids generated due to less production.

6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	2023-24: 4,28,191 m3	2023-24: 3,34,381m3	Less backfilling of U/G voids due to less production.
6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area	Not applicable being an underground mine.	Not applicable.	Nil
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	Not applicable being an underground mine.	Not applicable.	Nil
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	Not applicable being an underground mine.	Not applicable.	Nil
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	Total 1800 number of saplings during the RY.	Total 5800 numbers of saplings planted during the RY.	Nil
6n	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	2.05 hect. Gap filling plantation proposed in RY.	2.08 hect. area gap filling plantation carried out in RY.	Nil
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	Plantation	Plantation	Nil
бр	Compliance of environmental monitoring (core zone and buffer zone)	Proposal of environment monitoring has been envisaged	Environment monitoring carried out regularly.	Nil

6q General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.

The PMCP compliances is satisfactory.

### Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	No proposal of grade wise sorting of ROM.	Entire ROM was transported/dispatched to beneficiation plant.	Nil
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	No grade wise sorting of mineral, Entire ROM will be Beneficiated.	As per proposal	Nil
7c	Different grade of mineral sorted out at mines.	No proposal	Not applicable	Nil
7d	Any beneficiation process at mines .		Beneficiation of ROM was carried out at Dariba and SK beneficiation plant.	Nil

7e General remarks of inspecting officer on Mineral conservation and beneficiation

issues

General remarks No proposal of Entire ROM was of inspecting grade wise transported/dispatched officer on sorting of to beneficiation plant. Mineral ROM.

conservation and beneficiation.

mineral

No issue related

#### Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	top soil	No top soil generated during the RY 2023-24.	Nil
8b	Concurrent use or storage of topsoil	Not applicable as no proposal of top soil generation.	Not applicable.	Nil
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	reject and fines	Reject and fines was not generated during the RY. UG waste disposed as per proposal. Mill tailing disposed in tailing dam.	Nil
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Waste rock and tailing proposed to use in filling of UG voids/stopes.	Waste rock and tailing used for filling UG voids/stopes.	Nil
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No proposal during the reporting year.	Not applicable.	Nil

8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	saplings over 2.05 hect area (gap filling)	Total 5800 numbers of saplings planted over 2.08 hect area(gap filling) during the RY	Nil
8g	Survival rate	No proposal on survival rate.	Survival rate 85%	Nil
8h	Water sprinkling on roads to control airborne dust	<pre>air born dust, water sprinkling has</pre>	Water sprinkling has been observed on the roads to control airborne dust due to mining activity.	Nil
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area			The aesthetic beauty in and around the mine is satisfactory.

## Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	As per rule 45 of MCDR, 2017 monthly and annual returns to be submitted.	Monthly and annual returns have been submitted for the RY.	Timely submission.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Mining Engineer- Sanjay Kumar, Mine Manager- Sanjay Kumar, Geologist- Sandeep Kr. Rajput	Mining Engineer, Manager and Geologist are appointed.	AR 2023-24.
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	has been furnished under various	Details seems corrected.	AR 2023-24.
9d	Scrutiny of Annual return on afforestation	5800 no. of plants within lease area.	Information furnished is found in order.	Nil
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	•	Found in order.	Nil

9f	Scrutiny of Annual return on ROM stock and/or graded ore	 The information furnished found in order.	Nil
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	The information furnished appears to be in order.	Nil
9h	Scrutiny of Annual return on fixed assets	 The information furnished appears to be in order.	Nil
9k	Scrutiny of Annual return on mining machineries	 Details seems corrected.	Nil

PAGE: 15

# Details of violations observed during current inspection and compliance position of violation pointed out

Violation	n observed	Show couse position	
Rule NO.	Issued on Compliance on	Rule NO.	Issued on Compliance on
MCDR17 Rule 11(1)	19-JUL-24		

Date :

(DATA RAM GURJAR)

Indian Bureau of Mines