भारत सरकार / GOVERNMENT OF INDIA खान मंत्रालय / MINISTRY OF MINES भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक कार्यालय **OFFICE OF REGIONAL CONTROLLER OF** MINES



फैक्स: (080) 23371027 / 23373287 दूरभाष: 080-23371027 / 23375366/67 Email ID: ro. bangalore@ibm.gov.in सं/No.: KNT/BLR/Fe/437/BNG

29, इंडस्ट्रियल सबर्ब, 11 स्टेज, तुमकुर रोड, गोरगूंटापाल्या, येशवंतपुर, Bengaluru/ बेंगलुरु -560022 दिनांक/Dated:

सेवा में / To:

Shri D Abdulwaris S/o D. M. Umer Sab Nominated Owner M/s Marwa Mining Company 1st Cross, Rajiv Nagar, Mashallah Enterprises **HOSAPETE -583 201** Vijayanagara District, Karnataka Email: marwaminingcompany@gmail.com

विषय/Subject: Violation of provisions of MCDR, 2017 in respect of your Jigienehalli (Tonasigere) Mn Ore Mine (ML No. 2482) over an extent 22.45Ha, located in Jiginahalli village, Sandur Taluk, Ballari District, Karnataka State.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 04/12/2025 by undersigned in presence of Shri Venkata Rao K – Mines Manager and Shri M. Anil Kumar, Mining Engineer

Rules	Nature of Violations observed
11(1)	The Mining operations required to be carried out in accordance as per
	the approved Modifications in the Review and Updation of Mining Plan
	document vide letter no. 279/375/93/BNG dated 12/04/2022, However,
	during the inspection deviations were observed in mining operation vis-
	à-vis approved document and are as follows:
	During the year 2022-23, it was proposed to drill 11 no. of boreholes
	with a total meterage of 280m and 08 no. of exploratory pits to explore
	the mineralized area under G1 level. However, during inspection, it was
	observed that proposed exploration activities had not been carried out.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.

- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

डॉ. सुधाकर टी.एल. / Dr. Sudhakara T.L.) वरिष्ट खनन भूविज्ञानी / Senior Mining Geologist

Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

डॉ. सुधाकर टी.एल. / Dr. Sudhakara T.L.) वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist