



भारत सरकार / GOVERNMENT OF INDIA

खान मंत्रालय / MINISTRY OF MINES

भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES

Violation Letter / उल्लंघन पत्र

Reg. AD/Speed Post/Email/Fax

क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES

तृतीय तल, स्टालिन सेन्ट्रल, एम.जी. रोड, / 3rd Floor, Stalin Central, M.G. Road,

गवर्नरपेट, विजयवाड़ा, आंध्र प्रदेश - 520002 / Governorpet, Vijayawada, Andhra Pradesh - 520002

ई-मेल / Email: ro.vijayawada@ibm.gov.in

File No. AP/KNL/LST-218/HYD.

38 APR 11186

Date: 08/01/2025

फाईल क. ए.पी./कुर्नूल/चू.प.-218/हैदराबाद

38 ए.पी.आर. 11186

दिनांक 08/01/2025

प्रति / To,

Shri Chandrasekhar Pandey,  
Director and Nominated Owner,  
M/s Sree Jayajothi Cements Private Limited,  
9th Floor, Block -3, My Home Hub,  
Madapur, Hyderabad (Telangana) – 500 081

श्री चन्द्रशेखर पाण्डेय,  
डायरेक्टर एवं नामित मालिक,  
सर्वश्री जय ज्योति सीमेंट्स प्राइवेट लिमिटेड,  
9 वाँ तल, ब्लॉक - 3, माई होम हब,  
माधापुर, हैदराबाद (तेलंगाना) – 500 081

विषय : Violation of provisions of MCDR, 2017 in respect of your Palkur Limestone Mine over an area of 149.392 Ha. in Village Palkur, Mandal Banaganapalli, District Kurnool, State Andhra Pradesh.

महोदय / महोदया,

The following provisions of Mineral Conservation and Development Rules, 2017 (MCDR, 2017) were found violated in the above mine during analysis of the submitted drone data for the F.Y. 2022-23 & 2023-24 and accordingly the field inspection was carried out by the undersigned on 12/12/2024 in presence of the mine official Shri Narayana Reddy, Manager (Mines).

Rule No.	Nature of violation/ उल्लंघन का प्रकार
Rule No. / नियम संख्या 11 (1)	<p>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of minerals specified in Part B of the First Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession Rules, 2016.</p> <p><i>The following deviations have been found in the mine from the approved Review of Mining Plan vide letter no. AP/KNL/MP/Lst-139/Hyd. Hyderabad dated 25/11/2020 for the period of F.Y. 2021-22 to 2025-26.</i></p> <p><b>Production &amp; Development:</b></p> <p><b>(i) Working Pit:</b> During F.Y. 2023-24; It was proposed to carry out the production and development in between UTM Co-ordinates N1705609 to N1705865 and E843682 to E844125, whereas, production and development has been done at several places in between UTM co-ordinates N1705620 to N1705894 and E843610 to E844145 without any approved proposals.</p> <p><b>(ii) Dumping:</b> During F.Y. 2023-24; It was proposed to do the dumping in between UTM co-ordinates N1706160 to N1706186 and E845487 to E845531, whereas, dumping has been done in between UTM Co-ordinates N1706120 to N1706220 and E845478 to E845539. Moreover, there are several dumps have been observed within mining lease including 7.5 m barrier zone.</p> <p><b>(iii) Dump working:</b> Dump working has been observed in between UTM Co-ordinates N1705475 to N1705536 and E843838 to E843875 without any approved proposals.</p>

–2–

02. In this connection, it is brought to your notice that the violation of aforesaid rule constitutes an offence, punishable under Rule 62(1) of MCDR, 2017.

03. The mining operations and dispatches can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय,

(शैवाल कार्तिकेय)  
वरिष्ठ खनन् भूविज्ञानी  
भारतीय खान ब्यूरो, हैदराबाद

प्रतिलिपि: सूचनार्थ एवं आवश्यक कार्यवाही हेतु :-

1. खान नियंत्रक (दक्षिण), भारतीय खान ब्यूरो, बंगलूर (कर्नाटक) – 560022
2. The Director of Mines and Geology, Government of Andhra Pradesh, Sri Anjaneya Towers, Door No.7-104, B-Block, 5th and 6th Floors, BTPS Road, PO Ibrahimpatnam-521456, Vijayawada, Krishna District.

(शैवाल कार्तिकेय)  
वरिष्ठ खनन् भूविज्ञानी  
भारतीय खान ब्यूरो, हैदराबाद