



भारत सरकार/ Government of India
खान मंत्रालय / Ministry of Mines
भारतीय खान ब्यूरो / Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines



उल्लंघन नोटिस ईमेल द्वारा

To,

Shri Ajay Pal Singh Parmar
 Nominated Owner,
 Khera Majora Iron ore Mine 4.6 Ha
 S/o Mangal Singh Parmar ,
 10 Civil Line Chhatarpur ,
 MP Pin Code 471001
Email-khajurahomineral.sales@gmail.com

Subject:- Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect of your Khera Majora Iron ore Mine, over an area of 4.6 hectare, situated in village-Khera Majora, Tehsil : Baxwaha , District Chhatarpur of Madhya Pradesh State.

Sir,

Undersigned has inspected your mine in the presence of your representative Shri Rajneesh Mishra (Agent), Shri Praveen Rawat (Geologist) on 18/01/2025. Following provisions of MCDR 2017 were found violated in your mines at the time of inspection.

11(1) of MCDR 2017	<p>1. Mining operations under mining lease.-(1) No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2)</p> <p>The document of above mentioned mine was approved vide letter No. MP/Chattarpur/Iron ore/RMP-30/2019/20 dated 24/01/2020 incorporating proposal of working from 2020-21 to 2024-25</p> <p>During inspection it has been observed that the following provisions of the rule have been violated: -</p> <ol style="list-style-type: none"> 1. It was proposed to produce 102823 Tonnes of Iron ore, but only 19560 T of Iron ore is produced. 2. It was proposed to produce 3808.25 m3 of waste but only 450m3 of waste was produced thereby distorting the stripping ratio. 3. Pit has been developed in 7.5 m barrier. 4. It was proposed to maintain the bench height of 6m, but in actual height, of 10 m or more was maintained.
---------------------------	--

1. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
2. The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory.
3. You are advised to rectify the violations of above mentioned rules immediately and intimate the position to this office within 45 (days) days from the date of issue of this letter.

भवदीय,

(माधवराव साबरे)
 वरिष्ठ खनन भूविज्ञानी
 कृते क्षेत्रीय खान नियंत्रक

01. The Director, Director of Geology & Mining, Govt. of Madhya Pradesh, Khanij Bhawan, 29-A, Arera Hills, Jail Road, Bhopal (M.P.) for information and further necessary action.
02. The Controller of Mines (CZ), Indian Bureau of Mines, Nagpur for kind information.

(माधवराव साबरे)
 वरिष्ठ खनन भूविज्ञानी
 कृते क्षेत्रीय खान नियंत्रक