

I/37902/2024

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक कार्यालय
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,
सेक्टर-10A, गांधीनगर, गुजरात, 382010



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of Regional Controller of Mines
Karmayogi Bhavan, 4th Floor, Block-2, C Wing, Sec 10A
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

पत्रावली संख्या: JUNA/LST/303

Mine code 38GUJ08348

दिनांक:

सेवा में : भीमदेवल चुना पत्थर खान

मेसर्स जी एच सी एल लिमिटेड,

तालुका – सुतरापाड़ा, जिला – जूनागढ़ , गुजरात -362 268

e mail - manishkumar@ghcl.co.in, mining@ghcl.co.in

विषय: गुजरात राज्य के जूनागढ़ जिले की सुतरापाड़ा तालुका में स्थित आपकी भीमदेवल चुना पत्थर खान क्षेत्रफल- 56.351 हे. में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन।

महोदय,

आपकी उपरोक्त खान का स्टार रेटिंग/एम.सी.डी.आर निरीक्षण अधोहस्ताक्षरी द्वारा दिनांक 16-07-2024 को श्री विनोद कुमार (खान प्रबन्धक), चन्दन कुमार (भूविज्ञानी) एवं अन्य की उपस्थिति में किया गया तथा उक्त निरीक्षण के समय खनिज संरक्षण एवं विकास नियमावली, 2017 के निम्नलिखित नियमों का उल्लंघन पाया गया-

नियम सं./Rule No	उल्लंघन के प्रकार का विस्तृत ब्यौरा/ Detailed description of the type of violation
11(1)	The following work is not being done as per the Approved Review of Mining plan No 684(4)(1)/MP-206/2019 dated 14-03-2019:- 1. There was proposal of 38 drill holes with total meterage of 380 meters for the F/ y 2023-24. However the details submitted in Annual Return 2023-24 details of exploration is given as 9 holes & 117 meter.
45(5)(c) read with 45(7)	The following deficiencies have been found in the scrutiny of the annual return submitted by you for the year 2023-24 – 1. In PART-V (General Geology & Mining) at point 1 details of exploration is given as 9 holes & 117 meter, however at the time of inspection no core was shown. 2. In PART-V (General Geology & Mining) at point 2 Reserves and Resources estimated (in tonnes) (LIMESTONE) the exploration data is not found considered in updation of Reserves and Resouces. 3. In PART-V (General Geology & Mining) at point 3 Subgrade-Mineral Reject (in tonnes) (LIMESTONE) shown is greater than ROM production. 4. In per Part – VI, point 2 and 3, production of 41056.138 MT of ROM and 38592.770 MT of grade wise production is shown in the return. However the remaining quantity of 2463.368 MT is neither shown in the Subgrade-Mineral Reject column nor in any grade as the product grade is same as that of chemical grade.
47	Notice of shaft sinking and boreholes. – The holder of a mining lease shall send an intimation in Form I of the Schedule to the authorised officer, within fifteen days after the commencement of any of the following operations, namely:– (a) the sinking of trial shaft or borehole to a depth exceeding ten meters from the surface; or (b) the extension of an existing shaft or borehole to a depth exceeding ten meters; or (c) the sinking of a new shaft or boreholes commencing from underground workings: Provided that the authorised officer, as the case may be, may permit such intimation to be given collectively within such extended period as may be specified by him.

	However in your case no such records was found during the inspection.
1/37902/2024	<p>HoweveMCDR MisLsSTu70n2022GNR#BMROGNR you.</p> <p>Records of shafts and boreholes.– (1) The holder of a mining lease shall keep a record in Form-J of all shafts or boreholes and shall retain such records and preserve the samples of the strata passed through for a period of not less than twelve months after the completion of the work or abandonment thereof: Provided that the records of boreholes and shafts exceeding one hundred metres length shall not be destroyed except with the prior approval of the authorised officer, as the case may be.</p> <p>However in your case no such records was found during the inspection.</p>

1. In this connection, it is brought to your kind notice that above violations except Rule 45 :-
 - a) Constitute an offence punishable under Rule 62(1) of MCDR 2017 and/or;
 - b) Mining operations can be suspended as per rule 11(2) of MCDR 2017 in case of non-compliance of above rules as these violations also affects provisions of Rule11(1) of MCDR 2017 and/or;
 - c) You are advised to rectify the above violation of above Rules immediately and intimate the compliance position to this office, within a period of 45 days for violated rules from date of issue of this letter.
2. In case of violation of Rule 45,
 - a) Constitute an offence punishable under Rule 62(1) of MCDR 2017 and/or;
 - b) You are also liable to pay such amount as prescribed under MCDR 2017 for delay of each day as per **Schedule-II**, read with Rule **45(7A)** in case of non-compliance of various provisions of Rule 45.
 - c) As per provision of Rule **45(7) and/or45(7A)(ii)** the Regional Controller of Mines may take appropriate action including order of suspension of **all mining operations and dispatches** on non-compliance of various provisions of Rule 45.
3. In context to the violations of Rule 45, this letter has been considered as show cause notice where you are advised to rectify above violation immediately. You are therefore directed to show cause within a period of **30 days** for violations of Rule 45 from the date of issue of this letter as to why the action under Rules **45(7) and/or 45(7A)** shall not be taken against you. No further notice will be given to you in this regard.
4. This letter is being issued with the approval of Regional Controller of Mines.

भवदीय
Signed by Mohammad Nimar
Date: 19-08-2024 11:25:16
Reason: Approved
उप खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ हेतु प्रेषित/ Copy for favor and information:-

1. Controller of Mines(NZ), Udaipur
2. Commissioner of Geology and Mining, Gandhinagar
3. DDG, MMS Division, Nagpur
4. Guard File

उप खान नियंत्रक
भारतीय खान ब्यूरो