

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक कार्यालय
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,
सेक्टर-10A, गांधीनगर, गुजरात, 382010



Government of India
Ministry of Mines
Indian Bureau of Mines
Regional Controller of Mines
yogi Bhavan, 4th Floor, Block-2, C Wing, Sec 10A
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

पत्रावली संख्या: JUNA/LST-176

Mine code 38GUJ08042

दिनांक:

सेवा में : मेसर्स जीएचसीएल लिमिटेड
तालुका - वेरावल,
जिला - गिर सोमनाथ,
सूत्रापाडा- 362 275, गुजरात

e mail - mining@ghcl.co.in

विषय: गुजरात राज्य के जिले- गिर सोमनाथ की तालुका- तलाला में स्थित आपकी धमनवा गाभा चुना पत्थर खान,
क्षेत्रफल- 60.71 हे. में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन।

महोदय,

आपकी उपरोक्त खान का एमसीडीआर तथा स्टार रेटिंग निरीक्षण अधोहस्ताक्षरी द्वारा दिनांक 19-09-2024 को श्री राजेश तिवारी (खान प्रबन्धक एवं खनन अभियंता), शशिकांत शर्मा एवं अन्य की उपस्थिति की उपस्थिति में किया गया तथा उक्त निरीक्षण के समय खनिज संरक्षण एवं विकास नियमावली, 2017 के निम्नलिखित नियमों का उल्लंघन पाया गया-

नियम सं./ Rule No	उल्लंघन के प्रकार का विस्तृत ब्यौरा/ Detailed description of the type of violation
11(1)	The following mining operations were not carried out as per the Approved Review of Mining plan No 684(4)(1)/MP-377(19)/2021-22 dated 08-02-22 :- a) As per approved Mining Plan Mining operation shall be carried out leaving behind 7.5 m from lease boundary. However excavation was found near co-ordinates N 20.9985697, E70.5048493 in this barrier area. b) At point no 6.2.2.2.1 of PMCP proposal, there was proposal of 305 meters of fencing however no fencing was found at the time of inspection.

- In this connection, it is brought to your kind notice that :-
 - the above violations constitute an offence punishable under Rule 62 of MCDR 2017 and/or;
 - Mining operations can be suspended as per rule 11(2) of MCDR 2017 in case of non-compliance of above rules as these violations also affects provisions of Rule11(1) of MCDR 2017 and/or;
 - You are advised to rectify the above violation of above Rules immediately and intimate the compliance position to this office, within a period of 45 days for violated rules from date of issue of this letter.
- This letter is being issued with the approval of Regional Controller of Mines.

भवदीय

Signed by Mohammad Nimar

Date: 23-11-2024 11:40:25

(मोहम्मद निमर)

उप खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ हेतु प्रेषित/ Copy for favor and information:-

- Controller of Mines(NZ), Udaipur
- Commissioner of Geology and Mining, Gandhinagar
- Guard File

उप खान नियंत्रक
भारतीय खान ब्यूरो