

पंजीकृत पावती
उल्लंघन
पत्र



भारत सरकार
Government of India
खान मंत्रालय
Ministry of Mines
भारतीय खान ब्यूरो
Indian Bureau of Mines
Mine Code: 38RAJ20008

माखुपुरा औद्योगिक क्षेत्र,
Makhupura, Industrial Area
अजमेर – 305 002 (राजस्थान)
Ajmer- 305 002 (Rajasthan)

संख्या E/2648/MCDR-MiFLOLST/7/2022-AJM-IBM_RO_AJM

दिनांक : 11.11.2024

प्रेषित: Mines Agent,
Marwar Mundwa Limestone Mine No.1,
M/s Amubja Cement Ltd.,
Post & Tehsil- Marwar Mundwa,
District-Nagaur (Raj) 341026
E-mail: chetan.raval@adani.com,jitendraprasad.kumawat@adani.com

विषय : Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your **Marwar Mundwa Limestone Mine No. 1** (M.L. 111/2007, Lease area 699.9 Hect.) in Nagaur District of Rajasthan State.

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection made on 03.10.2024 & 04.10.2024 by the undersigned in presence of Sh. Jitendra Prasad Kumawat, Mines Manager & Sh. Mayur B Potkatara, Geologist:

Rule No.	Nature of violation observed in detail
Rule 11(1)	The mining operations are carried out in violation of following provisions of approved Review of Mining Plan (Approved on 22.12.2022): 1) During the year 2023-24, mine development was proposed between UTM grid 386051E to 386816E & 2997667N to 2998090N whereas actual mine development has been carried out between UTM grid 386051E to 387000E & 2997667N to 2998700N. It shows that mine development has been extended towards Eastern & Northern side of existing pit without proposal. 2) The area put to use under head mining was proposed 74.43 hectare at the end of year 2023-24 whereas as per submitted annual return the area put to use under head mining is 81.76 hect. 3) During the year 2023-24, the Ore to OB ratio was proposed 10.0018(T/m3) whereas actual Ore to OB ratio was achieved 22.17 (T/m3) it shows that proportionate mine development has not been carried out as per proposal. 4) During the year 2023-24, total 54252 m3 top soil generation was proposed whereas no top soil generated during the reporting year, it shows that no proper assessment of top soil generation has been carried out. 5) During the year 2023-24 the location of retaining wall changed with respect to proposal.

02 इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दण्डनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अंतर्गत :

- (क) आपकी खदान की सारी संक्रियाएं बंद की जा सकती हैं ।
- (ख) आपके विरुद्ध अभियोग दायर किया जा सकता है ।
- (ग) खनन पट्टे को निरस्त करने की सिफारिश राज्य सरकार से की जा सकती है ।

03 अतः आपको यह निर्देशित किया जाता है कि आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की दिनांक से 45 (पैंतालीस) दिनों के भीतर इस कार्यालय को प्रेषित करें ।

भवदीय

(डी. आर. गुर्जर)
उप खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि, सूचनार्थ प्रेषित : -

1. खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ईमेल द्वारा) ।
2. निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर ।
3. खनि अभियंता, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, नागौर ।
4. रक्षित पत्रावली ।