

Violation Notice Letter

By e-mail

**भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,
BHUBANESHWAR**

File

Date : 25/09/2025

No.: MCDR-MiFL0FE/34/2023-BBS-IBM_RO_BBS

To: Shri/M/s. Mr Balwant
Singh, Nominated Owner,
THE ORISSA MINING
CORPORATION LIMITED,
A GOVT. OF ORISSA
UNDERTAKING ,OMC
HOUSE, UNIT-5, POST BOX
NO.34, BHUBANESWAR,
Unchabali Village & Mandal,
Kendujhar district, Odisha,-
751001

Subject : Violation of provisions of MCDR, 2017, in respect of your Unchabali (Mahaparbat) Iron Mine (30ORI08087) over an area of 68.00 Ha. in Balda, Kundapasi and Unchabali Villages, Keonjhar district of Odisha State.

Sir, The following provision of MCDR 2017 were found violated in your above mine during the inspection carried out on 27th July 2025 by the undersigned in presence of the mine officials S/Shri Pravin Mahanta, Mines Manager, Pradeep Kumar Sahoo, Senior Manager (Mining) and other Mine Officials.

Summary of Violations :

Items for Reporting	As Per Plan	Actual	Deviati on	Rule	Reason
Exploration: UNFC category wise reported Resources/Reserves as per MP/MMP ROMP Total Reserves (111, 121 & 122) and Total Mineral Resources (331, 332 & 333 upto 334)	IRON ORE - Total Reserve 761443 5.00 , Total R esource 290892 0.00	Mineral reserves 111 - 0.00 ; 1 21:4562 184.00 ; 122: 11 3813.00 ; Total: 4,675,9 97.00 Mineral resourc es 211: 0.00 ; 221 : 28 58100.0 0 ; 222: 50812.0 0; 331: 0.00 ; 332 :0.00; 333: 0.00; 334 : 0.00 Total Reserve 4,675,9 97.00 , Total R esource 2,908,9 12.00	Deviati on obse rved as Reserve s in 111 have been in dicated as 0 whereas in the m odificat ion sub mitted the reserves have been shown as 7003 004.10	Rule 45(7),	
Development - Opencast: Location of development	QUAR RY-2 (2 420972 N TO 2	QUAR RY-1 (2 420792. 53N TO	Deviati on obse rved	Rule 11(1),	

w.r.t. lease area	421377 N & 33 6899E TO 337 237E FROM 606mR L to 58 8mRL) QUAR RY-3 (2 420324 N TO 2 421013 N AND 337161 E TO 3 37459E FROM 600mR L to 55 2mRL	242098 2.607N AND 3 36774.1 07E TO 336956. 254E FROM 600mR L to 57 9mRL) QUAR RY-2 (2 421025 N TO 2 421271 N AND 336899 E TO 3 37136E FROM 611mR L to 58 8mRL) QUAR RY-3 (2 420399 N TO 2 421004 N AND 337164 E TO 3 37456E FROM 600mR L to 55 2mRL)			
Development - Opencast: Quantity of overburden generation in m3	675141. 00	284434. 65	390706. 350	Rule 11(1),	Less

Development - Opencast: Quantity of topsoil generation in m3	1450.00	476	974.000	Rule 11(1),	
Exploitation - Opencast Mine: Quantity of ROM mineral production proposed (in T)	100000 0.00	980000	20000.0 00	Rule 11(1),	
Exploitation - Opencast Mine: Quantity of mineral reject/Sub-grade generation	21310.0 0	46368	-25058. 000	Rule 11(1),	
Solid Waste Management - Backfilling (Opencast): Year-wise area under backfilling of mined out area	2.13	1.45	0.680	Rule 11(1),	

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017. 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory. 04. You are advised to rectify the violation immediately and intimate the position to this office within a period of 45 (Forty five) days from the date of issue of this letter.

Yours faithfully,

(VIKRAM DESHPANDE, BHUBANESHWAR)
ACOM

Esigned by: MKRAM
Date: 26/09/2025 11:16:38 AM