



Government of India
Ministry of Mines
Indian Bureau of Mines

Office of the Regional Controller of Mines



Phone No: (0651) - 2242889
Fax No: (0651) - 2242903
E-Mail : ro.ranchi@ibm.gov.in

Prabandhan Nagar,
Murma, Nayasarai,
Near IIM,
Ranchi -835303

Violation Letter

Registered A/D/Email:
25/11/2025

To,

1. Shri Satish Pai,
Nominated Owner,
M/s Hindalco Industries Pvt LTD,
4202 The Imperial B B Nakashe Tardeo
Mumbai, Maharashtra-400034
Email:satish.pai@adityabirla.com,
2. Shri Shatrujit Kumar,
Mine Agent, M/s Hindalco Industries Limited,
Lohardaga, Jharkhand.
shatrujit.kumar@adityabirla.com.

Mine code -07BHR32009

Sub.: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Jalim and Sanai Bauxite Mine over area 38.447 ha in Gumla District of Jharkhand State.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated during the inspection of your above mine carried out on 04/11/2025 by the undersigned in the presence of Shri. Tapas Gachhayat, AGM (Geology), Shri Debjyoti Das (Asst Manager Geology), Shri Chandrasekhar Prasad (Mines Manager), Shri Satyabrata Behra (Mining Engineer).

01.

Rule No.	Nature of violation observed
----------	------------------------------

Rule-11(1):	No holder of a mining lease shall commence or carry out mining operation in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines.
--------------------	--

In your case, mining operations are not carried out in accordance with approved Review of mining plan along with Progressive mine closure plan, vide letter no. RAN/LOH/BXT/ROMP-3/2022-23, dated 06/02/2023 to the extent indicated below:

- a. 6.2 Solid Waste Management - Backfilling (Opencast) / Backfilling for 'Reclamation and Rehabilitation' and its plan as shown in plates annexed was not carried out as per the

Contd. ---- 2/-

proposal approved and hence not implemented at Quarry 2 and Quarry 3 in approved Review of Mining Plan during the year 2024-25.

- b. 6.2.3 Progressive Mine Closure Plan: Compliance on reclamation and rehabilitation by plantation: Total area for backfilling and numbers of plantation proposed was not carried as per the approved ROMP along with PMCP.
- c. 6.2.9 Environment: Phased restoration: Top soil Management was not carried out as proposed in approved ROMP along with Progressive mine closure plan.

-
02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule-62 of MCDR-2017.
 03. You are, therefore, advised to rectify the above violations immediately and intimate the position to this office within 45(forty-five) days from the date of issue of this letter.

Yours faithfully

(Vikrant Murlidhar Khedikar)
Senior Assistant Controller of mines)

Copy forwarded for kind information to:

1. **The Controller of Mines (EZ)**, Indian Bureau of Mines, Block-CP, Plot no.-13, Salt Lake, Sector-V, Kolkata- 700091.
2. **The Director (Mines)**, Department of Mines & Geology, Govt. of Bihar, 1st Floor, Vikas Bhawan, Patna – 800015

(Vikrant Murlidhar Khedikar)
Senior Assistant Controller of mines)