

भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,
DEHRADUN

File No.: MCDR-MiFL0LST/12/2022-DDN-IBM_RO_DDN

Date : 12/01/2026

To: Shri/M/s. N/A, Nominated Owner,
DEEPAK, 7A, Haridwar Road
,DEHRADUN, UK, Dehradun, Shiwa
Ridana (40) Village & Mandal, Sirmaur
district, Himachal Pradesh,- 248001

Subject: Violation of provision of Mineral Conservation and Development Rules, 2017 in respect of your 38HPR10035(38HPR10035) over an extent of 4.75 ha in Shiwa Ridana (40) in , Sirmaur, Himachal Pradesh

Sir, The above mine was inspected on 02.12.2025 by the undersigned in the presence of Shri RC Malik, Mine Manager and Owner Shri Deepak Chawla. During the inspection, the following provisions of the Mineral Conservation and Development Rules, 2017 were found to be violated.

Summary of Violations :

Items for Reporting	As Per Plan	Actual	Deviation	Rule	Reason
Drone Data submission	As per rule 34A(2), Every lessee, shall submit soft copy of high resolution Georeferenced Orthorectified Multispectral satellite images of the leased area and up to hundred metres outside the lease boundary as specified by the Indian Bureau of Mines.	The submitted data for the year 2024 is not as per SOP of IBM. The file can not be extracted.	File can not be extracted so Drone data analysis could not be done.	Rule 34A(2),	

OB / Waste Dumps details: Separate dumping of topsoil, OB & mineral rejects, fines, tailings (Rule 36,37)	Not Proposed	Dumping of overburden has been observed during inspection.	Deviation observed	Rule 11(1),	
Development - Opencast: Stripping ratio : ore to OB ratio	1:0.0	9.0827	9.0827	Rule 11(1),	
Development - Opencast: Quantity of overburden generation in m3	No overburden proposed in the reporting year.	4500 m3 of waste overburden generated as per Annual Returns 2024-25.	4500 m3	Rule 11(1),	
Development - Opencast: Location of development w.r.t. lease area	Development was proposed in both eastern block and Western Block. In Eastern Block from 1385 mRL to 1375 mRL with height of benches 5 meters. In Western Block from 1255 mRL to 1240 mRL with height of benches 5 meters.	Development work was not carried out in the Eastern block as per proposals given in mining plan. Lower most bench height is higher than 5 meters.	Lower most bench height is around 8 meters.	Rule 11(1),	

Esigned by: Matiul
Date: 19/01/2026 01:10:01 PM

In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017. 2) The mining operations can be suspended under the rule 11(1) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory. 3) You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,

(Matiul Islam, DEHRADUN)
Sr ACOM