

Violation Notice Letter

By e-mail

भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,
DEHRADUN

File No.: MCDR-MiFL0LST/9/2023-DDN-IBM_RO_DDND

Date : 15/01/2026

To: Shri/M/s. N/A, Nominated Owner,
SAVITA, 1766/7 ,SHAMSHER GANJ,
NAHAN, Shamahn Pamta (243) Village &
Mandal, Sirmaur district, Himachal
Pradesh,- 173001

Subject: Violation of provision of Mineral Conservation and Development Rules, 2017 in respect of your
38HPR10060(38HPR10060) over an extent of 3.1 ha in Shamahn Pamta (243) in , Sirmaur, Himachal Pradesh

Sir, The above mine was inspected on 03.12.2025 by the undersigned in the presence of Shri Ajay Purkayastha, Mine Manager and during the inspection, the following provisions of the Mineral Conservation and Development Rules, 2017 were found to be violated.

Summary of Violations :

Items for Reporting	As Per Plan	Actual	Deviation	Rule	Reason
PMCP data not attached.	PMCP data not attached with the annual return 2024-25.	PMCP data not attached with the annual return 2024-25.	PMCP data sheet not attached with the annual return.	Rule 45(7),	
Mineral Conservation: ROM Mineral dispatch or grade-wise sorting within lease area	60,000 tones Production has been proposed.	Dispatch from the mine head is 26,638 tonnes.	ROM Mineral dispatch is significantly lower than what was proposed (33,362 tonnes deviation).	Rule 11(1),	
Progressive Mine Closure Plan: Compliance on reclamation and rehabilitation by backfilling/Other means Total area and numbers of plantation proposed.	Reclamation and rehabilitation only proposed by filling voids and preparing parapet walls, roads. Total area and numbers of plantation proposed- 0.056 Ha with 60 plants.	No plants observed during inspection over 0.056 Ha area. No PMCP sheet attached with the Annual return of 2024-25. No mineral rejects are being generated as per proposal for rehabilitation. No parapet walls observed during inspection.	100% deviation. No plantation observed during inspection.	Rule 11(1), Rule 44,	
Solid Waste Management - Backfilling (Opencast): Locations of proposed reclamation & rehabilitated	It has been mentioned in the approved mining plan that the mineral rejects generated will be used to fill up the voids within the mineralized zones and also will be used to create parapet wall and roads.	No mineral rejects are being generated. No parapet walls observed during inspection.	No parapet wall observed during inspection.	Rule 11(1),	

Exploitation - Opencast Mine: Quantity of mineral reject/Sub-grade generation	1% (600 tonnes)	0 as per annual return for the reporting year.	Mineral reject quantity proposed to be 600 tonnes but generated nothing. A clarification is required.	Rule 11(1),	
Exploitation - Opencast Mine: Quantity of ROM mineral production proposed (in T)	60000	26638 As per submitted annual return for the reporting year.	33362.000	Rule 11(1),	
Development - Opencast: Location of development w.r.t. lease area	Development proposed From BP-4 to BP-10 from 1358 mRL to 1346 mRL with bench height proposed 6 meters.	Development work not carried out as per proposal. Bench height near BP-5 is greater than 6 meters around 12 meters.	Bench height found to be 6m higher than proposal.	Rule 11(1),	

Signed by: Matiul
 Date: 29/01/2026 12:42:55 PM

1) In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017. 2) The mining operations can be suspended under the rule 11(1) & 45(7) of MCDR-2017, if compliance of rule 11(1) & 45(7) of MCDR-2017 is not found satisfactory. 3) You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,

(Matiul Islam, DEHRADUN)
 Sr ACOM