Speed post with A/D

Violation Letter



GOVERNMENT OF INDIA MINISTRY OF MINES INDIAN BUREAU OF MINES OFFICE OF REGIONAL CONTROLLER OF MINES

AJA

REGISTRARS
MANAGEMENT
SYSTEMS

ISO 9001:2008

0059

29, Industrial Suburb, II Stage, Tumkur Road, Gorguntapalya, Yeshwantpur, Bangalore- 560 022.

Dated: 23/08/2017

FAX: 080-23371027 / 23373287
Tel: 080-23371027 / 23375366 / 67
Email ID: ro.bangalore@ibm.gov.in

No: KNT/GLB/Lst-54/BNG

Shri Desh Deepak Khetrapal Managing Director M/s Orient Cement Limited 5-9-22/57/D, GP Birla Centre, Adarsh Nagar, Hyderabad-500063 Telangana Shri. Pramod Kumar Singhania, Mines Agent M/s. Orient Cement Limited,

Village : Itagi, Taluk: Chittapur – 585211,

Dist- Kalaburgi, Karnataka

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Itagi Limestone (ML.NO. 2681) over an extent of 519 Ha Area in Gulbarga-Dist of Karnataka State
Sir,

The following provisions of Mineral Conservation & Development Rules, 2017 were found violated during inspection of your above mine on 7/8/2017 by the undersigned in presence of Shri K. Arunachalam, Mines Manager & other mine officials.

Rule No.	Nature of violation observed
11 (1)	The mining operations are not being carried out as per the approved Modified Mining Plan No-279/1060/2012, dated 28/09/2015 to the extent as mentioned below.
	(i)Exploration: 36 nos of core boreholes with 1800 total meterage during year 2015-16 (1 st year) and 15 nos of core boreholes with 750 total meterage during year 2016-17 (2 nd year) were proposed. However, 22 nos of core boreholes with 1200 total meterage were drilled so far, against 51 nos of boreholes with 2550 total meterage.

	(ii)Development: During year 2016-17(2 nd year), 173,561 m ³ top-soil wastes generated against the proposed 57,025 m ³ top soil wastes, thereby resulted in (+) 204% deviation . This may lead to deviation in ROM/waste ratio of 1:0.2 against
	proposals of 1:0.06. (iii) Top-soil/waste has not been stacked/dumped near southern side lease boundary as proposed. However, the same has been dumped / stacked in west-central part near to Seasonal Nala.
35 (2)	The copy of high resolution satellite image obtained from CARTOSAT-2 satellite LISS-IV sensor on the scale of cadastral map as on 31/3/2017 covering the mining lease and an area of two kms from lease boundary has not been submitted so far.

- 02. In this connection, it is brought to your notice that the above violations constitute an offence, punishable under Rule 62 of MCDR, 2017. The relevant extract of the rule 62 is given below: "62 Penalty:- Whoever contravenes any of the provisions of these rules shall be punishable with imprisonment for a term which may extend to two years or with fine which may extend to five lakh rupees, or with both, and in the case of a continuing contravention, with additional fine which may extend to fifty thousand rupees for every day during which such contravention continues after conviction for the first such contravention".
- 03. The mining operations can be suspended under rule 11(2) of MCDR 2017, if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

Sd/-

(Prashant S. Hegde)
Senior Mining Geologist

Copy forwarded for kind information:--

- 1) The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560 001
- 2) The COM(SZ), IBM, Bangalore.

Sd/-

(Prashant S. Hegde)
Senior Mining Geologist