

भारत सरकार /Government of India
खान मंत्रालय/Ministry of Mines
भारतीय खान ब्यूरो/ Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक का कार्यालय/Office of the Regional Controller of Mines

Phone No.: (0832)- 2741757
Fax No. : (0832) –2741758
E-Mail : ro.goa@ibm.gov.in
File No:- KNT/BJP/LST/59-GOA

Opp.Old R.T.O.'s Office,
P.O. FATORDA - 403602,
Margao-GOA
Date:- 30.12.2020

MINE CODE :- 38KAR26022

To,

Shri B.C.Udapudi, Lessee
Muddapur Limestone & Dolomite Mine (ML No.2534),
Main Bazar Road,Lokapur-587122,
Bagalkot District, Karnataka

Sub :Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Muddapur Limestone & Dolomite Mine (ML No.2534) situated in Village – Muddapur, Taluka- Mudhol, District-Bagalkot of Karnataka State.

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 08/12/2020 by the undersigned in presence of Shri M. Udapudi and Shri N.Murthy, Lessee representative

Rule	Nature of Violation observed
11(1)	Mining operations have not been carried out in accordance with the modification of Mining Plan approved vide MP/OTF.MECH-02/GOA/2016-17 dated 08/02/2017. Working benches in both limestone and dolomite pits, from E5354450 to E535600 were not found to be maintained systematic and scientific manner as loose boulders were found scattered all over the benches were found to be maintained disoriented and zigzag manner. The aforesaid violation was pointed out by this office vide letter even no, dtd 28.02.2020. However, it has observed in the office record that the outstanding violations are not complied so far.
35(2)	Every holder of a mining lease shall monitor his mining and allied activities as per the notified template of star rating in the format prescribed in this behalf by the Indian Bureau of Mines from time to time, and shall submit online its selfassessment report before the 1st day of July every year for the previous financial year, alongwith the soft copy (in the standard format), of high resolution satellite images obtained from CARTOSAT-2 satellite LISS-IV sensor on the scale of cadastral map, as on the 31st day of March for that financial year, covering the mining lease and an area of two kilometres. from the lease boundary, to the Regional Controller or the authorised

	officer of the Indian Bureau of Mines.
11(1) & 26(2)	An yearly report on progressive Mine closure Plan before 1 st July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive Mine closure plan has not been submitted for the year 2019-20.
55(1) (c) (i)	For the purpose of carrying out reconnaissance, prospecting or mining operations in accordance with these rules:“Every holder of a mining lease shall employ, in case of category ‘A’ mines, a full time mining engineer and a full time Geologist”. However during the inspection it was observed that a full time Mining Engineer and Geologist has not been employed under this rule.
33	The updated Plans and sections as required under rule 32 are not submitted/maintained.

02. It is observed from the office record that you have not complied the violation issued by this on dated 28.02.2020 so far. Further, it has observed from the office records that the some violations are in repeated in nature from the long back.This shows that, no action were taken from the your end to rectify the outsnndaing violations of the rule 11(1), 26(2), 35(2) and 55(1) of MCDR,2017.

03.In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

04. You are therefore,directed to show cause within period of **thirty (30)** days as why you should not be prosecuted for the above offence and/or why mining operations shall not be suspended as per provision of rule 11(2) of MCDR,2017..

05. Please note that no further notice will be given to you in this regards.

Yours faithfully,

(S.Prasad)
Deputy Controller of Mines & Officer Incharge
Indian Bureau of Mines

Copy forwarded to: -

1. The Controller of Mines, SZ, Indian Bureau of Mines, Bengaluru.
2. The Director, Directorate Mines and Geology, Govt.of Karnataka 49, Khanij Bhavan,Race Course Road, Bengaluru.

(S.Prasad)
Deputy Controller of Mines & Officer Incharge
Indian Bureau of Mines