### MCDR INSPECTION REPORT

#### 1.0 **GENERAL**

	EIVERAL	
SN	Particulars	Details
1(a)	Name of the Mine	Adityana – A-1, F & D-Plot Limestone Mine
1(b)	Name of Inspecting Officer & Designation	Sanjay M. Girhe, Sr. Mining Geologist
1(c)	Accompanying Mines Representatives	Sh. C.M.Diwedi, Geologist & Sh. D.Gaur, TQP
1(d)	Type of Inspection	Review of Mining Plan
1(e)	Date of Inspection	01.04.2018
2	Total Lease Area (Ha) with breakup of Non-	42.90 Hectare
	forest and forest land	
3	Minecode	38GUJ08231
4	IBM Registration Number under rule 45 of MCDR, 1988	IBM/437/2011
5	Name of the lessee, Address, phone, email and fax number	Tata Chemicals Limited P.ORanavav Quarries, Taluka-Ranavav, Dist- Porbandar, Gujarat – 360550 Ph No-+912801230381, Fax No-+912801230320
		Email:cdwivedi@tatachemicals.com
6	Village	Adityana
7	Taluka/Mandal	Ranavav
8	District	Porbandar
9	Pincode	360545
10	State	Gujarat
11	Post office	Adityana
12	Nearest police station	Adityana
13	Nearest Railway station	Ranavav
14	Date of Grant of Mining Lease	27.07.1971
15	Date of Execution	29.04.1972
		29.04.1972
16	Date of opening of Mine	- I I I 22 10 1000 for a series
17	Date of first Renewal, if applicable and its period & expiry	First renewal was applied on 22.10.1990 for next 10 years
18	Date of second Renewal, if applicable and its period & expiry	Second renewal was applied on 23.10.2000 for next 20 years
19	Date of submission of renewal application if Mining Operations are continuing under deemed extension	23.10.2000
20	Name of the Nominated Owner with Address, phone, email, fax number and date of appointment	R. Mukundan Tata Chemicals Limited Bombay House, 24 Homy Modi Street, Mumbai – 400001, Maharastra
21	Name of the Mine Agent with Address, phone, email, fax number and date of appointment	C M Dwivedi Tata Chemicals Limited P.ORanavav Quarries, Taluka-Ranavav, Dist- Porbandar, Gujarat – 360550 Ph No-+912801230381, Fax No-+912801230320 Email:cdwivedi@tatachemicals.com
22	Name of the Mines Manager with Address, phone, email, fax number and date of	NA- (Mine not in operation since 17.12.2009 due IBM notice for suspension of all mining operation
	appointment in mines	vide letter dtd 10.12.2009)
23	Name of the Mining Engineer, Qualification and total experience with Address, phone, email, fax number and date of appointment in mine	NA- (Mine not in operation since 17.12.2009 due IBM notice for suspension of all mining operation vide letter dtd 10.12.2009)
24	Whether Geologist and Mining Engineer appointed in mines satisfy the rule 42 & carrying out their duties as per rule 43 & 44.	NA

25	Date of Approval of Mining Plan/Modified Mining Plan with five-year period and specific condition in approval letter, if any.	682(23)(761)/97-MCCM(N)UDP, Dt-8.06.1998
26	Date of Approval of Scheme of	682(23)MS-201/2003-UDP, 22.7.2003.
	Mining/Modified Scheme of Mining with five-year period and specific condition in approval letter, if any.	682(23)MS-422/2008-UDP, 17.7.2008
27	Mineral(s) granted in lease and proved for mining	Limestone
28	Method of Mining (Opencast, Underground)	Opencast
29	Category (Fully Mechanised, Others or	Mechanised.
	Manual)	
30	Captive/Non Captive	Captive

Scientific Mining: Compliance of proposals of approved mining plan/scheme of mining. –  ${\bf Exploration}$ 

SN	Item	Proposals (2017-18)	Actual work	Remarks
1a	Backlog of previous year	Not Proposed	NA	Mine not in operation since 17.12.2009 due
1b	Exploration over lease area for Geological axis 1 or 2.	Not Proposed	NA	IBM notice for suspension of all
1c	Exploration Agency & Expenditure in lakh Rupees during the year	Not Proposed	NA	mining operation vide letter dtd 10.12.2009
1d	Balance area to be explored to bring Geological axis in 1 or 2	Not Proposed	NA	
1e	Balance reserves as on 01.04.2018	Proved (111)-0.22 (Million Ton) Resources-00	0	
1f	General remarks of inspecting officer on geology, exploration etc.	Entire lase area has bee MEMC Rules, 2015	en explored as per	UNFC Guidelines and

2.0 Development

SN	Item	Proposals(2017-18)	Actual work	Remarks
2a	Location of development w.r.t.	No Proposals	Not Applicable	
	lease area			
2b	Separate benches in topsoil, overburden and mineral (Rule 15)	No Proposals		
2c	Stripping ratio or ore to OB ratio	No Proposals		
2d	Quantity of topsoil generation in m3	No Proposals		
2e	Quantity of overburden generation in m3	No Proposals		
2f	General remarks of inspecting officer on development of pit w.r.t. type of deposit etc.	Mine not in operations suspension of all minin Hence, mine temporarily	ng operation vide	letter dtd 10.12.2009.

3.0 Exploitation

SN	Item	Proposals (2017-18)	Actual work	Remarks
3a	Number of pits proposed for	Not Proposed	Not Applicable	
	production			
3b	Quantity of ROM mineral	Not Proposed	Not Applicable	
	production proposed			
3c	Recovery of salable/usable	Not Proposed	Not Applicable	
	mineral from ROM production			

3d	Quantity of mineral reject generation	Not Proposed	Not Applicable	
3e	Grade of mineral reject generation and threshold value declared	Not Proposed	Not Applicable	
3f	Quantity of sub-grade mineral generation	Not Proposed	Not Applicable	
3g	Grade of sub-grade mineral generation	Not Proposed	Not Applicable	
3h	Manual / Mechanised method adopted for segregating from ROM	Not Proposed	Not Applicable	
3i	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	Not Proposed	Not Applicable	
3j	Provision of drilling & blasting in mineral benches	Not Proposed	Not Applicable	
3k	Provision of mining machineries in mineral benches	Not Proposed	Not Applicable	
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Not Proposed	Not Applicable	
3m	Total area covered under excavation/pits	36.09	36.09	
3n	Ore to OB ratio for the pit/mine during the year	Not Proposed	Not Applicable	
30	Total area put in use under different heads at the end of year	Pit- 36.09 Waste/reject Others- 6.81	Pit- 36.09 Waste/reject Others- 6.81	
3p	Production of ROM mineral during last five-year period, as applicable	Yr- 2012-13 Yr- 2013-14 Yr- 2014-15 Yr- 2015-16 Yr- 2016-17	0 0 0 0 0	NIL
3q	General remarks of inspecting officer on method of mining etc.	Mine not in operation suspension of all min Hence, mine temporari	ing operation vide le	etter dtd 10.12.2009.

## 4.0 Solid Waste Management-Dumping

SN	Item	Proposals (2017-18)	Actual work	Remarks
4a	Separate dumping of topsoil,	NA, No mines waste,	NA, No mines	
	OB & mineral reject (Rule 32,	concurrent use of top	waste, concurrent	
	33)	soil for plantation	use of top soil for	
			plantation	
4b	Location of topsoil, OB &	Not Proposed	Not Applicable	NIL
	mineral reject dumps			
4c	Number of dumps within lease	Not Proposed	Not Applicable	NA
	area and outside lease area			
4d	Location of dumps w.r.t.	Not Proposed	Not Applicable	NIL
	ultimate pit limit (Rule 16)			
4e	Number of active & alive	Not Proposed	Not Applicable	Nil
	dumps	_		
4f	Number of dead dumps	Not Proposed	Not Applicable	NIL
4g	Number of dumps stabilized	Not Proposed	Not Applicable	Nil
4h	Whether Retaining wall or	Not Proposed	Not Applicable	Nil
	garland drain all along dumps	_		
	are there			

4i	Length of Retaining wall or	Not Proposed	Not Applicable	Ni
	garland drain all along dump			
4j	Number of settling ponds	0	0	0
4k	Specific comments of	Mine not in operations	since 17.12.2009 d	ue IBM notice for
	inspecting officer	suspension of all mining	g operation vide lei	ter dtd 10.12.2009.
		Hence, mine temporarily discontinued from 16.12.2009		

5.0 Solid Waste Management-Backfilling

SN	Item	Proposals (2017-18)	Actual work	Remarks
5a	Status on part or full extraction	Not Proposed	Not Applicable	
	of mineral from mined out area			
	before starting backfilling			
5b	Area under backfilling of	Not Proposed	Not Applicable	
	mined out area			
5c	Concurrent use of topsoil for	Not Proposed	Not Applicable	
	restoration or rehabilitation of			
	mined out area (Rule 32)			
5d	Total area fully reclaimed &	Not Proposed	Not Applicable	
	rehabilitated			
5e	General remarks of inspecting	Mine not in operations		
	officer on backfilling,	suspension of all mining		
	reclamation etc	Hence, mine temporarily discontinued from 16.12.2009		

## **6.0 Progressive Mine Closure Plan**

nnual report on	No. Due to mine	No. Due to mine	
			nil
nitted on time and	discontinued.	discontinued	
Rule 23E(2).			
ven in Annexure-			
			nil
	discontinued	discontinued	
` '			
•			
	NI A	NI A	
	NA	INA	
tation by			
ailable for			
•			
•			
	NA	NA	Nil
tion			
abilitated (ha)			
of rehabilitation			
	Rule 23E(2).  Ild be given in the even in Annexure-  Int of worked/mined of the label for on (ha) aplings planted over the reactive no. of plants or specific method attion the label for (L X B X D) and the label for	ald be given in the even in Annexure-  ant of worked/mined alable for on (ha) antion done (ha) aplings planted rear give no. of plants or specific method attion arrived on watch & the year on reclamation tation by antiable for (L X B X D) ed by waste/tailings attion on the rea tation by making yoir or specific means of Rehabilitation ad within lease tion abilitated (ha)	ald be given in the even in Annexure-  ant of worked/mined lable for on (ha) ation done (ha) applings planted rear even no. of plants or specific method ation urred on watch & the year even or reclamation tation by anilable for (L X B X D) ed by waste/tailings ation on the rea tation by making coir or specific means even of Rehabilitation and within lease tion abilitated (ha)  No. Due to mine discontinued  No. Due to mine discontinued

бе	Compliance of Environmental monitoring (core zone & buffer zone)	Core Zone with in limit  — Ambient Air Quality, Surface water Quality, Ground water quality, Noise level, Noise vibration are with in limit	Core Zone with in limit – Ambient Air Quality, Surface water Quality, Ground water quality, Noise level, Noise vibration are with in limit	Nil
6f	General remarks of inspecting officer on PMCP compliance & progressive	Mine not in operations suspension of all mining Hence, mine temporarily d	g operation vide lette	r dtd 10.12.2009.

# 7.0 Mineral Conservation

SN	Item	Proposals (2017-18)	Actual work	Remarks
7a	ROM Mineral dispatch or	0	0	NIL
	grade-wise sorting within			
	lease area			
7b	Method of grade-wise	Mechanical	Mechanical	NIL
	mineral sorting i.e. manual or			
	mechanical			
7c	Different grade of mineral	Chemical Grade – 0 +50	Chemical Grade – 0	NIL
	sorted out at mines	mm to $-100$ MM) Cement	+50  mm to - 100MM	
		Grade – 0-50mm fines	Cement Grade – 0 -	
			50mm fines	
7d	Any beneficiation process at	Not Proposed	Not Applicable	NIL
	mines			
7e	General remarks of	Mine not in operations		
	inspecting officer on Mineral			
	conservation & beneficiation	mine temporarily discontinued from 16.12.2009		
	issues			

#### 8.0 Environment

SN	Item	Proposals (2017- 18)	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	Na	Concurrent use for plantation	NIL
8b	Concurrent use or storage of topsoil	Not Proposed	Not Applicable	NIL
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Not Proposed	Not Applicable	NIL
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not Proposed	Not Applicable	NIL
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Not Proposed	Not Applicable	NIL
8f	Baseline information on existence of plantation & additional plantation done (Rule 41)	Not Proposed	Not Applicable	NIL
8g	Survival rate	Not Proposed	Not Applicable	NIL
8h	Water sprinkling on roads to control airborne dust	Not Proposed	Not Applicable	NIL

8i	General remarks of inspecting	Mine not in operations since 17.12.2009 due IBM notice for
	officer on aesthetic beauty in and	suspension of all mining operation vide letter dtd 10.12.2009.
	around mines are	Hence, mine temporarily discontinued from 16.12.2009

9.0 Compliance of Rule 45

S.	Item	COMMENTS	Remarks
N.			
	Status of submission of Online Monthly	M.R. Submitted up to till date -	NIL
	and Annual returns	10.10.2017	
		A.R. submitted up to till date- 30.6.2017	

S. N.	Item	Details GIVEN in A.R.(2016-17)	Observation of I/Officer /Actual reported in Returns	Remarks
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	NA	NA	NIL
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Pit- 36.09 Waste/reject Others- 6.81	Pit- 36.09 Waste/reject Others- 6.81	NIL
9d	Scrutiny of Annual return on afforestation	NA	NA	NIL
9e	Scrutiny of Annual return on mineral reject generation (Grade & quantity)	NA	NA	NIL
9f	Scrutiny of Annual return on ROM stock and/or graded ore	NA	NA	NIL
9g	Scrutiny of Annual return on sale value, Ex. Mine price & production cost	NA	NA	NIL
9i	Scrutiny of Annual return on fixed assets	NA	NA	NIL
9k	Scrutiny of Annual return on mining machineries	NA	NA	NIL

10- Details of violations observed during current inspection and compliance position of earlier violation pointed out: -The last inspection of mine was carried out on dtd 06.09.2011 and violations of rules 23(E), 45 were observed and these violation rectified by the lessee vide letter No- RQG/368/2011 Date-22.09.2011. This inspection was carried out in connection with Review of Mining Plan. During the inspection no violation were pointed Mine not in operations since 17.12.2009 due IBM notice for suspension of all mining operation vide letter dtd 10.12.2009. Hence, mine temporarily discontinued from 16.12.2009

\*\*\*\*