



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखण्ड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail – [ro.dehradun@ibm.gov.in](mailto:ro.dehradun@ibm.gov.in)

फाईल संख्या File No: HP/SRM/LST-1 Mine Code: 38HPR10044

दिनांक, 26 December 2019

सेवा में मै0 जाकरा माइन्स एंड मिनरल्स,  
To : द्वारा श्री जे0एस0फौजी,  
ग्राम ब पो0 – सतौन,  
तह 0 – पावंटा साहिब,  
जिला – सिरमौर (हि0प्र0)।

E- mail: [jalamsingh@rediffmail.com](mailto:jalamsingh@rediffmail.com)

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Barwas Limestone Mine over an area of 8.91 ha located near Village-Barwas, in Sirmour district of HP State.

महोदय  
Sir,


The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 17.11.2019.

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	Mining operation were not carried out in accordance with the approved modified mining plan vide letter no 614(2)/MP-B-19/11- DDN dated 15.03.2019 to the following extent: (i) As per proposal during the year 2018-19, it was proposed to carry out 02 DTH holes 20 mtrs depth each, but during the inspection it was observed no such DTH drilling carried out during the year 2018-19. (ii) As per proposal during the year 2018-19, it was proposed to carry out mining operation from 1458 to 1422 MRL. During the inspection it was observed that benches have not been developed from 1446 mrl downwards so far. The height of benches has also been observed up to 10 mtrs whereas as per approved modified mining plan it should be six meter
26(2)	The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1 <sup>st</sup> day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof: On perusal of office records it is observed that yearly report for the year 2018-19 has not been submitted to the competent authority by the holder of the lease in the prescribed in this office till date.
33	The holder of a mining lease shall, on or before the 30 <sup>th</sup> day of June every year submit to the authorized officer a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32. However, the lessee has not submitted the copies of the plans and sections as per rules.

2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

3. Mining operations can be suspended as per rule 11(2) in case of non compliance and it constitutes non compliance of Rule 11(1) of MCDR, 2017.
4. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from the date of issue of this letter.

भवदीय Yours faithfully,

  
26-12-19

(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक / Assistant Controller of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

सहायक खान नियंत्रक / Assistant Controller of Mines  
भारतीय खान ब्यूरो / Indian Bureau of Mines