



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखण्ड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in

SHOW CAUSE NOTICE
E-MAIL / REGD A.D.



फाईल संख्या File No: HP/SRM/LST-1 Mine Code: 38HPR10044

दिनांक, March 2020

सेवा में To : मैसर्स जाकरा माइन्स एण्ड मिनरल्स

E- mail: jalamsingh@rediffmail.com

द्वारा श्री जे0 एस0 फौजी

गांव एवं पोस्ट- सतौन, तहसील-पांवटा साहिब

जिला सिरमौर, हि.प्र.

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Barwas Limestone Mine over an area of 8.91 ha located near Village-Barwas, in Sirmour district of HP State.

संदर्भ/Ref.

Violation letter No: HP/SRM/LST-1 dated 26.12.2019 & Your letter no. :JMM/BARWAS/IBM-VIOLATION/2019 dated 01.02.2019 received on dated 04.02.2020


महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 17.11.2019, in the presence of Shri Tapender Singh, Agent, Mines and violation letter dated 27.12.2019 was issued for below mentioned Violations Rules of MCDR, 2017:

| <u>RULE NO.</u> | <u>NATURE OF VIOLATION OBSERVED</u> |
|-----------------|--|
| 11(1) | Mining operation were not carried out in accordance with the approved modified mining plan vide letter no 614(2)/MP-B-19/11- DDN dated 15.03.2019 to the following extent: (i) As per proposal during the year 2018-19, it was proposed to carry out 02 DTH holes 20 mtrs depth each, but during the inspection it was observed no such DTH drilling carried out during the year 2018-19. (ii) As per proposal during the year 2018-19, it was proposed to carry out mining operation from 1458 to 1422 MRL. During the inspection it was observed that benches have not been developed from 1446 mrl downwards so far. The height of benches has also been observed up to 10 mtrs whereas as per approved modified mining plan it should be six meter |
| 26(2) | The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1 st day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof : On perusal of office records it is observed that yearly report for the year 2018-19 has not been submitted to the competent authority by the holder of the lease in the prescribed in this office till date. |
| 33 | The holder of a mining lease shall, on or before the 30 th day of June every year submit to the authorized officer a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32. However, the lessee has not submitted the copies of the plans and sections as per rules. |

2. In above reference your letter No.JMM/BARWAS/IBM-VIOLATIONS/2019 dated 04-02-2020, has been examined and compliance of violation of Rule 26(2) and 33 has been observed, Whereas the reply in respect of Violated Rule 11(1) is not found satisfactory, Hence the violation of Rule 11(1) of MCDR, 2017 still persists.
3. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
4. Mining operations can be suspended as per rule 11(2) in case of non compliance and it constitutes non compliance of Rule 11(1) of MCDR, 2017.
5. You are therefore directed to show cause within a period of thirty (30) days from the date of issue of this letter, as to why you should not be prosecuted for the above offences and / or why mining operation can be suspended under statutory provisions.
6. Please note that no further notice will be given to you in this regard.

भवदीय Yours faithfully,


11.03.2020

(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक / Assistant Controller of Mines

प्रतिलिपि सूचनार्थं प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

सहायक खान नियंत्रक / Assistant Controller of Mines
भारतीय खान ब्यूरो / Indian Bureau of Mines