



Hkkjr ljdkj/Government of India
[kku ea=ky;/Ministry of Mines
Hkkjr; [kku C;wjks/Indian Bureau of Mines
□□□□□□□□ {ks=h; dk;kZy;/Hyderabad Regional Office



No. AP/GNR/LST-40/HYD

Room No.603,CGO Towers,6th Floor,
Kavadiguda, Secunderabad-500080.
6/12/2019

To
Nominated owner/Agent,
Parasakti Limestone Mine,
M/s Parasakti Cements Industries Limited,
Jettipalem Village,
Rentachintala Mandal,Guntur Dist.A.P.

Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of Parasakti Limestone mine over an extent 317.782 ha. situated in Jettipalem village, Rentachintala Mandal, Guntur district, A.P state.

Sir,

The following provisions of Mineral Conservation and Development Rules 2017 (MCDR, 2017), were found violated in your above mine during the inspection on 21.11.2019 by the undersigned in the presence of Shri. G.Chandrasekhar, Dy.G.M (Mines).

| Rule No- | Nature of violation |
|----------|--|
| 11 (1) | No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section(2) of section 5. A garland drain was proposed along the boundary of pit but during inspection it was not found to be constructed. |
| 19 | Where heavy earth moving machinery is used in mines, the holder of a mining lease shall maintain log books duly authenticated by the manager or mining engineer of such mines in respect of each machine showing date-wise account of hours worked, hours not worked, reasons for non-working, consumption of fuel or energy and lubricants and output of the machine during the corresponding working hours. The log books were not maintained as per the contents mentioned in the rule No.19 (1). |
| 45(7) | If it is found that the holder of a mining lease or the person or company engaged in trading or storage or end-use or export of minerals, as the case may be, has submitted incomplete or wrong or false information in daily or monthly or annual returns or fails to submit a return within the date specified. In the annual returns(2018-2019), the depreciation cost found to be Rs.14/Ton as per submission of lessee in Part VII, whereas in accordance with Part II A, it is found to be different. |

| | |
|-------|---|
| 55(1) | <p>For the purpose of carrying out reconnaissance, prospecting or mining operations in accordance with these rules – in case of fully mechanised category ‘A’ mines, the Mining Engineer shall have minimum five years of professional experience of working in a supervisory capacity in the field of mining.</p> <p>However it was noticed that Mining Engineer was not having experience of 5 years as per the rule 55 (1) of MCDR 2017.</p> |
|-------|---|

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule- 62 of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty five) days from the date of issue of this letter.

Yours faithfully,

(Madhu Sudhan Yadav.M)
Assistant Controller of Mines

Copy for information & further necessary action to

1. The Director of Geology and Mining, Govt. of Andhra Pradesh, Ibrahimpatnam, Krishna District, Vijayawada, A.P State.
2. The Assistant Director of Geology & Mining, Dachepalli, Guntur district A.P. State.

(Madhu Sudhan Yadav. M)
Assistant Controller of Mines

□□□ □□□□□ □□ □□□□:

1 □□□ □□□□□□□□ □□□□□ (□), □□□□□□ □□□ □□□□□□□, □□□□□□□□.

(□□□□ □□□□
□□□□. □□)
□□□□□

□□□ □□□□□□□□□