

Registered/Speed Post

Violation letter



**GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF REGIONAL CONTROLLER OF MINES**

**FAX : 080- 23371027 / 23373287
Tel : 080-23371027 / 23375366 /
67
Email ID: ro.bangalore@ibm.gov.in
rcombng@rediffmail.com**

No.KNT/BLR/FE/52/BNG/ Vol VI



**29, Industrial Suburb, II Stage,
Tumkur Road, Gorguntapalya,
Yeshwantpur,
Bangalore- 560 022.**

Date: 06.12.2018

To,

M/s P.Balasubba shetty & Son,
Post Box No. 3, Hampi Road,
Taluka:Hospet
Dist: Bellary -583201

Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Karadikolla (Suresh) Iron Ore Mine (ML No. 2502) over an area of 42.10 Ha located in Karadikolla village, Sandur taluk, Ballari Dist., Karnataka State

Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Shri. Y.V.RamaKrishna Reddy, Manager Mining and Shri. J.Vijay Narasihulu, Mining Engineer on 14.11.2018.

Rule	Nature of violations observed
11(1)	As per the approved document vide letter No.279/125/89/BNG dt 13.07.2018, construction of retaining wall of 990 mts was proposed at the toe of the waste dump to arrest wash offs. It was observed that retaining wall of about was not constructed along with garland drain as per the plan.

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully,

Sd/-

(Arun Kumar)
Deputy Controller of Mines

Copy forwarded to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-

(Arun Kumar)
Deputy Controller of Mines