

## **GOVERNMENT OF INDIA** MINISTRY OF MINES **INDIAN BUREAU OF MINES** OFFICE OF REGIONAL CONTROLLER OF MINES



29, Industrial Suburb, II Stage, `Tumkur Road, Gorguntapalya,

Yeshwantpur, Bangalore- 560 022.

Date: 05.06.2015

NO: KNT/CTD/Mn-112/BNG To: Sri Basanth Poddar, Managing Director, M/s Mineral Enterprizes Limited, # 49, Race Course Road, 3<sup>rd</sup> Floor, West Wing, Khanija Bhavan, BENGALURU- 560 001.

Tel: 080-23371027 / 23375366 / 67

rcombng@rediffmail.com

Email ID: ro.bangalore@ibm.gov.in

Sub: Violation of provisions of MCDR 1988 in respect of your Hullikatte Manganese Limestone mine, ML 1992 (24.65Ha) in Hullikatte village, Davangere taluk and District, Karnataka state.

Sir,

The following provision of the Mineral Conservation and Development Rules 1988 was found violated in your above mine during the inspection on 30.05.2015 by Sri K. Srinivas. Asstt. Mining Geologist, accompanied by Sri Vinod Kumar, Mine Manager.

Rule No.	Violations observed
24(1)	As per the rule, a lease holder of every mine shall send to the Controller General, Controller
	of Mines and the Regional Controller of Mines notice in Form D -1 when the work in a mine
	is discontinued for a period exceeding ninety days so as to reach them within one hundred
	five days from the date of such temporary discontinuance. The mine is not in operation since
	1 <sup>st</sup> July, 2011, but no such notice has yet been submitted.

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR 1988.

d intimate the position to this office within 45 (forty five) days from the date of issue of this	03. and in letter.
Yours faithfully,	
Sd/-	
( Pukhraj Nenival ) Dy.Controller of Mines	

2. The Director, Department of Mining & Geology, No. 49, Kanijabhavan, R.C. Road,

Sd/-

( Pukhraj Nenival ) Dy.Controller of Mines

Copy for information to:

Bangalore – 560 001.

1. The Controller of Mines(SZ), IBM, Bangalore