

मेल/त्वरितडाकद्वारा



भारतसरकार /GOVERNMENT OF INDIA  
खानमंत्रालय/ MINISTRY OF MINES  
भारतीयखानब्यूरो /INDIAN BUREAU OF MINES  
क्षेत्रीयखाननियंत्रककार्यालय/ OFFICE OF THE REGIONAL  
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287  
दूरभाष: 080-23371027 / 23375366/67  
Email ID: ro. bangalore@ibm.gov.in.

29, इंडस्ट्रियलसबर्बIIस्टेज,,तुमकुरोड,  
गोरगुंटापाल्यायेशवंतपुर,  
बेंगलुरु -560022

सं.KNT/MYS/Ky-1/BNG

दिनांक:12.06.2020

सेवामें

Shri. Shivayogi.S.S,  
General Power Attorney,  
No.228, 'Neralu', First Floor, 8th Cross, 1st Main, 2nd Stage,  
Srirampura, Mysuru,  
District: Mysuru.  
State: Karnataka. Pin Code: 570034

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your of Karigala Kyanite Mine (ML No. 2286) over an area of 12.14 Ha located in Karigala village, HD Kote Taluka, Mysore district of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Shri., C P Prasanna Kumar-Qualified person & your good self on 06.02.2020.

Rule	Nature of violations observed
11(1)	<p>Scheme of Mining was approved vide letter no.279/635/99/BNG dated 11.06.2015 for a period of 2016-16 to 2019-2020. The deviation observed in mining operation vis-a-vis approved document are given below:</p> <p>i)Production &amp; development was proposed in Pit No.5 in between grid lines E658350- E658400, N1345150- N1345500,where as actual production was carried out in Pit No.1 &amp; 2, in between grid lines E658000N1345250 &amp; E657952N1345268 and E657946N1345367 &amp; E657973N1345346</p> <p>ii)Achieved the stripping ratio of 1:1.50 against the proposal of 1:2.12</p> <p>iii) working was proposed in one pit namely no.5,whereas actual working was going on in two pits, Pit no.1 &amp; pit No.2</p> <p>iv) Environmental monitoring of air water &amp; noise was not carried out.</p>

26(2)	Yearly report on PMCP setting forth the extent of protective and rehabilitative works carried out as per the approved Progressive Mine Closure Plan has not been submitted.
45 (5)(c)	The holder of a mining lease shall submit online returns in respect of each mine to the Regional Controller or any other authorised official of the Indian Bureau of Mines an annual return which shall be submitted before the 1st day of July each year for the preceding financial year in electronic form, along with a signed print copy of the same if it is not digitally signed.  Annual returns have not been sent to this office for the year 2018-19.

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(अरुणकुमार)  
उपखाननियंत्रक  
भारतीयखानब्यूरो

प्रतिलिपिसूचनार्थ'/Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-

उपखाननियंत्रक  
भारतीयखानब्यूरो