

**VIOLATION LETTER****REGD/ A D**

भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक का कार्यालय



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of the Regional Controller of Mines.  
Ph-(0674)2742463 / Fax-0674 2744430

File No. ORI/CR/JJP/MCDR-7/BBS/Vol-III/	Plot No: 149, Pokhariput In front of CPWD Office Bhubaneswar-751020
---	---

**To,**

Date : 27.06.2017

Shri Rajesh Patel, Chief (Mining) & Agent  
Sukinda Chromite Mines.  
M/s Tata Steel Ltd.,  
At & PO: Kalarangitta, District: Jajpur  
Odisha - 755028

**Sub: Violation of provisions of MCDR, 2017 in respect of your Sukinda Chromite Mine over an area of 406 Ha in Jajpur district of Odisha State.**

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 23.05.2017 by the undersigned and Shri Dilip Jain, JMG, accompanied by S/Shri Sabyasachy Mishra, Mine Manager, and Pinaki Mallick, Geologist of your mine.

Rule No.	Proposed in the approved Mining plan	Violation
11 (1)	As per the approved scheme of Mining dated 19.07.2016, bench width of 12 – 14 m is to be maintained in OB X quarry.	During inspection bench width of less than 12 -14 m was observed that in OB X Quarry bottom benches between gridlines of 3000E-3250E and 2200E-2600E.

**02.** It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR, 2017.

*Besides, inability to comply with the provision of Rule 11 (1) is liable for suspension of mining operations according to the provisions of Rule 11 (2) of MCDR, 2017.*

**03.** You are advised to rectify the above violations immediately and intimate the position to this office within **45 (forty-five) days** from the date of issue of this letter.

Yours faithfully,

*A. B. Singh*  
27/6/17  
(Ramkishan R)

Senior Assistant Controller of Mines  
Indian Bureau of Mines