Speed post with A/D

Violation Letter



GOVERNMENT OF INDIA MINISTRY OF MINES INDIAN BUREAU OF MINES OFFICE OF REGIONAL CONTROLLER OF MINES

AJA

REGISTRARS
RICE SAFET MERCON

ISO 9001:2008

0059

29, Industrial Suburb, II Stage, Tumkur Road, Gorguntapalya, Yeshwantpur, Bangalore- 560 022.

Dated: 1/05/2018

FAX: 080-23371027 / 23373287
Tel: 080-23371027 / 23375366 / 67
Email ID: ro.bangalore@ibm.gov.in

No: KNT/BLR/Fe/384/BNG

Shri Syed Ahmed

Managing Partner

M/s Zeenath Transport Company, #24 Zeenath house, Cowl Bazaar,

Bellary-583 102

Karnataka

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Dharmapur Iron ore Mine (ML.NO. 2239) over an extent of 43.58 Ha Area in Bellary-Dist of Karnataka State

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 was found violated during FMCP inspection of your above mine on 12/04/2018 by the undersigned in presence of S/Shri G. Harendra, QP, J. Srikhant, Mines Manager, Saleem Syed, Mining Engineer and other mine officials.

Rule No.	Nature of violation observed							
37 (2)	The proposed constructions of 17m retaining wall, 68m garland drain and 10 nos of gully plugs for year 2017-18, have not been completed to prevent escape of any materials from dumps.							

02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

03.	You	are	advised	to	rectify	the	above	violation	immediately	and	intimate	the	
position to this office within 45 (forty five) days from the date of issue of this letter.													

Yours faithfully,

 $\begin{array}{c} -sd/-\\ \text{(Prashant S. Hegde)} \\ \text{Senior Mining Geologist} \end{array}$

Copy forwarded for kind information:--

- 1) The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560 001
- 2) The COM(SZ), IBM, Bangalore.

-sd/-(Prashant S. Hegde) Senior Mining Geologist