#### **INSPECTION REPORT**

## 1<u>.0 **GENERAL**</u>

SN	Particulars	Details
1	Name of the Mine	Dhamanva Gabha Limestone Mine
2	Total Lease Area (Ha) with breakup of Non-forest and forest land	Total Lease Area: 60.7120 ha., Non-Forest land: 60.7120 ha., Forest Land: 00 ha.
3	Mine code	38GUJ08162 / 38GUJ08042, Dhamnava & Gabha mining leases were amalgamated as one single lease in the year 2007.
4	IBM Registration Number under rule 45 of MCDR, 1988	IBM/5292/2011
5	Name of the lessee, Address, phone, email and fax number	M/s. GHCI LIMITED, At & Post: - Sutrapada, Dist.:- Gir-Somnath-362265, Gujarat. Phone:- 02876305564/305377, E-Mail:- mining@ghcl.co.in, rchopra@ghcl.co.in, Fax:- 02876263480
6	Village	Dhamanva and Gabha
7	Taluka/Mandal	Talala
8	District	Gir-Somnath
9	Pincode	362150
10	State	Gujarat
11	Post office	Dhamanva
12	Nearest police station	Talala Police station
13	Nearest Railway station	Veraval Railway station
14	Date of Grant of Mining Lease	27/10/1986
15	Date of Execution	09/02/1987, 22/06/1987.
16	Date of opening of Mine	01/01/1988
17	Date of first Renewal, if app.	30/01/2006, 15/05/2006
18	Date of second Renewal, if applicable and its period & expiry	No renewal
19	Date of submission of renewal application if Mining Operations are continuing under deemed extension	30/01/2006, 15/05/2006
20	Name of the Nominated Owner with Address, phone, email, fax number and date of appointment	Mr. Raman Chopra, M/s GHCL Ltd,Corporate Office: B-38, institutional area, sector-1, Noida – 201301, (U.P.) Date of appointment-05.05.2012
21	Name of the Mine Agent with Address, phone, email, fax number and date of appointment	Mr. Manish Kumar, M/s GHCL Ltd, At & Post – Sutrapada, Dist.:- Gir-Somnath Pin- 362275 (Gujarat), Ph. No. 9328849666, Date of Appointment:-01/02/2014
22	Name of the Mines Manager	Mr. Rajesh Tiwari
	with Address, phone, email, fax	M/s GHCL Ltd, At & Post – Sutrapada, Dist.:- Gir-

	number and date of appointment in mines	Somnath Pin- 362275 (Gujarat), Ph. No. 9099093080 Date of appointment:- 22/01/2013
23	Name of the Mining Engineer, Qualification and total experience with Address, phone, email, fax number and date of appointment in mine	Mr. Rajesh Tiwari- M/s GHCL Ltd, At & Post – Sutrapada, Dist.:- Gir-Somnath Pin- 362275 (Gujarat), Ph. No. 9099093080, Qualification :- B.E. mining, Total Experience :- 13 Years Email :- rajeshtiwari@ghcl.co.in, Date of appointment:- 22/01/2013
24	Whether Geologist and Mining Engineer appointed in mines satisfy the rule 42 & carrying out their duties as per rule 43 & 44.	Geologist: - R.K.Pathak M/s GHCL Ltd, At & Post – Sutrapada, Dist.: - Gir-Somnath Pin- 362275 (Gujarat), Ph. No. 9099093080, Qualification: - B.E. mining, Total Experience: - 13 Years Email: - rajeshtiwari@ghcl.co.in,
25	Date of Approval of Mining Plan/Modified Mining Plan with five- year period and specific condition in approval letter, if any.	Date of Approval of mining Plan:- 18/04/2017, Period of Mining Plan:- 2017-18 to 2020-21
26	Date of Approval of Scheme of Mining/Modified Scheme of Mining with five-year period and specific condition in approval letter, if any.	Date of Approval of mining Scheme:- 20/02/2013 Period of Mining Scheme:- 2013-14 to 2016-17
27	Mineral(s) granted in lease and proved for mining	Limestone
28	Method of Mining(Opencast, Underground)	Opencast
29	Category (Fully Mechanised, Others or Manual)	В
30	Captive/Non Captive	CAPTIVE

# Scientific Mining: Compliance of proposals of approved mining plan/scheme of mining. – **Exploration**

SN	Item	Proposals (2016-17)	Actual work	Remarks
1a	Backlog of previous year	Not proposed	NIL	The mine
1b	Exploration over lease area for Geological axis 1 or 2.	Not proposed	NIL	lease area is
1c	Exploration Agency & Expenditure in lakh Rupees during the year	Not appl	icable	Fully explored.
1d	Balance area to be explored to bring Geological axis in 1 or 2	No proposal		
1e	Balance reserves as on 01.04.2017	1630900	1630900 T	
1f	General remarks of inspecting officer on geology, exploration etc.		NIL	

## 2.0 Development

SN	Item	Proposals(2016-17)	Actual work	Remarks
2a	Location of development w.r.t. lease area	9 benches at 63 t0 60 mRL in Pit no. DP-1,DP-3, DP-4, DP-6, GP-8, GP-7, GP-3,GP-1.	9 benches at 63 t0 60 mRL in Pit no. DP-1,DP-3, DP-4, DP-6, GP-8, GP-7, GP-3,GP-1.	
2b	Separate benches in topsoil, overburden and mineral (Rule 15)	No separate benches,	Area is devoid of OB	-
2c	Stripping ratio or ore to OB ratio	NO Proposal	Area is devoid of OB	
2d	Quantity of topsoil generation in m3	NO Proposal	NIL	-
2e	Quantity of overburden generation in m3	NO Proposal	NIL	-
2f	General remarks of inspecting officer on development of pit w.r.t. type of deposit etc.	NIL		

# 3.0 Exploitation

SN	Item	Proposals (2016-17)	Actual work	Remarks
3a	Number of pits proposed for production	8	8	-
3b	Quantity of ROM mineral production proposed	111358 MT	108950 MT	-
3c	Recovery of salable/usable mineral from ROM production	100000 MT	99144.160 MT	
3d	Quantity of mineral reject generation	Not Proposed	NIL	
3e	Grade of mineral reject generation and threshold value declared	Undersize Limestone	Undersize Limestone is spreading on L/s	
3f	Quantity of sub-grade mineral generation	11358MT	9806MT	
3g	Grade of sub-grade mineral generation	NP	NIL	
3h	Manual / Mechanised method adopted for segregating from ROM	Manual	As proposed.	-
3i	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	Not Proposed	NIL	
3j	Provision of drilling & blasting in mineral benches	Drilling and Blasting by Jack Hammer of 32mm dia.	Not required.	
3k	Provision of mining machineries in mineral benches	B-manual	As proposed.	

31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Yes	Yes	
3m	Total area covered under excavation/pits	30.9183 Ha	30.9183 Ha	-
3n	Ore to OB ratio for the pit/mine during the year	Not Proposed	NIL	-
30	Total area put in use under different heads at the end of year	Mining-30.9183 ha., Roads- 2.7347, Others- 3.3446	Mining-30.9183 Ha.,Roads- 2.7347 Others- 3.3446	
3p	Production of ROM mineral during last five-year period, as applicable	Yr- 2013-14 :- 111970 Yr- 2014-15 :- 111883 Yr- 2015-16 :- 111817 Yr- 2016-17 :- 111358	Yr- 2013-14 :-90400T Yr- 2014-15:- 82275T Yr- 2015-16:-110850T Yr- 2016-17 :- 108000	
3q	General remarks of inspecting officer on method of mining etc.			

## **4.0 Solid Waste Management-Dumping**

SN	Item	Proposals (2016-17)	Actual work	Remarks
4a	Separate dumping of topsoil, OB & mineral reject (Rule 32, 33)			-
4b	Location of topsoil, OB & mineral reject dumps			-
4c	Number of dumps within lease area and outside lease area	Not proposed	NIL	-
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)			-
4e	Number of active & alive dumps			-
4f	Number of dead dumps			-
4g	Number of dumps stabilished			-
4h	Whether Retaining wall or garland drain all along dumps are there			-
4i	Length of Retaining wall or garland drain all along dump			-
4j	Number of settling ponds			-
4k	Specific comments of inspecting officer			

# 5.0 Solid Waste Management-Backfilling

SN Item	Proposals (2016-1	17) Actual work	Remarks
---------	-------------------	-----------------	---------

5a	Status on part or full extraction of mineral from mined out area before starting backfilling	Fully mined out	Fully mined out	
5b	Area under backfilling of mined out area	1.5083 Ha	1.5083 Ha	
5c	Concurrent use of topsoil for restoration or rehabilitation of mined out area (Rule 32)	Not Proposed	NIL	
5d	Total area fully reclaimed & rehabilitated	Not Proposed	1.5083	-
5e	General remarks of inspecting officer on backfilling, reclamation etc			

## **6.0 Progressive Mine Closure Plan**

SN	Item	Proposals (2016-17)	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly - Rule 23E(2).	Wire fence+post plantation care.	Annual return for the PMCP is submitted with in stipulated time.	
6b	Management of worked/mined out benches i) Area available for rehabilitation (ha) ii) Afforestation done (ha) iii) No. of saplings planted during the year iv) Cumulative no. of plants v) Any other specific method of rehabilitation vi) Cost incurred on watch & care during the year	NP 2.90 Ha 250 saplings Not Proposed Not Proposed	NIL 2.90 Ha 250 Saplings NIL	
6c	Compliance on reclamation and rehabilitation by backfilling i) Voids available for backfilling (L X B X D) ii) Void filled by waste/tailings iii) Afforestation on the backfilled area iv) Rehabilitation by making water reservoir v) Any other specific means	Not Proposed	NIL	
6d	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Methof of rehabilitation	Not Proposed	NIL	

6e	Compliance of Environmental monitoring (core zone & buffer zone)	Yes, Comet consultancy, Rajkot	Yes	
6f	General remarks of inspecting officer on PMCP compliance & progressive			

# 7.0 Mineral Conservation

SN	Item	Proposals (2016-17)	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	-	Size & grade as per plant requirement.	
7b	Method of grade-wise mineral sorting i.e. manual or mechanical	B-category	B-category	
7c	Different grade of mineral sorted out at mines	Not Proposed	Chemical Grade and Cement Grade	
7d	Any beneficiation process at mines	Not Proposed	NIL	
7e	General remarks of inspecting officer on Mineral conservation & beneficiation issues	NIL		

## 8.0 Environment

SN	Item	Proposals (2016-17)	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	Not Proposed	NIL	
8b	Concurrent use or storage of topsoil	Not Proposed	NIL	
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Not Proposed	NIL	-
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not Proposed	NIL	-
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Not Proposed	NIL	-
8f	Baseline information on existence of plantation & additional plantation done (Rule 41)	EXISTENCE OF PLANTS: 423 Additional:250 per year	Existence:423 Planted: 250	
8g	Survival rate		42.3	
8h	Water sprinkling on roads to control airborne dust	Water sprinkling	Water sprinkling by tankers.	

8i	General remarks of	NIL
	inspecting officer on	
	aesthetic beauty in and	
	around mines are	

#### 9.0 Compliance of Rule 45

S.N.	Item	COMMENTS		Remarks
	Status of submission of Online Monthly and Annual returns	M.R. Submitted up to till date –June-2017 A.R. submitted up to till date-2016-17.		The lessee/party has
S. N.	Item	Details GIVEN in A.R.( 2016-17)	Observation of I/Officer /Actual reported in Returns	been submitted
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Mining Engineer & Geologist have been appointed as per provision of rules as per category of mines.		the online annual return on IBM
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Area under abanded & current O/c working-7.9&21.9Ha,Reclaimed-9.76Ha, waste-0.25Ha,Infra-2.93Ha		website for the year 2016- 17 on
9d	Scrutiny of Annual return on afforestation	400Nos Plantation 71.25% Survival		29.6.17.
9e	Scrutiny of Annual return on mineral reject generation (Grade & quantity)	The OB/MR shown NIL	Advised to put in closing stock, which ever generated instead of backfill.	
9f	Scrutiny of Annual return on ROM stock and/or graded ore	L/S-O/s-0, Production & Dispatch-99144.16T, C/stock-0,		
9g	Scrutiny of Annual return on sale value, Ex. Mine price & production cost	Ex Mine Price/Cost of production-487.41Rs/T, Captive use		
9i	Scrutiny of Annual return on fixed assets	The fixed assets given.		
9k	Scrutiny of Annual return on mining machineries	As proposed, given in returns.		

The instant mine are amalgamation of two leases & presently lessee is using two mine code for submission of periodical returns, therefore advised to submit in single valid mine code in further submission & accordingly informed to IBM/CGM.

<sup>10-</sup> Details of violations observed during current inspection and compliance position of earlier violation pointed out:- The RMP was approved on 18.4.2017 for the period of 2017-18 to 2020-21. Presently no significant violation observed.