INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

MCDR INSPECTION REPORT

Hyderabad regional office

Mine file No : AP/CDP/FE-10/HYD Mine code: 30APR04006

(i)Name of the Inspecting : AP03) A.Prabhakar Rao

Officer and ID No.

(ii) Designation : Assistant Mining Geologis

(iii) Accompaning mine : Santosh kumar Geologist representative of lessee

Official with

Designation

(iv) Date of Inspection : 17/02/2017 Prev.inspection date : 09/04/2008 (v)

PART-I : GENERAL INFORMATION

(a) Mine Name : ANJANI IRON ORE MINE

(b) Registration NO. : IBM/5627/2011

(C) Category : A Manual (d) Type of Working Opencast

(e) Postal address

> State : ANDHRA PRADESH

District CUDDAPAH

Village Taluka Post office Pin Code : FAX No.

E-mail : srianjaniminesandminerals@g 08562-233489,CELLNO=944125 Phone

(f) Police Station : PENDLIMARRI First opening date : 01/04/2005 (g)

Weekly day of rest (h) : SUN

Address for : M/s ANJANI MINES & MINERALS correspondance YELLATUR (V&PO), D.NO: 2/56

PENDLIMARRI(M) KADAPA DT.

3. (a) Lease Number : APR2478 (b) Lease area : 208.3 Period of lease : 20 (C)

> (d) Date of Expiry : 26/11/2024

Mineral worked 4. : IRON ORE Main

> Associated LATERITE

5. Name and Address of the

Lessee : M/S ANJANI MINES & MINERALS

YELLATUR (V&PO)

PENDLIMARRI(M) KADAPA DT. CUDDAPAH ANDHRA PRADESH

Phone: FAX:

Owner : G.NARASIMHAREDDY.M.P,SRI ANJANIMINES&MINERALS

D.NO.2/56, VELLATUR(V) PENDLI

MARRI(M) KADAPA.DIST ,ANDHRAPRADESH CUDDAPAH

ANDHRA PRADESH

Phone: (08562)233489,C

FAX : -

Agent : M.NAGAMALLARTEDDY

M/S.ANJANI MINES &MINERALS D.NO.2/56, VELLTUR(PO)&(V) PENDLIMARRI(M) CUDDAPAH

ANDHRA PRADESH

Phone: FAX:

Manager

Name : JANARDANAMBHAVANASI

Qualification : B.Tec.MINING Appointment/ : 20/01/2014

Termination date

6. Date of approval of Mining : Modif.of approved Mining Plan 05/01/2007 Plan/Scheme of Mining Mining Scheme rule 12 MCDR1988 23/08/2010

PAGE : 3

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	As on date of inspection no valid document for this mine	91 DTH Bore holes minimum 19.0 meters to maximum 30.0 meters depth were drilled	Mining plan approved vide letter no .AP/CDP/Lat&Fe- 220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013- 2014.The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working
1b	Exploration over lease area for geological axis or 2	As on date of inspection no valid document for this mine	Geological AIS 1	Mining plan approved vide letter no .AP/CDP/Lat&Fe- 220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013- 2014.The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

1c Exploration
Agencies and
Expenditure in
lakh rupees
during the year

As on date of inspection no valid document for this mine

Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

1d Balance area to
 be explored to
 bring Geological
 axis in 1 or 2

As on date of inspection no valid document for this mine

Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working 30.00 Hectars

1f General remarks
 of inspecting
 officers on
 geology,
 exploration etc

As on date of inspection no valid document for this mine

Mining opertions in the mine suspended under approved approved of 13(2) MCDR 1988 on letter no 26.11.2014 .As on date of inspection no valid document for this mine 23.08.2010, the mine was not the period working 2009-2010

Mining plan approved vide .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not workin

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease a	inspection no	Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working	Mining plan approved vide letter no .AP/CDP/Lat&Fe- 220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013- 2014.The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

2b in topsoil, overburden and minerals (Rule 15)

valid document for this mine

Separate benches As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan

2c Stripping ratio or ore to OB ratio

valid document for this mine

As on date of Mining operations in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Quantity of 2d topsoil generation in m3 valid

document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

2e Quantity of overburden generation in m3 valid

document for this mine

As on date of Mining operations in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

2f General remarks of inspecting officers on development of pit w.r.t. type of deposit etc

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production		Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working	Mining plan approved vide letter no .AP/CDP/Lat&Fe- 220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013- 2014.The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Quantity of ROM mineral production proposed

valid document for this mine

As on date of Mining operations in the inspection no mine suspended under Rule 13(2) MCDR 1988 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

3c Recovery of sailable/usable mineral from ROM valid production

document for date of valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date this mineAs on of inspection no valid document for this mine inspection no ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

3d Ouantity of mineral reject generation

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

3e rejects generation and threshold value declared.

valid document for this mine

Grade of mineral As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Ouantity of sub grade mineral generation.

valid document for this mine

As on date of Mining operations in the inspection no mine suspended under Rule 13(2) MCDR 1988 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Grade of sub 3q grade mineral generation

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

3h Manual / Mechanised method adopted for segregating from ROM

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

3i Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

3 ј Provision of drilling and blasting in mineral benches

3k

mining

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Provision of machineries in mineral benches

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Whether height of benches in overburden and mineral suitable document for for method of mining proposed in MP/SOM

valid this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Total area 3m covered under excavation/pits

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

during the year. valid

document for this mine

Ore to OB ratio As on date of Mining opertions in the for the pit/mine inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Total area put 30 in use under different heads at the end of year

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Production of 3p ROM mineral during the last five year period document for as applicable

valid this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

General remarks 3q of inspecting officers on method of mining document for etc.

valid this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Solid Waste Management - Dumping:

Sl.No. Item Propasals Actual work Remarks

Mining plan

approved vide

4a of topsoil, OB and mineral rejects (Rule 32,33)

valid document for this mine

Separate dumping As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

4b Location of topsoil, OB and mineral reject dumps

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan

letter no

approved vide

4c Number of dumps within lease area and outside valid of lease area

document for this mine

As on date of Mining operations in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

.AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

4d Location of dumps w.r.t. ultimate pit limit (Rule 16)

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

4e

valid document for this mine

Number of active As on date of Mining opertions in the and alive dumps. inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was

not working

4f Number of dead dumps.

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

4g Number of dumps established.

valid document for this mine

As on date of Mining operations in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

4h Whether Retaining wall or garland drain valid all along dumps are there.

document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan

approved vide

4i Length of Retaining wall or garland drain valid all along dumps

document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Number of 4ј settling ponds

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

4k Specific comments of inspecting officer on waste document for dump management

valid this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	inspection no valid document for	Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working, Part or full extrction of mineral not completed not matured for starting backfilling	Mining plan approved vide letter no .AP/CDP/Lat&Fe- 220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013- 2014.The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

5b Area under backfilling of mined out area valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working not matured for back filling

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

5c Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

5d As on date of Mining opertions in the Mining plan Total area inspection no mine suspended under approved vide fully reclaimed valid Rule 13(2) MCDR 1988 on letter no rehabilitated document for 26.11.2014 .As on date .AP/CDP/Lat&Fethis mine of inspection no valid 220-52 Dated document for this mine 23.08.2010 ,the mine was not the period from working M.L. area was 2009-2010 to 2013not matured for 2014. The validity reclamation and of Approved Mining rehabilation Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working 5e General remarks As on date of Mining operations in the Mining plan of inspecting inspection no mine suspended under approved vide officers on valid Rule 13(2) MCDR 1988 on letter no backfilling and document for 26.11.2014 .As on date .AP/CDP/Lat&Fereclamation etc. this mine of inspection no valid 220-52 Dated document for this mine 23.08.2010 for ,the mine was not the period from 2009-2010 to 2013working 2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Actual work

Remarks

Progressive Mine Clousre Plan:

Propasals

Sl.No.

Item

ба Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working. Annual Report on PMCP not submitted

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

6b Area available for rehabilitation (ha) .

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working Area was not available for rehabilation

бс afforestation done (ha).

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

6d No. of saplings planted during the year

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working no saplings were planted during the year

бе Cumulative no .of plants

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

бf of rehabilitation

valid document for this mine

Any other method As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

ба watch and care during the year

valid document for this mine

Cost incurred on As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

6h Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx

B x D

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

бi Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

бј Compliance on reclamation and rehabilitation by backfilling (iii) Afforestati this mine on on backfilled area

valid document for

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

бk Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working no rehabilation work crriedout by making water redorvoir

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

61 Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

бm Compliance of rehabilitation of waste land within lease (i)afforestation this mine

valid document for

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

бn Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

60 Compliance of rehabilitation of waste land within lease (iii) Method of rehabilitation valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Compliance of бр environmental monitoring (core valid zone and buffer zone)

document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working environmental monitoring in 9core zon and buffer zone) notcarriedout

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

бq General remarks of inspecting officers on PMCP valid compliance and progressive closure operations etc.

document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area		Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working	Mining plan approved vide letter no .AP/CDP/Lat&Fe- 220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013- 2014.The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working
	_		of inspection no valid document for this mine ,the mine was not	220-52 Dated 23.08.2010 for the period from 2009-2010 to 201 2014. The validity of Approved Minit Plan expired on 31.03.2014. Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As of date of inspection no valid document for this mine , the mine was

7b wise mineral sorting i.e. manual or mechanical.

valid document for this mine

Method of grade- As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

7с Different grade of mineral sorted out at mines.

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Remarks

7d As on date of Mining opertions in the Mining plan Any beneficiation inspection no mine suspended under approved vide process at mines valid Rule 13(2) MCDR 1988 on letter no document for 26.11.2014 .As on date .AP/CDP/Lat&Fethis mine of inspection no valid 220-52 Dated document for this mine 23.08.2010 ,the mine was not the period from working 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working As on date of Mining opertions in the 7e General remarks Mining plan of inspecting inspection no mine suspended under approved vide Rule 13(2) MCDR 1988 on officer on valid letter no Mineral document for 26.11.2014 .As on date .AP/CDP/Lat&Fe-220-52 Dated conservation and this mine of inspection no valid beneficiation document for this mine 23.08.2010 for issues ,the mine was not the period from 2009-2010 to 2013working 2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Actual work

Environment:

Item

Propasals

Sl.No.

8a and utilization of topsoil (Rule valid 32)

document for this mine

Separate removal As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

8b Concurrent use or storage of topsoil

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

8c Separate dumps for overburden, waste rock, rejects and fines (Rule 33)

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan

approved vide

8d Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

8e Phased restoration,

etc)

reclamation and rehabilitation of lands affected by mining operations (Pits, dumps

valid document for this mine

As on date of Mining opertions in the Rule 13(2) MCDR 1988 on 26.11.2014 .As on date ,the mine was not working

inspection no mine suspended under of inspection no valid document for this mine

8f

Baseline information on existence of plantation and additional plantation done (Rule 41)

valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

8g Survival rate valid document for this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

8h on roads to control airborne valid dust

document for this mine

Water sprinkling As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

8i General remarks of inspecting officer on aesthetic beauty document for in and around mines area

valid this mine

As on date of Mining opertions in the inspection no mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	Annual Return for the year 2015-16 not submitted by the lessee	Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014.The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working	Mining plan approved vide letter no .AP/CDP/Lat&Fe- 220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013- 2014.The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

9b Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager

9c

Annual Return for the year 2015-16 not submitted by the lessee

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Scrutiny of for area under pits, reclaimed area, dumps etc.

Annual return on for the year land use pattern 2015-16 not submitted by the lessee

Annual Return Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

9d Scrutiny of Annual return on for the year afforestation

Annual Return 2015-16 not submitted by the lessee

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

9e Scrutiny of Annual return on for the year mineral reject generation (Grade and quantity)

2015-16 not submitted by the lessee

Annual Return Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine the mine was not working

9£ Scrutiny of Annual return on for the year ROM stock and/or 2015-16 not graded ore

Annual Return submitted by the lessee

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

9q Scrutiny of Annual return on for the year sale value, Ex. Mine price and production cost

2015-16 not submitted by the lessee

Annual Return Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

9h Scrutiny of Annual return on for the year fixed assets

Annual Return 2015-16 not submitted by the lessee

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

9k Scrutiny of Annual return on for the year mining machineries

2015-16 not submitted by the lessee

Annual Return Mining plan approved vide letter no .AP/CDP/Lat&Fe-220-52 Dated 23.08.2010 for the period from 2009-2010 to 2013-2014. The validity of Approved Mining Plan expired on 31.03.2014.Mining opertions in the mine suspended under Rule 13(2) MCDR 1988 on 26.11.2014 .As on date of inspection no valid document for this mine ,the mine was not working

PAGE: 45

Details of violations observed during current violation pointed out	t inspection and compliance position of
Violation observed	Show couse position

Issued on Compliance on Rule NO. Issued on Compliance on

Date : (A.Prabhakar Rao)

Rule NO.

Indian Bureau of Mines