भारत सरकार /Government of India खान मंत्रालय/Ministry of Mines

भारतीय खान ब्यूरो/ Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय/Office of the Regional Controller of Mines

Phone No.: (0832)- 2741757 Opp.Old R.T.O.'s Office, Fax No. : (0832) -2741758 P.O. FATORDA - 403602,

E-Mail : <u>ro.goa@ibm.gov.in</u> Margao-GOA

File No:- KNT/BJP/LST-105/GOA Date:- 22.03.2018

To,

Shri V.R.Mathad, Lessee,Muddapur Limestone Mine Shree Veerbhadra Minerals, Taluka-Mudhol,District-Bagalkot, ,Karnataka Pin No. 587122

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Muddapur Limestone Mine, (M.L.No.2672), Shri V.R.Mathad situated in Muddapur Village, Mudhol Taluka, Bagalkot- District of Karnataka State.

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 06/03/2018 by the undersigned in presence of Mr. Govinda shetty, Mines Manager.

Rule	Nature of Violation observed
11(1)	Mining operations have not been carried out in accordance with the modification of Mining Plan approved vide MP/MAN-613(KNT)/GOA//207-08 dated 30/08/2011. As per the aforesaid approved MMP the height of benches were proposed upto3m.
	Whereas, It was observed during the inspection that the height of benches were between 5m to 6m, which is against the safety of the persons deployed and requirement of the scientific mining.
11(2)&27(2)	A financial assurance of an amount equal to the difference between the financial assurance due as on the date of notification of these rules and the financial assurance already furnished, shall be furnished to the authorized officer within a period of ninety days from the date of notification of these rule. However, the same has not been furnished to the competent authority under these rule. This may attract the provisions of rule 11(2) for suspension of mining operations.
45	In Annual Returns submitted from your mine for the Faniancial Year 1 st April 2016 to 31 st March 2017; details reprted under:-

- (i) Part-II A:-Information in respect of Capitail Structure were not furnished.
- (ii) Section 3 the reserves and resources estimated at the end of the year ,the Proved Mineral Reserve under 111 were reported as 67,488 Tonnes.

The above figures are unrealistic, incomplete or false as submitted by your mine lease.

- 02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.
- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Fourty five) days from the date of issue of this letter.

Yours faithfully,

(S.Prasad)
Deputy Controller of Mines
Indian Bureau of Mines

Copy forwarded to: -

- 1. The Controller of Mines, SZ, Indian Bureau of Mines, Bengaluru.
- 2. The Director, Directorate Mines and Geology, Govt.of Karnataka 49, Khanij Bhavan,Race Course Road, Bengaluru.

(S.Prasad)
Deputy Controller of Mines
Indian Bureau of Mines