भारत सरकार /Government of India खान मंत्रालय/Ministry of Mines

भारतीय खान ब्यूरो/ Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय/Office of the Regional Controller of Mines

Phone No.: (0832)- 2741757 Opp.Old R.T.O.'s Office, Fax No. : (0832) –2741758 P.O. FATORDA - 403602,

Margao-GOA E-Mail : ro.goa@ibm.gov.in File No:- MAH/KLP/BX-9/Goa, Date:-04.10.2017

Mine Code:-07MSH13008

To,

Shri S.T. Kodachwad, Proprietor,

M/s Bhartesh Construction Company,

Shop No.34/35, Corporation Complex,

Goa-Ves, Hindawadi, Dist; Belgaum,

Karnataka-590001.

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Girgaon Bauxite Mine, over an extent of 140.2 Ha. Situated in Girgaon village, Tq-Shahuwadi, in Kolhapur District of Maharashtra State. Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 21/09/2017 by the undersigned in presence of Mr Rajeev kumar Mining engineer

Mr.Rajeev kumar Mining engineer.	
Rule	Nature of Violation observed
11(1)	a) In the approved modified mining plan dated 20/04/2015 there was a proposal for making 20 trial pits in the year 2015-16. During inspection it was observed that no such pitting was done by the lessee. b) During field visit it was observed that woking and backfilling is not done as per the proposal marked on production and development plan for the year 2016-17.
26(2)	An yearly report before 1st July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive mine closure plan has not been submitted for the year 2016-17 so far.
31(4)	The plans and sections are not updated for reference.
Rule 45(5)(c)	Annual return for the year 2016-17 is not submitted to this office so far.
67	A self appraisal note to be submitted by the mines owner/lessee stating extent of implementation of approved minig plan/scheme of mining during the year 2016-17 along with supporting plan & sections ,representative photographs is not submitted to this office so far in hard as well as soft copy.

02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Fourty five) days from the date of issue of this letter.

Yours faithfully,

(Kalmata.M.K) Senior Mining Geologist Indian Bureau of Mines

Copy forwarded to: -

- 1. The Controller of Mines, SZ, Indian Bureau of Mines, Bengaluru.
- 2. The Director, Directorate of Geology & Mining, Govt.of Maharashtra, Khanij Bhavan, plot No-27, Shivaji Nagar, Cement Road, Nagpur-440010.

(Kalmata.M.K)
Senior Mining Geologist
Indian Bureau of Mines