

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग, सेक्टर-10A
गांधीनगर, गुजरात, 382010



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of Regional Controller of Mines
Karmayogi Bhavan, 4th Floor, Block-2, Sector 10A,
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

फाइल संख्या/File No.: GUJ/Porb/Bxt-09

Date: 13/08/2021

Mine Code – 07GUJ08009

प्रेषित/To: श्री नरेश प्रभुदास मखेचा
विथल निवास, स्टेशन रोड
जिला – पोरबंदर (गुजरात) – 360575
E-mail- naresh_makhecha@rediffmail.com

विषय /Subject: Violation notice of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Vishvada Bauxite Mines, Sy. No.-731/P, over an area of 12.1405 ha located near Village- Vishvada, District-Porbandar in Gujarat.

महोदय / Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 30.06.2021 in the presence of your representative Shri Dhruvil Makhecha :

<u>Rule No.</u>	<u>Nature of violation observed</u>
11(1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines... In your case it was found that Approved Review of Mining Plan approved on 13/07/2017 by the end of fifth year (2021-22) proposal for area under mining was 5.8530 ha. and during the inspection it was found that area towards the Northern End of Pit 1 towards Lease boundary was mined out which is not in the proposal. Hence the area under mining is exceeding for the yearly proposal of 2020-21.
26(2)	The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1st day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof... In your case it was found that yearly report for the Year 2020-21 for the extent of protective and rehabilitative work carried out has not been submitted.
27(2)	The nature of Violation of Rule 11(1) observed during inspection attracts the violation of second proviso of Rule 27(2).
33	Copies of plans and sections to be submitted.–The holder of a mining lease shall, on or before the 30th day of June every year submit to the authorised officer, as the case may be, and the State Government, a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32. In your case it was found that Digital copy along with print copy of Surface Geological Plan as maintained under Rule 32 of MCDR 2017 has not been submitted to this office

34(1)	<p>All digitally prepared plans, sections and print copies there of kept at the mine shall be suitably indexed.</p> <p>In your case during inspection the digitally prepared updated plans & sections were not present during inspection. (Rule 34(1) of MCDR 2017 should be read with Rule 31(4) of MCDR 2017, which clearly says Plans & Sections required under these rules shall be maintained up to date within 3 months in case of category "A" mines.)</p>
-------	--

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय /Yours faithfully,

नमन एक्का / Naman Ekka

वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist

मूल प्रति में नहीं :-

फाइल संख्या/File No.: GUJ/porb/Bxt-09

Date: 13/08/2021

प्रतिलिपि सूचनार्थ हेतु /Copy for information to:

1. खान नियंत्रक (उ. आ.), भारतीय खान ब्यूरो, उदयपुर ।
2. आयुक्त, भूविज्ञान एवं खनन निदेशालय, गुजरात ।
3. जिला भू- वैज्ञानिक, खनिज एवं खनन विभाग, कलेक्टर ऑफिस बिल्डिंग, ग्राउंड फ्लोर, रानीबाघ, पोरबंदर ।
4. कार्यालय प्रतिलिपि ।

नमन एक्का / Naman Ekka

वरिष्ठ खनन भूविज्ञानी /Senior Mining Geologist