

Registered with A/D.
Violation Letter

GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES

File No: MP/Katni/Limestone-181 2127-2129

Jabalpur,
Dated: /07/2016

To

Shri Pooranlal Vishwakarma, Mine Owner
At -Jalpa Devi Ward, Gautam Lane,
Distt. - Katni,(MP) -483501

19

Subject: Violation of provisions of Mineral Conservation & development Rule 1988 In respect of your **Jamuwankalan, Limestone Mine** over an area of **0.813 Hect.** in **Katni** district of M.P.

Sir,

The following provisions of the MCDR, 1988 were found violated in your above mine during MCDR inspection on **21/06/2016** by Sri G. Srivastava, Assitant Mining Geologist and Shri R.S.Munda, Assistant Mining Engineer of Indian Bureau of Mines in presence of your Representative, Shri S.K.Garg.

| | |
|----------------------|--|
| Rule-13(1) | <p>According to this rule every holder of a mining lease shall carry out mining operations in the mine in accordance with the approved mining plan. The Mining Plan for this mine was approved vide letter no.MP/Katni/Limestone/MPLN/R-08/2011-12,dated 02/08/2012 for a period up to 2012-13 to 2016-17.</p> <p>i) During the inspection, the location of pillar no.2 was not found at location as shown on the surface plan. The coordinates of pillar no.2 has been shown as N24 06' 45.051" E80 44' 1.45" on surface plan where as in field, it is located N24 06' 45.2" E80 44' 1.6". Therefore, location of pillar no.2 may be corrected as per surface plan and photograph of the same may be submitted.</p> <p>ii) As per chapter (7) seven and plate no. VIII of the approved mining plan dated 02/08/2012, dump no.1& 2 were proposed to be rehandle and utilized for the backfilling of excavated South-Eastern barrier zone but during the inspection, it was found that D-1 & D-2 are kept at their places intact and no back filling of the proposed site i.e. excavated South-Eastern barrier Zone was carried out. In compliance, the photograph of the above rectification may be submitted.</p> |
| Rule 45(5)(b) | <p>According to this rule the owner, agent, mining engineer or manager of every mine, shall submit to the Regional Controller of Mines returns in respect of each mine,(separate for all minerals) in the following manner, namely:-an annual return which shall be submitted before the 1st July each year for the preceding financial year in the prescribed Form. An annual return for 2015-16 has not been received in this office till date.</p> |

....2/-

2. In this connection it is brought to your notice that the above violations constitute an offence punishable under rule 58 of MCDR, 1988.
3. The mining operations can be suspended under rule 13(2), if compliance of rule 13(1) is not found satisfactory.
4. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

(K) *aw*
(Kathaiya Lal)

ofe Senior Mining Geologist
Indian Bureau of Mines

N.O.O

Copy for kind information to: -

1. The Director, Directorate of Geology & Mining, Khanij Bhavan, Arera Hills, Bhopal. (MP)
2. The Controller of Mines (CZ), Indian Bureau of Mines, Nagpur

*प्रिन्ट
आउट*

ofe (K) *aw*
Senior Mining Geologist
Indian Bureau of Mines

पता-/ Address योजना क्रमांक 11 कमला नेहरू नगर, जबलपुर 482002 (म.प्र.) Scheme No.11, Kamla Nehru Nagar, Jabalpur, 482002 (M.P.) फोन/Phone 2416780, 2416589 2416331
फैक्स/Fax 0761)-2416780 ई-मेल/E. Mail ro.jabalpur@ibm.gov.in