



दूरभाष सं. : / फॅक्स सं.: 0361 2656184,

Tel/Fax – 0361-2656184

ईमेल: ro.guwahati@ibm.gov.in

E-mail – ro.guwahati@ibm.gov.in

House No. 216, 3rd Floor, Above
IDBI Bank Chandmari, Post –
Bamunimaidan, Dist – Kamrup
(M), Guwahati, Assam-781021

No:- IBM/GHY/MEG/JNH/LST-12

Dated- 04.09.2018

To,

Sri Basant Kumar Mittal, (Nominated Owner)

M/s. Hills Cement Company Limited,

Village- Mynkree, 116 Km. Stone, NH-44,

Dist- East jaintia Hills,

Meghalaya-793200

E-mail: hcclmines@gmail.com

Subject: Violation of provisions of MCDR, 2017, in respect of your Mynkree Limestone Mine (38MEG03014) over an area of 4.00 Ha. in village Mynkree Village, Taluka-Khliehriat, East Jaintia Hills district of Meghalaya State.

Sir,

The following provisions of MCDR 2017 were found violated in your above mine during the inspection carried out on 22nd August 2018 by the undersigned in presence of the mine officials Sri M. K. Jain (Mines Manager) and Deependra Singh (Geologist).

Rule Number	Nature of violations observed
11(1): No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of minerals specified in Part B of the First Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession.	The following deviations to the approved review of mining plan were found in your mine:- i) Future Exploration:- There was a proposal given to drill 2 (Two) no. of bore hole during the year 2017-18, but till date you have not carried out any exploration program as envisaged in the approved review of mining plan document. ii) Protective Measures:- There was a proposal given to construct retaining wall- 90m x 1.5m x 1m and garland drain- 90m x 1m x 1m around the proposed temporary waste dump in the approved review of mining plan document; but till date there is no retaining wall and garland drain around the proposed temporary waste dump.
32(1) (a) & 32(5) (b) Regarding types of plan (digitally prepared) to be maintained by the holder of mining lease.	i) The surface plan and environment plan has not been updated till date.

o/c

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the violation immediately and intimate the position to this office within a period of 45 (Forty five) days from the date of issue of this letter.


Yours faithfully



(S. K. Mohapatra)
Senior Mining Geologist

Copy forwarded for kind information to:

- (i) The Controller of Mines (EZ), Indian Bureau of Mines, Kolkata.
- (ii) The Director, Directorate of Mineral Resources, Govt. Of Meghalaya, Risa Colony, Shillong, Meghalaya-793003.



(S. K. Mohapatra)
Senior Mining Geologist

o/c