

REGISTERED A.D.



GOVERNMENT OF INDIA  
MINISTRY OF MINES  
INDIAN BUREAU OF MINES  
OFFICE OF REGIONAL CONTROLLER OF MINES



FAX : 080- 23371027 / 23373287  
Tel : 080-23371027 / 23375366 / 67  
Email ID: ro.bangalore@ibm.gov.in  
rcombng@rediffmail.com

29, Industrial Suburb, II Stage,  
Tumkur Road, Gorguntapalya,  
Yeshwantpur,  
Bangalore- 560 022.

NO: KNT/TMK/Mn-55/BNG  
To: Smt. Sunanda V.Allum,  
Gadgi Palace Car Street,  
Bellari -583 101.

Date: 30.03.2016

Sub: Violation of provisions of MCDR 1988 in respect of your Shivsandra Mn ore mine, ML No.2636 (21.38Ha) in Shivsandra village, Gubbi taluk, Tumkur District, Karnataka state.

Sir,

The following provisions of the Mineral Conservation and Development Rules 1988 were found violated in your above mine during the inspection on 12.03.2016 by Sri K. Srinivas. Asstt. Mining Geologist, accompanied by Sri R.Kenchappa, Manager.

Rule No.	Violations observed
13(1)	<p>Scheme of Mining was approved vide letter no. 279/954/2007/BNG dated 22.06.2015 for the period 2015-16 to 2019-20. The deviations observed in mining operations vis-à-vis approved document are given below.</p> <p>(i) It was proposed to drill 5 exploratory core boreholes during the year 2015-16, but the same was not carried out.</p> <p>(ii) During the year 2015-16, the proposed production was 10000 tonnes, whereas the actual production during the year is reported as 700 tonnes(upto Feb,2016). The deviation is several folds on negative side.</p> <p>(iii) During the year 2015-16, construction of retaining wall, Garland drain,</p>
42(1)( c)(i)	

	<p>Gully checks were. The same has not been carried out.</p> <p>A holder of a Mining Lease is required to employ a whole-time Mining Engineer and Geologist possessing the qualification and experience laid down under the rule, but no such Mining Engineer/ Geologist has been appointed so far.</p>
--	---

-2-

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR 1988.

03. You are advised to rectify/explain the valid reasons for the above violation immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

Sd/-  
( Pukhraj Nenival )  
Dy. Controller of Mines

Copy for information to:

1. The Controller of Mines(SZ), IBM, Bangalore.
2. The Director, Department of Mining & Geology, No. 49, Kanijabhavan, R.C Road, Bangalore – 560 001.

Sd/-

( Pukhraj Nenival )  
Dy. Controller of Mines