INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

FMCP Inspection REPORT

Bangalore regional office

	Mine :	file No : KNT/BLR/FE/1	.26,	/BNG Mine code : 30KAR03124
	(i)	Name of the Inspecting Officer and ID No.	:	A101) ARUN KUMAR
	(ii)	Designation	:	Deputy Controller Mines
	(iii)	Accompaning mine Official with Designation	:	
	(iv)	Date of Inspection	:	24/09/2021
	(v)	Prev.inspection date	:	
		PA	RT-	I : GENERAL INFORMATION
1.	(a)	Mine Name	:	KARADIKOLLA (M.L. NO 1874
	(b)	Registration NO.	:	IBM/202/2011
	(c) (d) (e) (f) (g) (h)	Category Type of Working Postal address State District Village Taluka Post office Pin Code FAX No. E-mail Phone Police Station First opening date Weekly day of rest	: : : : : : : : : : : : : : : : : : : :	A Other than Fully Mech. Opencast KARNATAKA BELLARY KARADIKOLLA SANDUR HOSPET 583203 08394-230782 (F), goggabrothers@rediffmail.cd 08394-231487 (O), 94481909: Sandur 04/09/1983
2.		ess for espondance	:	M/S GOGGA GURUSANTHIAH & BROS MINE OWNERS & MINERAL GRINDERS, P.B.NO. 4, N.C.COLONY,HOSPET,BELLARY,KARNATAKA-583201.
3.	(a) (b) (c) (d)	Lease Number Lease area Period of lease Date of Expiry	:	KAR0175 18.21 20 03/09/2003
4.	Miner	ral worked	:	IRON ORE Main

5.	Name	and Address of	the		
		Lessee	:	GOGGA GURUSANTHIAH & BROS	
				POST BOX NO 4, NEHARU CO-OP COLONY, HOSPET, BELLARY KARNATAKA Phone:08394-28787,24617	
				FAX :08394-25782	
		Owner	:	GOGGA GURUSANTHIAH & BROS	
				POST BOX NO 4, NEHARU CO-OP	
				COLONY, HOSPET, BELLARY KARNATAKA	
				Phone: 28787,24617	
				FAX : 08394-25782	
		Mining Enginee	r		
		Name	:	K.V.BAKTHA VASTHALA NAIDU,Full Time	
		Qualification	:	B.E.MINING	
		Appointment/ Termination da		28/12/2000	
		Mining Enginee	r		
		Name	:	K.V.NARASIMHA REDDY,Full Time	
		Qualification	:	B.E.MINING	
		Appointment/ Termination da		07/11/2003	
б.		of approval of Scheme of Minin		ng : Existing rule 11 MCDR1988 04/05/19 Renewal under rule 22 MCR1960 04/06/20 Mining Scheme rule 12 MCDR1988 27/08/20 Mining Scheme rule 12 MCDR1988 22/09/20 MP review under 17(1) MCR 2016 21/10/20)02)09)15

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
la	Backlog of previous year	16 Trial Pits, 10 DTH & 3 Core Holes.	No exploration carried out.	Mine is non operational since 30.04.2008 for want of Environmental Clearance.
1b	Exploration over lease area for geological axis 1 or 2		G2-3.67 Ha,G3-4.43 Ha	Nil.
lc	Exploration Agencies and Expenditure in lakh rupees during the year	Nil	Rs.45000/- spent on putting trial pits & sampling analysis in the past.	6 Trail pits were made to prove the depth of the ore body & 4 trial pits were made for conducting recovery test.
1d	Balance area to be explored to bring Geological axis in 1 or 2	Not specified.	10.67 Ha needs to be explored.	Nil.
1e	Balance reserve as on 01/04/20	Nil.	127612 Tons(+45%Fe) & 42537 Tons (+35%Fe)	As per approved document.
lf	General remarks of inspecting officers on geology, exploration etc			Mine is non operational since 30.04.2008 for want of Environmental Clearance.

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	proposed: N -	Nil.	Nil.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)		Nil.	Nil.
2c	Stripping ratio or ore to OB ratio	1:0.33	Nil.	Nil.

2d	Quantity of topsoil generation in m3	No proposal.	Nil.	Nil.
2e	Quantity of overburden generation in m3		Nil.	Nil.
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc			Mine is non operational since 30.04.2008 for want of Environmental Clearance.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	One pit proposed.	Nil.	Nil.
3b	Quantity of ROM mineral production proposed	3700 Tons	Nil	Nil
3c	Recovery of sailable/usable mineral from ROM production	80%	Nil	Nil
3d	Quantity of mineral reject generation	No proposal	Nil	Nil
3e	Grade of mineral rejects generation and threshold value declared.	No proposal.	Nil.	Nil.
3f	Quantity of sub grade mineral generation.	No proposal .	Nil.	Nil.
3g	Grade of sub grade mineral generation	No proposal .	Nil.	Nil.
3h	Manual / Mechanised method adopted for segregating from ROM	B - Category Manual	Nil.	Nil.

3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No proposal.	Nil.	Nil.
3j	Provision of drilling and blasting in mineral benches	No proposal.	NA	NA
3k	Provision of mining machineries in mineral benches	Tipper = 1 No Tanker = 1 No Jeep = 1No	Nil.	Mine is non operational.
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Yes	Nil.	Nil.
3m	Total area covered under excavation/pits	1.09 Ha at the end of plan period.	1.07 Ha.	Nil.
3n	Ore to OB ratio for the pit/mine during the year.	1:0.33	Nil.	Nil.
30	Total area put in use under different heads at the end of year	Arae under mining-1.09 Ha,Waste dump- 0.18 Ha,Mineral storage-0.30 Ha,Infrastruct ure-& roads- 0.95 Ha,Green belt- 1.30Ha,area for bio diversity-1.0 Ha,Area for future use- 10.28 Ha	Nil.	Nil.
Зp	Production of ROM mineral during the last five year period as applicable	2016-17: NIL 2017-18 :NIL 2018-19: NIL 2019-20:3700 Tons 2020-21:3700 Tons	2016-17:NIL 2017-18 NIL 2018-19: NIL 2019-20: NIL 2020-21: NIL	Mine is non operational.

3q	General remarks of inspecting officers on method of mining etc.	Mine is non operational since 30.04.2008 for want of Environmental Clearance.

Solid Waste Management - Dumping:

Sl.No. Item Propasals Actual work Remarks 4a Separate dumping Backfilling Nil. Nil. of topsoil, OB proposed in FY and mineral 2020-21 rejects (Rule 32,33) Location of No proposal. Nil. Nil. 4b topsoil, OB and mineral reject dumps Number of dumps WML-02 Dumps, WML-02 Dumps, 4c Nil within lease OML- Nil. OML- Nil. area and outside of lease area 4d Location of No proposal. Backfilling proposed. Nil. dumps w.r.t. ultimate pit limit (Rule 16) 4e Number of active 2 No's Nil. Nil. and alive dumps. Inactive dumps (ID1 & ID2) Reclaimed & one Temporary dump. 4f Number of dead 2 Nos. 02 Nos. Nil. dumps. Number of dumps 2 No's 02 Nos. Stabilized with 4g established. plantation. 4h Whether Yes Yes Retaining wall or garland drain all along dumps are there. 4i Length of No proposal. Nil. Constructed in the Retaining wall past as per the or garland drain approved R & R all along dumps Plan & maintained. 4j Number of Constructed in the No proposal. Nil. settling ponds past as per the approved R & R Plan & maintained.

4k	Specific	Mine is non
	comments of	operational since
	inspecting	30.04.2008 for
	officer on waste	want of
	dump management	Environmental
		Clearance.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposal.	Nil.	Nil.
5b	Area under backfilling of mined out area	0.06 Ha	Nil.	Nil.
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No Proposal.	Nil.	Nil.
5d	Total area fully reclaimed and rehabilitated	0.06 Ha.	Nil.	Nil.
5e	General remarks of inspecting officers on backfilling and reclamation etc.			Mine is non operational since 30.04.2008 for want of Environmental Clearance.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	Annual report on PMCP to be submitted by 1st July of every year.	Not submitted.	Violation issued.
6b	Area available for rehabilitation (ha) .	No Proposal.	Nil.	Mine is not Operational.

бс	afforestation done (ha).	0.325 Ha.	Nil.	Nil.
6d	No. of saplings planted during the year	325 No's	Nil.	Nil.
бе	Cumulative no .of plants	Not specified.	Nil.	Nil.
бf	Any other method of rehabilitation	Not specified.	Nil.	Nil.
бg	Cost incurred on watch and care during the year	16250/-	Nil.	Nil.
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	6.060 Ha X 3M	Nil.	Mine is non operational.
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	Backfilling proposed.	Nil.	Nil.
6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area	No proposal.	Nil.	Nil.
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No proposal.	Nil.	Nil.
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	No proposal.	Nil.	Nil.
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	Afforestation proposed.	Nil.	Nil.

6n	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	0.325 Ha.	Nil.	Nil.
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	Plantation of 325 saplings proposed.	Nil.	Nil.
бр	Compliance of environmental monitoring (core zone and buffer zone)		Nil.	Nil.
бq	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.			Mine is non operational since 30.04.2008 for want of Environmental Clearance.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	Manual Sorting & Sizing.	Nil.	Nil.
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	Manual sorting proposed.	Nil.	Nil.
7c	Different grade of mineral sorted out at mines.	Fines: - 10mm,C-Ore: 10 mmto 40 mm	Nil.	Nil.
7d	Any beneficiation process at mines	No proposal.	Nil.	Nil.
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			Mine is non operational since 30.04.2008 for want of Environmental Clearance.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	No Proposals.	Nil.	Nil.
8b	Concurrent use or storage of topsoil	No proposals.	Nil.	Nil.
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	No proposals.	Nil.	Nil.
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No Proposals Except Backfilling of waste.	Nil.	Mine is non Operational.
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Proposals of Mined out Pit by backfilling & Plantation.	Nil.	Nil.
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	Available	Nil.	Nil.
8g	Survival rate	80%	75%	Nil.
8h	Water sprinkling on roads to control airborne dust	sprinkling		Nil.

8i General remarks	Mine is non
of inspecting	operational since
officer on	30.04.2008 for
aesthetic beauty	want of
in and around	Environmental
mines area	Clearance.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns		M.R. Submitted up to _AUGUST 2021 ***** A.R. Submitted up to 2019-20	AR submitted on 04.07.2020 (2019- 20). Violation issued for non submission of AR for FY 2020-21.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager		Seshagiri Samji was appointed as Mine Manager.	AR 2019-20
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	current	Appears to be correct.	
9d	Scrutiny of Annual return on afforestation	150 Saplings with in ML area @75% survival rate.	Appears to be correct.	
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Nil.	Nil.	

9f	Scrutiny of Annual return on ROM stock and/or graded ore	6251.65 Tons,	Appears to be correct.
9g		Ex. Mine price & production	Mine is non operational since 30.04.2008
9h	Scrutiny of Annual return on fixed assets		Nil.
9k	Scrutiny of Annual return on mining machineries	Nil.	Nil.

Details of violations observed during current inspection and compliance position of violation pointed out							
	Violation observed Show couse position						
Rule I	NO.	Issued on	Compliance on	Rule NO.	Issued on Compliance on		
MCDR17	Rule 26(2) 11/10/2021					
MCDR17	Rule 28(1) 11/10/2021					
MCDR17	Rule 45(5)(c11/10/2021					

Date :

(ARUN KUMAR)

Indian Bureau of Mines