# MINERALS DE LOPMEMT AND REGULATION DIVISION Review and updation of Mining Plan REPORT Hyprabad regional office

(i)	Name of the Inspecting Officer and ID No.	:	MQ29 ) MADHU SUDHAN YADAV M
(ii)	Designation	:	Assistant Controller Mine
(iii)	Accompaning mine Official with Designation	:	Sri. V. Ramachandram, Mines Manager, Sri. J. Srinivas
(iv)	Date of Inspection	:	21-SEP-22
(v)	Prev.inspection date	:	13-OCT-17

#### PART-I : GENERAL INFORMATION

1.	(a)	Mine Name	: SRI VENKATESWARA
	(b)	Registration NO.	:
		Category	: A Manual
		Type of Working Postal address	• Opencast
		State	: TELANGANA
		District	: NALGONDA
		Village	: CHINTALAPALEM
		Taluka	: MELLACHERVU
		Post office	:
		Pin Code	: 508246
		FAX No.	: 040-23353093
		E-mail	: info@anjanicement.com
		Phone	: 04023353096
	(f)	Police Station	: JAGGAIAHPET
	(g)	First opening date	: 24-DEC-93
	(h)	Weekly day of rest	: SUN
2.	Addr	ess for	: CHINTAPALEM VILLAGE
	corr	espondance	MELLACHERVU MANDAL
			NALGONDA DISTRICT
3.	(a)	Lease Number	: APR0025
	(b)	Lease area	33-993
	(C)	Period of lease	: 20

(d) Date of Expiry

4. Mineral worked

: LIMESTONE

: 21-MAY-05

Main

: M/S ANJANI PORTLAND CEMENT LTD SITHA NILAYAM 153 DWARAKAPURI COLONY PUNJAGUTTA HYDERABAD TELANGANA Phone: 3353093 FAX :40-3353093

Owner

K.VISHNU RAJU : M/S. ANJANI PORTLAND CEMENT LTD. SUTA NILAYAM, 153, DARAKAPUERI COLO PUNJAGUTTA, HYDERABAD. NALGONDA TELANGANA Phone: FAX :

Agent

: S.N.RAJU CHINTHAPALEM VILLAGE GUDIMALKAPURAM nALGONDA DIST. NALGONDA TELANGANA Phone: 08683-230160 FAX : 08683-230024

Manager V.RAMACHANDRAM Name : DIPLOM IN MINING Qualification : Appointment/ : 05-JUN-07 Termination date

6. Date of approval of Mining Plan/Scheme of Mining

: Mining Scheme rule 12 MCDR1988 23-DEC-09 MP modif under 17(3) MCR 2016 MP review under 17(1) MCR 2016

04-MAY-16 20-NOV-17

PAGE : 2

### PART - II : OP RVATION/COMMENTS OF INSPECTING OFFICERS

: 3

Exploration :

-

Sl.No.	Item	Proposals	Actual work	Remarks
la	Backlog of previous year	No proposal	Nil	
1b	Exploration over lease area for geological axis 1 or 2	Nos. of	Only 5 Nos. of boreholes drilled. Violation issued as per rule.	5
1c	Exploration Agencies and Expenditure in lakh rupees during the year		Not submitted by the lessee	
1d	Balance area to be explored to bring Geological axis in 1 or 2		Entire mining lease area is not covered under exploration.	1
le	Balance reserve as on 01/04/20		Mineral Reserves as per last approved Review of Mining Plan is 9.6 million tonnes	
lf	General remarks of inspecting officers on geology, exploration etc			In the mining lease area no borehole is drilled upto contact zone. Advised lessee to submit proposal to drill boreholes upto contact zone.

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	E390686- E390536, N1852182- N1852001	No work done due to no Environment Clearance.	
2b	· · · · ·	Only mineral benches proposed	Only mineral benches developed in the mine	
2c	Stripping ratio or ore to OB ratio	Nil	Nil	

No development

work carried out

during the plan

of Environment

Clearance.

in the lease area

period due to lack

2d Quantity of No proposal Nil topsoil generation in m3

1

- 2e Quantity of No proposal Nil overburden generation in m3
- 2f General remarks of inspecting officers on development of pit w.r.t. type of deposit etc

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	One	One	
3b	Quantity of ROM mineral production proposed	2021-22- 299972 Te	Nil	
3с	Recovery of sailable/usable mineral from ROM production	100%	Níl	
3d	Quantity of mineral reject generation	No proposal	Nil	
3e	Grade of mineral rejects generation and threshold value declared.	Not applicable	Nil	
3f	Quantity of sub grade mineral generation.	No proposal	Nil	
Зg	Grade of sub grade mineral generation	Not applicable	Nil	

PAGE : 5

Difference found

per drone images submitted by the lessee. Advised to verify the data.

in the pit area as

_

3h Manual / No proposal Nil
Mechanised
method adopted
for segregating
from ROM


3i Any analysis or No proposal Nil beneficiation study proposed and carried out for sub grade mineral and rejects.

- 3j Provision of Drilling and Nil drilling and Blasting blasting in proposed in mineral benches the mineral benches
- 3k Provision of Excavator and Nil
  mining dumper
  machineries in combination
  mineral benches was proposed.
- 31 Whether height It was Nil of benches in proposed to overburden and maintain the mineral suitable bench height for method of of 8 meters mining proposed in MP/SOM
- 3m Total area 7.516 Ha 3.446 Ha as per last covered under approved Review of excavation/pits Mining Plan
- 3n Ore to OB ratio No proposal for the pit/mine during the year.

Nil

30 Total area put 13.05 Ha in use under different heads at the end of year

4.8203 Ha as per last approved Review of Mining Plan



3q General remarks of inspecting officers on method of mining etc. No production carried out during the last approved Review of Mining Plan period due to lack of Environment Clearance.

### Solid Waste Management - Dumping:

million tonnes

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	No proposal	Nil	
4b	Location of topsoil, OB and mineral reject dumps	No proposal	Nil	
4 c	Number of dumps within lease area and outside of lease area	No proposal	Nil	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	No proposal	Nil	
4e	Number of active and alive dumps.	No proposal	Nil	
4f	Number of dead dumps.	No proposal	Nil	
4g	Number of dumps established.	No proposal	Nil	

PAGE 7

-

4h	Whether Retaining wall or garland drain all along dumps are there.	No	proposal	Nil
4i	Length of Retaining wall or garland drain all along dumps	No	proposal	Nil
4j	Number of settling ponds	No	proposal	Nil
4 k	Specific comments of inspecting officer on waste dump management			

### Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposal	Nil	
5b	Area under backfilling of mined out area	No proposal	Nil	
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No proposal	Nil	
5d	Total area fully reclaimed and rehabilitated	No proposal	Nil	
5e	General remarks of inspecting officers on backfilling and reclamation etc.			The pit is not mined out upto its ultimate pit limit to start backfilling.

Progressive Mine Clousre Plan:

### 

Sl.No.	Item	Propasals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	To be submitted as per rule	Not submitted. Violation issued as per rule.	
6b	Area available for rehabilitation (ha) .	No proposal	Nil	
6c	afforestation done (ha).	2021-22 - 0.832 Ha	Nil.	Violation issued as per rule for not carrying out plantation work.
6d	No. of saplings planted during the year	2021-22 - 2080 Nos.	Nil	Violation issued as per rule for not carrying out plantation work.
6e	Cumulative no .of plants	10400 till 2022-23	Nil	Violation issued as per rule for not carrying out plantation work.
6f	Any other method of rehabilitation	No proposal	Nil	
6g	Cost incurred on watch and care during the year	No proposal	Nil	
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling ( Lx B x D	No proposal	Nil	
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No proposal	Nil	

PAGE : 8

6j Compliance on No proposal Nil reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area 6k Compliance on No proposal Nil reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir 61 Compliance on No proposal Nil reclamation and rehabilitation by backfilling (v) any other specific means. 6m Compliance of No proposal Nil rehabilitation of waste land within lease (i) afforestation No proposal 6n Compliance of Nil rehabilitation of waste land within lease (ii)Area rehabilitation (ha) 60 Compliance of No proposal Nil rehabilitation of waste land within lease (iii) Method of rehabilitation 6p Compliance of Quarterly No environmental environmental environmental monitoring work carried monitoring (core monitoring of out.

buffer zone.

zone and buffer core and

zone)

Violaiton issued as per rule.

-

PAGE : 10



6q

General remarks of inspecting officers on PMCP compliance and progressive closure operations etc. No plantation work, garland drain construction, siltation tank construction done as per proposal. Violation issued as per rule.

#### Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	' Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	No grade wise sorting proposed. Entire ROM is to be despatched.	Nil	
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	No proposal	Nil	
7c	Different grade of mineral sorted out at mines.	No proposal	Nil	
7d	Any beneficiation process at mines	No proposal	Nil	
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			No sub grade has been generated. Beneficiation is not required as the entire ROM mineral is proposed to utilise for captive plant

#### Environment:

Sl.No.	Item	Propasals	Actual work	Remarks	

\*

8a	Separate removal and utilization of topsoil (Rule 32)	No proposal	Nil
8b	Concurrent use or storage of topsoil	No proposal	Nil
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	No proposal	Nil
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No proposal	Nil
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No proposal	Nil
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	10400 Nos. of saplings in 4.16 Ha area during the plan period	Nil
8g	Survival rate	No proposal	Nil
8h	Water sprinkling on roads to control airborne dust	Water Tankers to be provided for dust supression.	Nil
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area		

Violation issued as per rule.

Old plantation found near the mine office area.

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	To be submitted as per rule	Submitted.	
9b	Scrutiny of Annual return for information on Mining Engineer,	V.	Mining Engineer - Working in other lease Geologist - Not working in the company	Violation issued for not appointing Mining Engineer and Geologist as per rule.
	Geologist and Manager	Sri. J. Srinivas Raju Geologist - Sri. P.		
9c	Scrutiny of	Aravind Pit = 3 89 Ha	Difference found in the	
	Annual return on land use pattern	Infrastructure - 1.74 Ha Green Belt -	pit area as per drone images submitted by the lessee. Advised to correct in the returns portal.	
9d	Scrutiny of Annual return on afforestation	Nil	Nil	
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Nil	Nil	
9f	Scrutiny of Annual return on ROM stock and/or graded ore	Nil	Nil	
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	Nil	Nil	
9h	Scrutiny of Annual return on fixed assets	Nil	Nil	
9k	Scrutiny of Annual return on mining machineries	Nil	Nil	

AGE : 12'

## Complian of Rule 45:

Details of violations observed during ent inspection and compliance position of violation pointed out						
Violation observed		Show couse position				
Issued on Compliance on	Rule NO.	Issued on Compliance o				
29-SEP-22						
29-SEP-22						
29-SEP-22						
(c 29-SEP-22						
29-SEP-22						
29-SEP-22						
	Issued on Compliance on 29-SEP-22 29-SEP-22 29-SEP-22 (c 29-SEP-22 29-SEP-22 29-SEP-22	Issued on Compliance on Rule NO. 29-SEP-22 29-SEP-22 29-SEP-22 (<29-SEP-22 29-SEP-22 29-SEP-22				

Date : 16/11/2022

1

(MADHU SUDHAN YADAV M) Indian Bureau of Mines

