

GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
Office of the Regional Controller of Mines, Hyderabad

No.AP/KNL/Lst-121/Hyd

6th Floor, CGO Towers,
Kavadiguda,
Secunderabad-500080.
Date

To
Sri. B.Rajendranth, Lessee,
H.no.10/161,
At & PO:Bethamcherla-518599,
Kurnool dist.

Sub: Violation of provisions of MCDR, 1988 in respect of Palkur Limestone mine over an area of 4.05 ha in Sy.no.57/1C & 57/2 of Palkur Village, Banganapalli Mandal, Kurnool District, A.P. State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above mine during the inspection on 21.8.2016 by Shri M, Pratap Reddy Asstt.Mining Geologist of this office accompanied by Sri B.Bo Reddy, Mines Manager

Rule No.	Nature of Violation
13(1)	The mining operations have not been carried out in accordance with the proposals given in the approved Scheme of Mining vide letter No. AP/KNL/MP/Lst-23/Hyd dated 16.11.2012 to the extent given below: i) Against the proposal of plantation of 200 saplings in the year 2015-16, no plantation is done.
23E(2)	The yearly report for the year 2014-15 setting forth the extent of protective and rehabilitation work as envisaged in the approved Scheme of Mining ought to have been submitted to the Regional Controller of Mines, Indian Bureau of Mines, Hyderabad before First July, 2016 has not been submitted.
42(1) (C) (ii)	A Part time Mining Engineer and Part time Geologist under Rule 42(6) of MCDR, 1988 has not been employed for carrying out mining operations as required under the rule.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 58 of MCDR, 1988.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

(Manish K Maindiratta)
Deputy Controller of Mines

मूल प्रति पर नहीं/Not on the Original:

1. खान नियंत्रक(द), भारतीय खान ब्यूरो, बंगलूर को प्रतिलिपि सूचनार्थ अग्रेषित ।
2. The Director of Mines & Geology, Government of Andhra Pradesh, BRBK Bhawan, Tank Bund Road, Hyderabad.
3. The Assistant Director of Mines & Geology, Government of Andhra Pradesh Banaganapally, Kurnool district, A.P.

(मनीष के .मेन्दीरत्ता)
उप खान नियंत्रक