REPORT ON CHECK INSPECTION OF <u>ADANAKURICHI LIMESTONE MINE</u> OF <u>M/S</u> <u>THE INDIA CEMENTS LIMITED, DALAVOI WORKS</u> IN <u>ARIYALUR</u> DISTRICT OF <u>TAMILNADU</u> STATE [PREPARED IN THE FORMAT, PRESCRIBED VIDE CCOM'S LETTER NO. 11013/35/MP/MISC/89-CCOM (Vol. III)]

Name and designation of inspecting officer : G.C.Sethi, RCOM, IBM, Chennai

Date of Inspection : 12.02.2023

1. General information of the mine

(i) Name of the mine : Adanakurichi Limestone Mine [GO.Ms.NO.765]

(ii) Owner : The India Cements Limited (iii) Nominated owner : Lakshmi Aparna Sreekumar

(iv) Mining Engineer : P.Arunkumar (v) Agent : T.Balasubramanian

(vi) Mine Manager: G.Balu(vii) Lease area: 17.58.0 ha

(viii) Location : Alathiyur village, Sendurai taluk, Ariyalur district

(ix) Lease period : 50 years (as per MMDR amendment act)

(x) Date of Expiry: 27.10.2049(xi) Date of approval of Mining Plan: 30.07.1999(xii) Date of approval of Review of Mining Plan: ROMP-11.11.2019(xiii) Period of Mining Plan/ Review of Mining Plan: 2020-21 to 2024-25

(xiv) Production (achieved) : 2021-22

ROM – 56868.58 Ts LST – 56717.32 Ts

2. Brief description of the mine:

(a) A brief description of the mine covering location, geology, problems associated with mining of the deposit etc.

(1) Location:

Adanakurichi Limestone Mine is located in revenue villages of Adanakurichi and Alathiyur villages, Sendurai taluk and Ariyalur district. The area is accessible through the metal/tar road branching off from Pennadam and it is situated about 7kms. Toposheet Number: 58M/7.

Latitude: 11°22' 16.3" N to 11°22' 36.4" N, Longitude: 79°15'02.7" E to 79°15'25.6" E.

(2) Geology:

Local Geological Set-up

This area is belonging to the Niniyur stage of the cretaceous system of Trichy area. The local geological section constructed on the basis of exploratory boreholes drilled in the area is as follows:

Lithology:

Overburden Soil

Cuddalore Sandstone

Limestone

Marl / Low-grade Limestone

Limestone

Greenish Clay and Sandstone.

The entire sequence has strike direction of N 25 $^{\circ}$ E – S 25 $^{\circ}$ W with a gentle south-easterly dip of about 5 to 7 $^{\circ}$ SE.

(3) Problems associated with mining of the deposit etc. ---

(b) Description on deployment of mining machinery

S1.	Machineries	Capacity	Number	In	Idle	Percentage	Brief	Remarks
No.	deployed		of units	use		of	description	
						utilization		
1	2	3	4	5	6	7	8	9
1	Dipper Shovels							
2	Back Hoes							
3	Front End Loader							
4	Water Sprinkler							
5	Tippers	8 m^3	5	5	0	84.30%		
6	Drills / Blast Holes							
7	Bull Dozers							
8	Motor Graders							
9	Crushers							
10	Cranes							
11	Air Compressor							
12	Surface Miner	900 HP	1	1	0	62.00%		

3. Implementation of Mining Plan or Review of Mining Plan:

Sl.No	1 1 11	Observations regarding imple	Remarks/Rea		
	Mining Plan or Scheme	given in approved Mining Plan or Review of Mining		son for	
	of Mining	of Mining Plan.		deviation	
1	2	3	3		
(1)	CONSERVATION OF MINERALS				
		Proposal	Actual	2021-22	
(a)	Exploration	Nil	Nil	Nil	
(b)	Utilization of sub-grade mineral	Nil	Nil	Nil	
(c)	Any other proposal for monitoring	Nil	Nil	Nil	
(2)	SCIENTIFIC MINING				
(a)	Mine Development and method of mining	225536 tons	56717 tons	Nil	
(b)	Handling of Waste/ sub- grade material	6930 cum	140 cum	Nil	
(c)	Area reclamation & restoration	0.10 hect	0.03 hect	Nil	
(d)	Any other proposal for monitoring	Nil	Nil	Nil	

(3)	PROTECTION OF ENVIRONMENT					
(a)	Afforestation	300 Nos of Saplings 300 nos of Saplings Nil				
(b)	Quality of air	Monitoring and all values are with	Nil			
(c)	Quality of Water	Monitoring and all values are within the limit.				
(d)	Noise level	Monitoring and all values are with	Nil			
(e)	Vibration	Monitoring and all values are within the limit.				

(f)	Any other	 Nil
	proposal for	
	monitoring.	

4. History of Violations after approval of Mining Plan or Review of Mining Plan:

SL	Date of	Name of	Violations of MCDR, 2017	Rectification of	Remarks
No.	Inspection	inspectin	observed and pointed out	violations	
		g officer			
1	2	3	4	5	6
1	01.02.2021	Matiul	Non Submission of Plan &	Complied on 15.04.2021	
		Islam	sections		
2	07.08.2021	Salil	Less Production	Complied on 20.10.2021	
		Sandip			
		Kujur			
3	09.09.2022	Matiul	Less Production	Complied on 09.11.2022	
		Islam			

5. Socio-Economic Development Plan:

Sl.	Proposed Action Plan towards	Expenditure	Expenditure	Remarks
No.	socio-Economic Development	proposed	Incurred	
		(In Rs. Lakh)	(In Rs. Lakh)	
1	2	3	4	5
(1)	General Development in the			
	area			
	(i) Housing			
	(ii)Water Supply	0.100	0.100	
	(iii) Sanitation	0.442	0.442	
	(iv) Health safety and Medical	0.050	0.050	
	Facilities			
(2)	Education and Training	0.250	0.250	
(3)	Employment to local inhabitants			
(4)	Public Transportation and	0.076	0.760	
	communication			
(5)	Recreation and other sports	0.126	0.126	
	activities			
(6)	Expenditure for environment			
	management			
(7)	Other	1.40	1.40	
	Total	2.44	2.44	

- 6. Observations/ remarks on the earlier inspection carried out by sub-ordinate officer(s) with specific thrust on systematic and scientific mining, mineral conservation and environmental protection and other sensitive/ important aspects pertaining to the mine area or surroundings (CRZ/ Western Ghats/ Wildlife Sanctuaries etc.):
- 1) Name of inspecting officer: Shri. Matiul Islam, ACOM
- 2) Date and Type of inspection: MCDR & Star Rating Inspection 09.09.2022
- 3) Observations/ Remarks w.r.t. the inspection carried out by the sub-ordinate officer(s) and shortfalls in the inspection report, if any, thereof: Nil

Name of the Officer: G.C.Sethi
Designation: Regional Controller of Mines