# INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

#### FMCP Inspection REPORT

#### Hyderabad regional office

Mine file No : AP/VZNR/Mn-131/Hyd Mine code : 40APR20076

(i) Name of the Inspecting : RK13 ) A.V.Ramesh Kumar

Officer and ID No.

(ii) Designation : Assistant Mining Geologis

(iii) Accompaning mine : Sri Asok Konda, Nominated Owner.

Official with Designation

(iv) Date of Inspection : 04-MAY-23

(v) Prev.inspection date :

PART-I : GENERAL INFORMATION

1. (a) Mine Name : CHINNARAVYAM MN (4.053 HA)

(b) Registration NO. : IBM/732/2011

(c) Category : A Other Mechanised

(d) Type of Working : Opencast

(e) Postal address

State : ANDHRA PRADESH
District : VIZIANAGARAM
Village : CHINNARAVYAM
Taluka : MERAKAMUDIDAM

Post office : GARBHAM Pin Code : 535102

FAX No. :

E-mail : mines@sarawagi.com

Phone : 9704988444

(f) Police Station : Budarayavalasa

(g) First opening date : 01-MAR-08

(h) Weekly day of rest : SUN

2. Address for : M/S S.K.SARAWAGI & Co(P) Ltd

correspondance CHEEPURUPALLI (PO)

VIZIANAGARAM Dt,-535 128

3. (a) Lease Number : APR3130 (b) Lease area : 4.06

(c) Period of lease : 50

(d) Date of Expiry : 23-MAR-57

4. Mineral worked : MANGANESE ORE Main

5. Name and Address of the

Lessee : SK SARAWAGI AND (P)CO LTD

VIZIANAGARAM ANDHRA

PRADESH

Phone: 08952 83225 &83374

FAX :

Owner : ASOK KONDA

SK SARAWAGI HOUSE KASPA STREET, CHIPURUPALLY, VIZIZNAGARAM DISTRICT

VIZIANAGARAM ANDHRA PRADESH

Phone: 9704988444

FAX :

Agent : B CHANDRASEKHAR

M/s S K Sarawagi & Co

Waltair Uplands

Visakhapatnam VIZIANAGARAM

ANDHRA PRADESH Phone: 9346546023

FAX :

Mining Engineer

Name : P ARUN JYOTHI, Full Time

Qualification : BTECH MINING

Appointment/ : Termination date

Geologist

Name : V CHIRANJEEVI, Full Time

Qualification : MSC GEOLOGY

Appointment/ : Termination date

6. Date of approval of Mining : Mining Scheme rule 12 MCDR1988 23-JAN-14 Plan/Scheme of Mining Modif.approved Mining Scheme 30-MAR-15 MP review under 17(1) MCR 2016 09-AUG-18

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

#### Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	No exploration was proposed during the year 2022-23.	No exploration carried out during the year 2022-23	No comments to offer.
1b	Exploration over lease area for geological axis 1 or 2		The entire potentiall mineralised zone is explored under G-1 level.	No comments to offer.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	None	None	None
1d	Balance area to be explored to bring Geological axis in 1 or 2	Nil	Nil	None
1e	Balance reserve as on 01/04/20		The reserves as on 1.4.2023 are 4,06,891 tonnes	No comments
1f	General remarks of inspecting officers on geology, exploration etc		None	The mining operations are under suspension since 29.07.2022.

#### Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	development	proposal for	The Mining operations are under suspension since July 2022.No development taken place	No comments to offer.
2b	in topsoil,	approved proposals for	No mining operations carried out duirng the year 2022-23. There are seperate benches in OB and ore from previous year working.	No comments to offer.
2c	Stripping ratio or ore to OB ratio	Nil	None	None

2d	Quantity of topsoil generation in m3	Nil	None	None
2e	Quantity of overburden generation in m3	Nil	None	None
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc		There was no development duirng the year 2022-23 as the mining operations were suspended since July 2022. Also there are no approved proposals for the year 2022-23.	The inspection was carried out as the lessee submitted Final Mine Closure plan.

# Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	proposals for	earlier working was done from one pit.No operations carried out duirng the year 2022-23.	No comments
3b	Quantity of ROM mineral production proposed	Nil	None	None
3с	Recovery of sailable/usable mineral from ROM production	Nil	None	None
3d	Quantity of mineral reject generation	Nil	None	None
3e	Grade of mineral rejects generation and threshold value declared.	Nil	None	None
3f	Quantity of sub grade mineral generation.	None	None	None
3g	Grade of sub grade mineral generation	Nil	None	None

3h	Manual / Mechanised method adopted for segregating from ROM	Nil	None	None
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	Nil	None	None
3ј	Provision of drilling and blasting in mineral benches	Nil	None	None
3k	Provision of mining machineries in mineral benches	Nil	None	None
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Nil	No development took place duirng the year 2022-3. The earlier benches wwere having a height of 6 meters.	No comments
3m	Total area covered under excavation/pits		Pit - 2.730 ha Infrastructure - 0.210 ha Dump - 0.80 ha	No comments
3n	Ore to OB ratio for the pit/mine during the year.	Nil	None	No comments
30	Total area put in use under different heads at the end of year	Nil	Pit - 2.730 ha Infrastructure - 0.210 ha Dump - 0.80 ha	No comments

3p	ROM mineral during the last	approved production proposals for the year 2022-23.	There are no production for the year 2022-23. 2018-19 - 37162 tonnes 2019-20 - 41042 tonnes 2020-21 - 51863 tonnes 2021-22 - 10260 tonnes 2022-23 - none	No comments
3q	General remarks of inspecting officers on method of mining etc.		There are no valid approved proposals for the year 2022-23. The mining operations are under suspension from July 2022.	No comments

### Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	of topsoil, OB	proposals for the year 2022-	No development took place duirng the year 2022-23. However, there are benches in OB and ore for the earlier years.	No comments
4b	Location of topsoil, OB and mineral reject dumps	Nil	None	None
4c	Number of dumps within lease area and outside of lease area	Nil	None	None
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	None	None	None
4 e	Number of active and alive dumps.	Nil	One dead dump	No comments
4 f	Number of dead dumps.		One	No comments

4g	Number of dumps established.	Nil	None	None
4h	Whether Retaining wall or garland drain all along dumps are there.	Nil	None	None
4i	Length of Retaining wall or garland drain all along dumps	Nil	Nil	None
4j	Number of settling ponds	Nil	None	None
4 k	Specific comments of inspecting officer on waste dump management	Nil	None	None

# Solid Waste Management - Backfilling:

Item	Propasals	Actual work		Remarks
Status of part or full extraction of	There are approved document for	out duirng the		No comments
		,		
Area under backfilling of mined out area	Nil	None		None
Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	Nil	None		None
Total area fully reclaimed and rehabilitated	Nil	None		None
General remarks of inspecting officers on backfilling and reclamation etc.	Nil	None		None
	Status of part or full extraction of mineral from mined out area before starting backfilling.  Area under backfilling of mined out area Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)  Total area fully reclaimed and rehabilitated  General remarks of inspecting officers on backfilling and	Status of part or full approved extraction of document for the year 2022-mined out area before starting backfilling.  Area under Nil backfilling of mined out area  Concurrent use Nil of topsoil for restoration or rehabilitation of mineral out area (Rule 32)  Total area Nil fully reclaimed and rehabilitated  General remarks Nil of inspecting officers on backfilling and	Status of part There are not document for 2022-23 mineral from the year 2022-23 mined out area 23 before starting backfilling.  Area under Nil None backfilling of mined out area  Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)  Total area (Rule 32)  Total area Nil None  fully reclaimed and rehabilitated  General remarks of inspecting officers on backfilling and	Status of part or full approved out duirng the year extraction of document for the year 2022-23 mined out area before starting backfilling.  Area under Nil None backfilling of mined out area  Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)  Total area (Rule 32)  Total area Nil None  fully reclaimed and rehabilitated  General remarks of inspecting officers on backfilling and

### Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).		The Mining operations are under suspension since July 2022.	No comments to offer.
6b	Area available for rehabilitation (ha) .	Nil	None	None
6c	afforestation done (ha).	Nil	None	None
6d	No. of saplings planted during the year	Nil	None	None
6f	Any other method of rehabilitation	Nil	None	None
6g	Cost incurred on watch and care during the year	Nil	Rs.2,00,000/- for the year 2022-23 as reported by the lessee.	None
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling ( Lx B x D	Nil	None	None
5i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	None	None	None
6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestati on on backfilled area	Nil	None	None

Remarks

6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	None	None	None
61	Compliance on reclamation and rehabilitation by backfilling (v) any other specific means.	None	None	None
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	None	None	None
6n	Compliance of rehabilitation of waste land within lease (ii) Area rehabilitation (ha)	None	None	None
60	Compliance of rehabilitation of waste land within lease (iii) Method of rehabilitation	None	None	None
6p	Compliance of environmental monitoring (core zone and buffer zone)	Nil	None	None
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.		No mining operations were carried out during the year 2022-23. The mining operations were under suspension under Rule 1192) of MCDR, 2017.	No comments to offer.

Propasals Actual work

Mineral Conservation:

Sl.No. Item

7a	ROM Mineral dispatch or grade-wise sorting within lease area	Nil	None	None
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	Nil	None	None
7c	Different grade of mineral sorted out at mines.	Nil	None	None
7d	Any beneficiation process at mines .	Nil	None	None
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	Nil	None	None

#### Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	Nil	None	None
8b	Concurrent use or storage of topsoil	Nil	None	None
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Nil	None	None

8d	Use of overburden, waste rock,	Nil	None	None
	rejects and fines dumps for restoring the land to its original use			
8e	Phased restoration, reclamation and rehabilitation	Nil	None	None
	of lands affected by mining operations (Pits, dumps			
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	Nil	Except for the plantation made by lessee in the lease, there is no other vegetation in the lease.	No comments
8g	Survival rate	Nil	None	None
8h	Water sprinkling on roads to control airborne dust	None	None	None
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area		No mining operations were carried out duirng the year 2022-23. The mining operations were suspended since July 2022.	No comments.

### Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and		The AR & MR being submitted regularly by the lessee.	No comments to offer.

9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	As per the annual return 2021-22, Sri Chiranjeevi and sri Arun jyothi were appinted as Geologist and Minig engineer.		No comments
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	return for the year 2022-23 is yet to be submitted.	As per Annual return 2021-22, the area under pit was 2.730 ha, Infrastructure - 0.210 ha, Wasre dump - 0.80 ha	No comments to make.
9d	Scrutiny of Annual return on afforestation		As per 2021-22,100 no.s were planted.	No comments
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Nil	None	None
9f	Scrutiny of Annual return on ROM stock and/or graded ore	year 2022-23	As per AR 2021-22, 10,260 tonnes was reported.	None
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost		The ex-mine price reported as per AR 2021-22 was Rs.2234/- per tonne	No comments
9h	Scrutiny of Annual return on fixed assets		The value of fixed assets as per AR 2021-22 was seven crore rupees.	The Mining operations are under suspension since July 2022.No production reported duirng the year 2022-23.
9k	Scrutiny of Annual return on mining machineries		The mining machinery as per AR 2021-22 is as follows: Tippers - 4 Hydraulic shovel - 1	No comments to offer.

Dozer - 1

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed

Show couse position

Rule NO.

Issued on Compliance on

Rule NO.

Issued on Compliance on

Date : 22 (5/2023

Indian Bureau of Mines

(A.V.Ramesh Kumar)